



COMMONWEALTH of VIRGINIA

Jennifer B. DeBruhl
Director

DEPARTMENT OF RAIL AND PUBLIC TRANSPORTATION
600 EAST MAIN STREET, SUITE 2102
RICHMOND, VA 23219-2416

(804) 786-4440
FAX (804) 225-3752
Virginia Relay Center
800-828-1120 (TDD)

PRE -AWARD BUY AMERICA COMPLIANCE CERTIFICATION

As required by Title 49 of the CFR. Part 663 - Subpart B, **Department of Rail and Public Transportation** (the recipient) is satisfied that the vehicles to be purchased, 12-Year Heavy Duty Transit Bus from Proterra, Inc. and meet the requirements of Section 16(b)(3) of the Surface Transportation Assistance Act of 1982, as amended. The recipient has reviewed documentation provided by the manufacturer, which lists (1) the proposed component and sub-component parts of the buses identified by manufacturer, county of origin, and cost; and (2) the proposed location of the final activity point for the buses, including a description of the activities that will take place at the final assembly point and the cost of final assembly.

A handwritten signature in black ink, appearing to read "Avery Daugherty".

Avery Daugherty, Statewide Program Manager

Date: 10/24/2022


CER 8. Federal Certifications
CER 8.1 Buy America Certification

This form is to be submitted with an offer exceeding the small purchase threshold for federal assistance programs, currently set at \$100,000.

Certificate of Compliance

The Proposer hereby certifies that it will comply with the requirements of 49 USC Section 5323(j)(2)(C), Section 165(b)(3) of the Surface Transportation Assistance Act of 1982, as amended, and the regulations of 49 CFR 661.11:

Name and title: John Walsh, Chief Commercial Officer
Company: Proterra Operating Company, Inc.

DocuSigned by:

190E3GD36916412...
Authorized signature

9/7/2022

Date

Certificate of Non-Compliance

The Proposer hereby certifies that it cannot comply with the requirements of 49 USC Section 5323(j)(2)(C) and Section 165(b)(3) of the Surface Transportation Assistance Act of 1982, as amended, but may qualify for an exception to the requirements consistent with 49 USC Sections 5323(j)(2)(B) or (j)(2)(D), Sections 165(b)(2) or (b)(4) of the Surface Transportation Assistance Act, as amended, and regulations in 49 CFR 661.7.

Name and title:
Company:

Authorized signature

Date



| PART NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY / VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | Component % of Vehicle Material Costs | |
|-------------|--|--|---|---|---------------|-----------------|--------------|--------------------|--------|---------|---------------------------------------|--------|
| | | | | | | | | | | | CUMULATIVE | 77.42% |
| 118-5027 | BODY, 40' HERON, 6HP | TPI Composites, INC | USA | Warren, RI | 1 | 0 | 100% | 24.33% | 32.16% | -7.83% | 24.33% | |
| 046035 | ASY,HV BATTERY,15BT3A | Proterra, Inc. | USA | City of Industry, CA | 4 | 0 | 100% | 22.49% | 29.72% | -7.23% | 46.82% | |
| 130-0088 | Seats, 40 Passenger, Gemini | USSC | USA | Exton, PA/Chicago, IL | 1 | 0 | 100% | 4.23% | 5.58% | -1.36% | 51.05% | |
| 048220 | WINDOW KIT,50% L,T, NON-SERVICE, 5MM-TEMP, NON VANDAL | AROW Global Corp | USA | Mosinee, WI | 1 | 0 | 100% | 1.76% | 2.33% | -0.57% | 52.81% | |
| 034673 | Devices for Electric Control (TRACTION MOTOR INVERTER) | Danfoss Power Solutions (US) Company | USA | Lomont, CO | 1 | 0 | 100% | 1.44% | 1.90% | -0.46% | 54.25% | |
| 034675 | TRACTION MOTOR (ECCNL EAR99 NLR) | Danfoss Power Solutions (US) Company | USA | Lomont, CO | 1 | 0 | 100% | 1.38% | 1.83% | -0.44% | 55.63% | |
| 045663 | SKELETON, OVERHEAD LIGHTING, INTERIOR, KIT | Superior Interior Systems | USA | Grand Rapids, MI | 1 | 0 | 100% | 1.12% | 1.48% | -0.36% | 56.75% | |
| 030099-002 | RAMP, F/OVER, 30"Wx48"H, 24v, W/O CAGE RIC-081489 NUTS, ALTRO TEM 2702 | RICON | USA | Escalon, CA | 1 | 0 | 100% | 1.02% | 1.35% | -0.33% | 57.78% | |
| 046655 | DOOR, EXIT, PNEUMATIC, IGP2, 56% VLT, PARSOL GREY, 4MM TEMPERED GLASS, YELLOW HANDLES, BASE SPEC | Ventura Inc | USA | Dallas, NC | 1 | 0 | 100% | 0.97% | 1.28% | -0.31% | 58.74% | |
| 046653 | DOOR, ENTRANCE, PNEUMATIC, IGP2, 90% VLT, CLEAR, 4MM TEMPERED GLASS, YELLOW HANDLES, BASE SPEC | Ventura Inc | USA | Dallas, NC | 1 | 0 | 100% | 0.90% | 1.18% | -0.29% | 59.64% | |
| 053110 | DEHROSTER, 800V | Therma-Tech (A.R. Lintern) | USA | Redford, MI | 1 | 0 | 100% | 0.67% | 0.89% | -0.22% | 60.32% | |
| 018362 | PLEXUS, MA-530 | Composites One LLC | USA | Danvers, MA | 125 | | 50% | 1.03% | 0.69% | 0.34% | 60.84% | |
| 039129 | SINGLE PARALLEL AC 136G3 II AE E-C | Eberspaecher Climate Control Systems U.S.A. Inc. | USA | Monteary | 1 | 0 | 9% | 4.86% | 0.58% | 4.28% | 61.27% | |
| 053069 | HARNES, PRODRIVE (PDRV) | Precisionworks MFG LLC | USA | Grand Rapids, MI | 1 | 0 | 100% | 0.42% | 0.56% | -0.14% | 61.70% | |
| 049533 | CAGE, PRODRIVE | GH Metal Solutions, Inc. | USA | Fort Payne, AL | 1 | 0 | 100% | 0.37% | 0.49% | -0.12% | 62.07% | |
| 029082 | OLEMS LED US ASSY 'N50' | Harover Displays | USA | ELK GROVE VILLAGE, IL | 1 | 0 | 100% | 0.36% | 0.48% | -0.12% | 62.43% | |
| 045719 | DOORS, OVERHEAD LIGHTING, INTERIOR | Superior Interior Systems | USA | Grand Rapids, MI | 1 | 0 | 100% | 0.33% | 0.43% | -0.11% | 62.76% | |
| 044978 | MODULAR INSTRUMENT (MOK3) | Continental Automotive Systems US, Inc. | General waiver applies | Germany | 1 | 0 | 100% | 0.33% | 0.43% | -0.10% | 63.09% | |
| 052244 | STANCHIONS, 40 PASSENGER | Bentech | USA | Philadelphia, Pa | 1 | 0 | 100% | 0.31% | 0.41% | -0.10% | 63.40% | |
| 021657 | V-ROD BRACKET | GH Metal Solutions, Inc. | USA | Fort Payne, AL | 1 | 0 | 100% | 0.30% | 0.39% | -0.10% | 63.70% | |



| PART NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY / VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|---------------|---|---|---|--|---------------|-----------------|--------------|--------------------|-------|---------|------------|
| 088326 | MODULE (AL)W/E-FANS | Modine Manufacturing Company | USA | Grand Rapids, MI | 1 | 0 | 100% | 0.29% | 0.38% | -0.09% | 63.98% |
| 051243 | HARN DRIVERS WORKPLACE (DRWP) | Precisionworks MFG LLC | USA | Loveland, CO | 1 | 0 | 100% | 0.25% | 0.34% | -0.08% | 64.24% |
| 051209 | HARNESS, STREETSIDE MAIN (SSMN) | Precisionworks MFG LLC | USA | Loveland, CO | 1 | 0 | 100% | 0.25% | 0.33% | -0.08% | 64.49% |
| 048257 | HARNESS, ELECTRICAL CABINET (ECAB) | Precisionworks MFG LLC | USA | Loveland, CO | 1 | 0 | 100% | 0.24% | 0.32% | -0.08% | 64.73% |
| 053418 | CABLE ASSY, CCS MANUAL CHARGE GEN2, 40', CS-R | REMA USA LLC | USA | Fountain Inn, SC | 1 | 0 | 100% | 0.23% | 0.31% | -0.07% | 64.96% |
| 050414 | HARNESS, REAR DECK (RDCK) | Precisionworks MFG LLC | USA | Loveland, CO | 1 | 0 | 100% | 0.23% | 0.30% | -0.07% | 65.19% |
| 037645 | WP29-24V-CH-A PROGRAMMED ASSY (PUMP, WATER, CATALYST, E-MARK) | Engineered Machined Products Inc. | USA | Escanaba, MI | 3 | 0 | 100% | 0.23% | 0.30% | -0.07% | 65.42% |
| 029083 | O/S LED US SGN OLEM N50 | Hanover Displays | USA | ELK GROVE VILLAGE, IL | 1 | 0 | 100% | 0.22% | 0.30% | -0.07% | 65.64% |
| 046967-025 | FLOORING, ALTRO KIT, 40' | Altro Transfloor | United Kingdom | Letchworth, England / Santa Fe Springs, CA | 1 | 0 | 60% | 0.31% | 0.25% | 0.07% | 65.83% |
| 024800 | SWPT-BPR-FRT-101-MES-V2.0-BLK | Romeo Rim, Inc. | USA | Romeo, MI | 1 | 0 | 100% | 0.18% | 0.24% | -0.06% | 66.01% |
| 044508 | SWPT-BPR-RR-101-BLK-44508 | Romeo Rim, Inc. | USA | Romeo, MI | 1 | 0 | 100% | 0.17% | 0.23% | -0.06% | 66.19% |
| 045461-01AA01 | PANEL, WALL, BASE | Kenson Plastics Inc | USA | Beaver Falls, PA | 5 | 0 | 100% | 0.17% | 0.22% | -0.05% | 66.35% |
| 037376 | MIRROR, EXTERIOR, CURBSIDE | Safe Fleet Bus & Rail | USA | Elkhart, IN | 1 | 0 | 100% | 0.16% | 0.22% | -0.05% | 66.52% |
| 047953 | COVERS, OVERHEAD LIGHTING, INTERIOR, KIT | Superior Interior Systems | USA | Grand Rapids, MI | 1 | 0 | 100% | 0.16% | 0.21% | -0.05% | 66.68% |
| 045665 | HARNESS, HV JUNCTION BOX (HVJB) | Precisionworks MFG LLC | USA | Loveland, CO | 2 | 0 | 100% | 0.15% | 0.20% | -0.05% | 66.83% |
| 001273 | CONTROLLER, NODE, MUX2-B+V | Continental Automotive Systems US, Inc. | General waiver applies | Germany | 4 | 0 | 100% | 0.14% | 0.18% | -0.04% | 66.97% |
| P021607 | BRACKET, MOUNT, STEERING CAM | GHI Metal Solutions, Inc. | USA | Fort Payne, AL | 1 | 0 | 100% | 0.14% | 0.18% | -0.04% | 67.11% |
| 051241 | HARNESS, CURB-SIDE MAIN (CSMN) | Precisionworks MFG LLC | USA | Loveland, CO | 1 | 0 | 100% | 0.13% | 0.17% | -0.04% | 67.24% |
| 018170 | BRACKET, SUSPENSION ASSY 1, LOWER | Aranda Tooling, Inc. | USA | Chino, CA | 1 | 0 | 60% | 0.21% | 0.17% | 0.04% | 67.36% |
| 014135 | TILT / TELESCOPE COLUMN ASSEMBLY | ZF Active Safety & Electronics, US | USA | Grand Rapids, MI | 1 | 0 | 100% | 0.13% | 0.17% | -0.04% | 67.49% |
| 052376 | HARN, ROOFTOP REAR (RTRR_STR3) | Precisionworks MFG LLC | USA | Loveland, CO | 1 | 0 | 100% | 0.12% | 0.16% | -0.04% | 67.61% |
| 000197 | MOTOR, ELECTRICAL, POWER STEERING, 5 HP, 230V, 3PH | Cross Company. | USA | Fort Smith, AR | 1 | 0 | 100% | 0.11% | 0.14% | -0.03% | 67.72% |
| 053353 | CS ADAPTER, HVAC, HERON | Lock-Ridge Tool Co., Inc. | USA | Pomona, California | 1 | 0 | 100% | 0.10% | 0.13% | -0.03% | 67.82% |
| 053372 | SS ADAPTER, HVAC, HERON | Lock-Ridge Tool Co., Inc. | USA | Pomona, California | 1 | 0 | 100% | 0.10% | 0.13% | -0.03% | 67.92% |
| 013721 | MIRROR, EXTERIOR, LOW SLUNG, SS | Safe Fleet Bus & Rail | USA | Elkhart, IN | 1 | 0 | 100% | 0.10% | 0.13% | -0.03% | 68.02% |
| 042660 | FRAME, DESTINATION SIGN, UPPER HERON | Specfab Services, Inc | USA | Greenville, SC | 1 | 0 | 100% | 0.10% | 0.13% | -0.03% | 68.12% |
| 038692 | AMP EQUALIZER W/ CANBUS | Vanner, Inc. | USA | Hilliard, OH | 1 | 0 | 100% | 0.10% | 0.13% | -0.03% | 68.22% |



| PAK NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY / VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|---------------|--|--------------------------------------|---|---|---------------|-----------------|--------------|--------------------|-------|---------|------------|
| 038244 | CABLE ASSY, POWER STEERING | Precisionworks MFG LLC | USA | Loveland, CO | 1 | 0 | 100% | 0.10% | 0.13% | -0.03% | 68.32% |
| 053015 | HARN, BATTERY SIGNAL & REAR (BARI) | Precisionworks MFG LLC | USA | Grand Rapids, MI | 1 | 0 | 100% | 0.10% | 0.13% | -0.03% | 68.42% |
| 044608 | HARN, ROOFTOP REAR (RTRR-STIR) | Precisionworks MFG LLC | USA | Loveland, CO | 1 | 0 | 100% | 0.10% | 0.13% | -0.03% | 68.51% |
| 024924-03AA04 | PANEL, DASH, DRIVERS | Kenson Plastics Inc | USA | Beaver Falls, PA | 1 | 0 | 100% | 0.10% | 0.13% | -0.03% | 68.61% |
| 024923-03AB04 | PANEL, DASH, CS | Kenson Plastics Inc | USA | Beaver Falls, PA | 1 | 0 | 100% | 0.09% | 0.12% | -0.03% | 68.70% |
| 052355 | FRAME ASSY, STORAGE SHELF, CS HERON | SpecFab Services, Inc | USA | Greenville, SC | 1 | 0 | 100% | 0.09% | 0.12% | -0.03% | 68.80% |
| 044605 | HARN, BATTERY SIG STRING (BSTR) | Precisionworks MFG LLC | USA | Loveland, CO | 1 | 0 | 100% | 0.09% | 0.11% | -0.03% | 68.88% |
| 042027 | CABLE ASSEMBLY, DC LINK, PRODRIVE | Danfoss Power Solutions (US) Company | USA | Lonmont, CO | 1 | 0 | 100% | 0.08% | 0.11% | -0.03% | 68.97% |
| 021639 | DPSV II W/ #16 MTG, OSR, ARM (WHITE) NO | Specialty Manufacturing, Inc | USA | Grand Rapids, MI | 2 | 0 | 100% | 0.08% | 0.11% | -0.03% | 69.05% |
| 042496-03AC08 | PANEL, MODESTY PANEL | Kenson Plastics Inc | USA | Philadelphia, Pa | 2 | 0 | 100% | 0.08% | 0.11% | -0.03% | 69.13% |
| 040055 | BRACKET STRUCTURE, DASH | Metal Solutions, Inc. | USA | Grand Rapids, MI | 1 | 0 | 100% | 0.08% | 0.10% | -0.03% | 69.21% |
| 051004 | ASSY, HOOD, GUARD, VENT, RAIL | Metal Solutions, Inc. | USA | Vandergrift, PA | 4 | 0 | 100% | 0.08% | 0.10% | -0.03% | 69.29% |
| 044166 | TANK, POWER STEERING | Industrial Fabricators, Inc. | USA | Piedmont, SC | 1 | 0 | 100% | 0.08% | 0.10% | -0.03% | 69.37% |
| 042419-03AA04 | PANEL, OH, FRONT DEST SIGN | Kenson Plastics Inc | USA | Beaver Falls, PA | 1 | 0 | 100% | 0.08% | 0.10% | -0.03% | 69.45% |
| 045281 | PLATE, ITS, ACCESS PANEL | Ananda Tooling, Inc. | USA | Chino, CA | 1 | 0 | 100% | 0.08% | 0.10% | -0.02% | 69.52% |
| 045210 | FRAME, REAR, UPPER | SpecFab Services, Inc | USA | Greenville, SC | 1 | 0 | 100% | 0.08% | 0.10% | -0.02% | 69.60% |
| 050623 | BRACKET, TANK, AIR | SpecFab Services, Inc | USA | Greenville, SC | 1 | 0 | 100% | 0.07% | 0.10% | -0.02% | 69.67% |
| 045244-03AA04 | PANEL, REAR, OVERHEAD | Ray Products Company, Inc. | USA | Ontario, California | 1 | 0 | 100% | 0.07% | 0.10% | -0.02% | 69.75% |
| 024147 | MOUNT, ISOLATION | J F Industries Inc | USA | Woburn, MA | 80 | 0 | 100% | 0.07% | 0.09% | -0.02% | 69.82% |
| 039861 | BRACKET, BATTERY BOX TRAY | Watson Engineering | USA | Piedmont, SC | 1 | 0 | 100% | 0.07% | 0.09% | -0.02% | 69.89% |
| 040832 | SUSPENSION PLATE ASSY, UPPER R | Ananda Tooling, Inc. | USA | Chino, CA | 1 | 0 | 100% | 0.07% | 0.09% | -0.02% | 69.96% |
| 040834 | SUSPENSION PLATE ASSY | Ananda Tooling, Inc. | USA | Chino, CA | 1 | 0 | 100% | 0.07% | 0.09% | -0.02% | 70.03% |
| 021019 | FLAT GASKET SILICONESP (w GLUE) | Elasto Proxy | Canada | Canada | 2 | 0 | 100% | 0.07% | 0.09% | -0.02% | 70.10% |
| 042416-03AA04 | PANEL, DRIVER OVERHEAD | Kenson Plastics Inc | USA | Beaver Falls, PA | 1 | 0 | 100% | 0.07% | 0.09% | -0.02% | 70.17% |
| 022653 | SPLINE COUPLING PER DRAWING | NSK Industries Inc | USA | Cleveland, OH | 1 | 0 | 100% | 0.07% | 0.09% | -0.02% | 70.24% |
| 043834-03AA04 | PANEL, DRIVERS STORAGE OVERHEAD | Kenson Plastics Inc | USA | Beaver Falls, PA | 1 | 0 | 100% | 0.07% | 0.09% | -0.02% | 70.30% |
| 051387 | FRAME, REAR, LOWER | SpecFab Services, Inc | USA | Greenville, SC | 1 | 0 | 100% | 0.06% | 0.08% | -0.02% | 70.36% |
| 043835 | FRAME ASSY, UPPER PANEL, SS | SpecFab Services, Inc | USA | Greenville, SC | 1 | 0 | 100% | 0.06% | 0.08% | -0.02% | 70.43% |
| 018315 | SKID PLATE, CAGE | Dellinger Enterprises, LTD | USA | Belmont, NC | 1 | 0 | 100% | 0.06% | 0.08% | -0.02% | 70.49% |
| 024850-03AC04 | PANEL, FRONT DOOR, OVERHEAD | Kenson Plastics Inc | USA | Beaver Falls, PA | 1 | 0 | 100% | 0.06% | 0.08% | -0.02% | 70.55% |
| 049873 | HARNES, LOW VOLTAGE POWER EXTERNAL (EPWR123) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.06% | 0.08% | -0.02% | 70.61% |



| PART NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY / VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|---------------|---------------------------------------|---|---|---|---------------|-----------------|--------------|--------------------|-------|---------|------------|
| 012857 | ADAPTOR, TRANSMISSION, MOTOR | AFL Telecommunications Inc | USA | Bristol, VA | 1 | 0 | 100% | 0.06% | 0.08% | -0.02% | 70.67% |
| 047558 | COVER, PROTECTION, UNDERBODY | Dellinger Enterprises, LTD | USA | Belmont, NC | 1 | 0 | 100% | 0.06% | 0.07% | -0.02% | 70.73% |
| 044697 | HARNES, SSDASH (SSDASH) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.06% | 0.07% | -0.02% | 70.79% |
| 049690 | FIREWALL, PRODRIVE | Specfab Services, Inc | USA | Greenville, SC | 1 | 0 | 100% | 0.06% | 0.07% | -0.02% | 70.84% |
| 051002 | CNTR,SHIELD,GUARD,VENT,RAIL,15BT3A | Metal Solutions, Inc. | USA | Vandergift, PA | 4 | 0 | 60% | 0.09% | 0.07% | 0.02% | 70.90% |
| 046558 | HARNES, ROOFTOP REAR (RTRR) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.06% | 0.07% | -0.02% | 70.95% |
| 001275 | Controller, MULTIPLEX, ZR32-A, 24V | Continental Automotive Systems US, Inc. | General waiver applies | Germany | 1 | 0 | 100% | 0.05% | 0.07% | -0.02% | 71.01% |
| 037999 | HARNES, POWERTRAIN _PRODRIVE (TRAIN) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.05% | 0.07% | -0.02% | 71.06% |
| 045250-03AA04 | PANEL, REAR, LOWER SHELF | Ray Products Company, Inc. | USA | Ontario, California | 1 | 0 | 100% | 0.05% | 0.07% | -0.02% | 71.11% |
| 046888 | MOUNT, BRACKET, WHEEL WELL, CS | Watson Engineering | USA | Piedmont, SC | 1 | 0 | 100% | 0.05% | 0.07% | -0.02% | 71.17% |
| 009933 | ADAPTOR, PUMP, POWER STEERING, 6.125" | Cross Company. | USA | Alpena, MI | 1 | 0 | 100% | 0.05% | 0.07% | -0.02% | 71.22% |
| 047557 | RAMP, PROTECTIVE, UNDERBODY | Dellinger Enterprises, LTD | USA | Belmont, NC | 1 | 0 | 100% | 0.05% | 0.07% | -0.02% | 71.27% |
| 039674 | AMP EQUALIZER W/CANBUS | S. Sterling Company | USA | Arlington Heights, IL | 1 | 0 | 100% | 0.05% | 0.07% | -0.02% | 71.32% |
| 009842 | PUMP, POWER STEERING EATON | Cross Company. | USA | Seacy, AR | 1 | 0 | 100% | 0.05% | 0.07% | -0.02% | 71.37% |
| 024862-03AB04 | PANEL, ARMREST, DRIVERS | Kenson Plastics Inc | USA | Beaver Falls, PA | 1 | 0 | 100% | 0.05% | 0.06% | -0.02% | 71.42% |
| 051001 | RHS,SHIELD,GUARD,VENT,RAIL,3A | Metal Solutions, Inc. | USA | Vandergift, PA | 4 | 0 | 60% | 0.08% | 0.06% | 0.02% | 71.47% |
| 051003 | LHS,SHIELD,GUARD,VENT,RAIL,3A | Metal Solutions, Inc. | USA | Vandergift, PA | 4 | 0 | 60% | 0.08% | 0.06% | 0.02% | 71.51% |
| 021422 | GROUND BUSS 300A 30VDC | Sealed Buss Bar LLC | USA | Sarasota, FL | 5 | 0 | 100% | 0.05% | 0.06% | -0.01% | 71.56% |
| 045423 | BRACKET, FRONT DOOR OH PANEL | Specfab Services, Inc | USA | Greenville, SC | 1 | 0 | 100% | 0.05% | 0.06% | -0.01% | 71.61% |
| 045248-03AA04 | PANEL, REAR, CHASSIS, C/S | Ray Products Company, Inc. | USA | Ontario, California | 1 | 0 | 100% | 0.04% | 0.06% | -0.01% | 71.65% |
| 045249-03AA04 | PANEL, REAR, CHASSIS, S/S | Ray Products Company, Inc. | USA | Ontario, California | 1 | 0 | 100% | 0.04% | 0.06% | -0.01% | 71.70% |
| 024776 | BRACKET, MOTOR, MOUNT | GH Metal Solutions, Inc. | USA | Fort Payne, AL | 1 | 0 | 100% | 0.04% | 0.06% | -0.01% | 71.74% |
| 027508-009 | RAIL, SEAT TRACK | Specfab Services, Inc | USA | Greenville, SC | 2 | 0 | 50% | 0.09% | 0.06% | 0.03% | 71.78% |
| 043915 | BRACKET, FRAME, ECAB, SS | Lock-Ridge Tool Co., Inc. | USA | Grand Rapids, MI | 1 | 0 | 100% | 0.04% | 0.06% | -0.01% | 71.82% |
| 050035 | GRILLE, FAIRING, REAR, HERON | Dellinger Enterprises, LTD | USA | Belmont, NC | 1 | 0 | 100% | 0.04% | 0.06% | -0.01% | 71.87% |
| 044347 | BRACKET STRUCTURE, DEFROSTER | Specfab Services, Inc | USA | Greenville, SC | 1 | 0 | 100% | 0.04% | 0.05% | -0.01% | 71.91% |
| 044738 | PLATE, MOUNTING, ECAB | Dellinger Enterprises, LTD | USA | Belmont, NC | 1 | 0 | 100% | 0.04% | 0.05% | -0.01% | 71.95% |
| 049529 | TUBE, COOLANT | Tube Specialties | USA | Troutdale, OR | 1 | 0 | 100% | 0.04% | 0.05% | -0.01% | 71.99% |
| 049532 | TUBE, COOLANT | Tube Specialties | USA | Troutdale, OR | 1 | 0 | 100% | 0.04% | 0.05% | -0.01% | 72.03% |
| 045252-03AA04 | PANEL, ECAB, FRONT | Kenson Plastics Inc | USA | Beaver Falls, PA | 1 | 0 | 100% | 0.04% | 0.05% | -0.01% | 72.07% |



| PART NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY / VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|---------------|--|------------------------------------|---|---|---------------|-----------------|--------------|--------------------|-------|---------|------------|
| 013086 | PITMAN, ARM / ARM, STEERING | ZF Active Safety & Electronics, US | USA | Grand Rapids, MI | 1 | 0 | 100% | 0.04% | 0.05% | -0.01% | 72.11% |
| 045253-03AA04 | PANEL, ECAB, REAR | Kenson Plastics Inc | USA | Beaver Falls, PA | 1 | 0 | 100% | 0.04% | 0.05% | -0.01% | 72.14% |
| 049851 | HARNES, LOW VOLTAGE POWER INTERNAL (IPWR114) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.04% | 0.05% | -0.01% | 72.18% |
| 049842 | HARNES, LOW VOLTAGE POWER EXTERNAL | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.04% | 0.05% | -0.01% | 72.22% |
| 045464-01AA01 | PANEL, WALL, PLUG, FORWARD | Kenson Plastics Inc | USA | Beaver Falls, PA | 1 | 0 | 100% | 0.04% | 0.05% | -0.01% | 72.26% |
| 045465-01AA01 | PANEL, WALL, PLUG, AFT | Kenson Plastics Inc | USA | Beaver Falls, PA | 1 | 0 | 100% | 0.04% | 0.05% | -0.01% | 72.30% |
| 039876 | BRACKET, BATTERY | Watson Engineering | USA | Piedmont, SC | 1 | 0 | 100% | 0.04% | 0.05% | -0.01% | 72.34% |
| 024777 | BRACKET, TRANSMISSION MOUNT, ASSEMBLY | Ananda Tooling, Inc. | USA | Chino, CA | 1 | 0 | 100% | 0.04% | 0.05% | -0.01% | 72.38% |
| 040840 | BRACKET, DASH | Lock-Ridge Tool Co., Inc. | USA | Grand Rapids, MI | 1 | 0 | 100% | 0.04% | 0.05% | -0.01% | 72.41% |
| 040780 | TUBE, COOLANT | Tube Specialties | USA | Troutdale, OR | 7 | 0 | 100% | 0.04% | 0.05% | -0.01% | 72.45% |
| 046768 | BRACKET, REAR DECK, UPPER ACCESS PANEL | Specfab Services, Inc | USA | Greenville, SC | 1 | 0 | 100% | 0.04% | 0.05% | -0.01% | 72.49% |
| 027508-008 | RAIL, SEAT TRACK | Specfab Services, Inc | USA | Greenville, SC | 2 | 0 | 50% | 0.07% | 0.05% | 0.02% | 72.52% |
| 045245-03AA04 | PANEL, REAR, OVERHEAD, ACCESS | Ray Products Company, Inc. | USA | Ontario, California | 1 | 0 | 100% | 0.04% | 0.05% | -0.01% | 72.56% |
| 045251-03AA04 | PANEL, REAR, LOWER SHELF, ACCE | Ray Products Company, Inc. | USA | Ontario, California | 1 | 0 | 100% | 0.04% | 0.05% | -0.01% | 72.59% |
| 049847 | HARNES, LOW VOLTAGE POWER (IPWR111) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.04% | 0.05% | -0.01% | 72.63% |
| 020456 | SPANNER, DRIVESHAFT LOOP | Watson Engineering | USA | Fort Payne, AL | 1 | 0 | 100% | 0.03% | 0.04% | -0.01% | 72.66% |
| 045461-01AB01 | PANEL, WALL, WW, S/S, REAR | Kenson Plastics Inc | USA | Beaver Falls, PA | 1 | 0 | 100% | 0.03% | 0.04% | -0.01% | 72.70% |
| 045461-01AC01 | PANEL, WALL, S/S WHEEL WELL, FRONT | Kenson Plastics Inc | USA | Beaver Falls, PA | 1 | 0 | 100% | 0.03% | 0.04% | -0.01% | 72.73% |
| 045461-01AF01 | PANEL, WALL, ENTRANCE DOOR | Kenson Plastics Inc | USA | Beaver Falls, PA | 1 | 0 | 100% | 0.03% | 0.04% | -0.01% | 72.76% |
| 045461-01AG01 | PANEL, WALL, E-CAB | Kenson Plastics Inc | USA | Beaver Falls, PA | 1 | 0 | 100% | 0.03% | 0.04% | -0.01% | 72.80% |
| 045461-01AH01 | PANEL, WALL, REAR, S/S | Kenson Plastics Inc | USA | Beaver Falls, PA | 1 | 0 | 100% | 0.03% | 0.04% | -0.01% | 72.83% |
| 045461-01AI01 | PANEL, WALL, REAR, C/S | Kenson Plastics Inc | USA | Beaver Falls, PA | 1 | 0 | 100% | 0.03% | 0.04% | -0.01% | 72.86% |
| 045461-01AJ01 | PANEL, WALL, REAR, C/S | Kenson Plastics Inc | USA | Beaver Falls, PA | 1 | 0 | 100% | 0.03% | 0.04% | -0.01% | 72.90% |
| 039603 | PLATE, FUSE | Kenson Plastics Inc | USA | Beaver Falls, PA | 1 | 0 | 100% | 0.03% | 0.04% | -0.01% | 72.95% |
| 045246-03AA04 | PANEL, REAR, PILLAR, C/S | Watson Engineering | USA | Piedmont, SC | 1 | 0 | 100% | 0.03% | 0.04% | -0.01% | 72.96% |
| 049852 | HARNES, LOW VOLTAGE POWER INTERNAL (IPWR115) | Ray Products Company, Inc. | USA | Ontario, California | 1 | 0 | 100% | 0.03% | 0.04% | -0.01% | 72.99% |
| 045911 | BRACKET, BATTERY | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.03% | 0.04% | -0.01% | 73.03% |
| 044698 | HARNES, ARMREST CENTER (ARM2) | Watson Engineering | USA | Piedmont, SC | 1 | 0 | 100% | 0.03% | 0.04% | -0.01% | 73.06% |
| 014657 | HARNES, ARMREST CENTER (ARM2) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.03% | 0.04% | -0.01% | 73.09% |
| 024863-03AB04 | COVER, BROADWAY, MIDDLE | Specfab Services, Inc | USA | Greenville, SC | 2 | 0 | 100% | 0.03% | 0.04% | -0.01% | 73.12% |
| 043010-03AA04 | PANEL, DUMP VALVE COVER | Kenson Plastics Inc | USA | Beaver Falls, PA | 1 | 0 | 100% | 0.03% | 0.04% | -0.01% | 73.15% |
| | PANEL, ACCESS, DEST SIGN | Kenson Plastics Inc | USA | Beaver Falls, PA | 1 | 0 | 100% | 0.03% | 0.04% | -0.01% | 73.18% |



| PAK NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY / VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|---------------|---|--|---|---|---------------|-----------------|--------------|--------------------|-------|---------|------------|
| 044169 | TUBE, COOLANT | Tube Specialties | USA | Troutdale, OR | 1 | 0 | 100% | 0.03% | 0.04% | -0.01% | 73.21% |
| 014419 | COOLER, TRANSMISSION, OIL TO AIR (KIT) | Cross Company. | USA | Racine, WI | 1 | 0 | 50% | 0.06% | 0.04% | 0.02% | 73.24% |
| 024778 | BRACKET, TRANSMISSION MOUNT, ASSEMBLY | Ananda Tooling, Inc. | USA | Chino, CA | 1 | 0 | 100% | 0.03% | 0.04% | -0.01% | 73.27% |
| 044022 | BRACKET, MOUNTING WIPER MOTOR | Metal Solutions, Inc. | USA | Vandergrift, PA | 1 | 0 | 100% | 0.03% | 0.04% | -0.01% | 73.30% |
| 044159 | BRACKET, MOUNTING, WIPER MOTOR | Metal Solutions, Inc. | USA | Grand Rapids, MI | 1 | 0 | 100% | 0.03% | 0.04% | -0.01% | 73.32% |
| 040772 | TUBE, COOLANT | Tube Specialties | USA | Troutdale, OR | 1 | 0 | 100% | 0.03% | 0.03% | -0.01% | 73.35% |
| 047034 | BRACKET, PANEL, REAR, PILLAR, | Ananda Tooling, Inc. | USA | Chino, CA | 1 | 0 | 100% | 0.03% | 0.03% | -0.01% | 73.38% |
| 047035 | BRACKET, PANEL, REAR, PILLAR, | Ananda Tooling, Inc. | USA | Chino, CA | 1 | 0 | 100% | 0.03% | 0.03% | -0.01% | 73.40% |
| 033213 | PCBA TELEMETRY SYSTEM | Silicon Forest Electronics | USA | Vancouver, WA | 1 | 0 | 10% | 0.26% | 0.03% | 0.22% | 73.43% |
| 018318 | BELLY PAN, REAR, CAGE | Lock-Ridge Tool Co., Inc. | USA | Pomona, CA | 1 | 0 | 100% | 0.03% | 0.03% | -0.01% | 73.45% |
| 013881 | SPACER, AIR SPRING, FRONT | GH Metal Solutions, Inc. | USA | Fort Payne, AL | 2 | 0 | 100% | 0.02% | 0.03% | -0.01% | 73.48% |
| 019737-005 | 1/4-20X0.25, M6-1.0X25 | Rotaloc Intl, LLC | Taiwan | Taiwan | 258 | 0 | 50% | 0.05% | 0.03% | 0.02% | 73.50% |
| 044360 | PLATE, STUD, M8 | Watson Engineering | USA | Piedmont, SC | 2 | 0 | 100% | 0.02% | 0.03% | -0.01% | 73.52% |
| 051950 | PLATE, DRIVERS WORKPLACE, HERON | Ananda Tooling, Inc. | USA | Chino, CA | 1 | 0 | 100% | 0.02% | 0.03% | -0.01% | 73.55% |
| 022098 | CABLE, POSITION CABLE 90/90 | Danfoss Power Solutions (US) Company | USA | Lomont, CO | 1 | 0 | 100% | 0.02% | 0.03% | -0.01% | 73.57% |
| 038243 | CABLE ASSY, AIR COMPRESSOR | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.02% | 0.03% | -0.01% | 73.60% |
| 024860-03AA04 | PANEL, ACCESS | Kenson Plastics Inc | USA | Beaver Falls, PA | 1 | 0 | 100% | 0.02% | 0.03% | -0.01% | 73.62% |
| 043916 | ASSEMBLY, ECAB INTERIOR STRUCTU | Dellinger Enterprises, LTD | USA | Belmont, NC | 1 | 0 | 100% | 0.02% | 0.03% | -0.01% | 73.64% |
| 024858-03AA04 | PANEL, ACCESS | Kenson Plastics Inc | USA | Beaver Falls, PA | 1 | 0 | 100% | 0.02% | 0.03% | -0.01% | 73.67% |
| 044847 | BRACKET, COLUMN, STEERING | Ananda Tooling, Inc. | USA | Chino, CA | 1 | 0 | 100% | 0.02% | 0.03% | -0.01% | 73.69% |
| 024864-03AA04 | PANEL, CENTER CATHEDRAL PANEL | Kenson Plastics Inc | USA | Beaver Falls, PA | 1 | 0 | 100% | 0.02% | 0.03% | -0.01% | 73.71% |
| 021010 | PLATE, STUD, M10 | Metal Solutions, Inc. | USA | Vandergrift, PA | 6 | 0 | 100% | 0.02% | 0.03% | -0.01% | 73.74% |
| 030295 | BRACKET, SIDE SIGN | Griffiths Corporation (DBA K-TEK Carolina) | USA | Pineville, NC | 1 | 0 | 100% | 0.02% | 0.03% | -0.01% | 73.76% |
| 024903-03AA04 | PANEL, ACCESS, ECAB | Kenson Plastics Inc | USA | Beaver Falls, PA | 1 | 0 | 100% | 0.02% | 0.03% | -0.01% | 73.78% |
| 026481 | DEFLECTOR, HVAC | Kenson Plastics Inc | USA | Beaver Falls, PA | 2 | 0 | 100% | 0.02% | 0.03% | -0.01% | 73.80% |
| 048836 | PASS THROUGH, AIR SYSTEM, SS WHEEL WELL | Metal Solutions, Inc. | USA | Grand Rapids, MI | 1 | 0 | 100% | 0.02% | 0.03% | -0.01% | 73.82% |
| 049324 | TUBE, COOLANT | Tube Specialties | USA | Troutdale, OR | 1 | 0 | 100% | 0.02% | 0.03% | -0.01% | 73.85% |
| 045744 | PANEL, CEILING, HERON, MIDDLE | Kenson Plastics Inc | USA | Beaver Falls, PA | 3 | 0 | 100% | 0.02% | 0.03% | -0.01% | 73.87% |
| 045218 | BRACKET, REAR DECK, LOWER CS | Ananda Tooling, Inc. | USA | Chino, CA | 1 | 0 | 100% | 0.02% | 0.03% | -0.01% | 73.89% |
| 026477 | DEFLECTOR, HVAC | Kenson Plastics Inc | USA | Beaver Falls, PA | 2 | 0 | 100% | 0.02% | 0.03% | -0.01% | 73.91% |
| 045219 | BRACKET, REAR DECK, LOWER, SS | Ananda Tooling, Inc. | USA | Chino, CA | 1 | 0 | 100% | 0.02% | 0.03% | -0.01% | 73.93% |
| 014944 | BRACKET, CROSSMEMBER SUPPORT, FRONT | SpecFab Services, Inc | USA | Greenville, SC | 1 | 0 | 100% | 0.02% | 0.03% | -0.01% | 73.95% |
| 051645 | FLEX LINE, POWER STEERING, 1" | Hydradyne LLC | USA | Greensboro, NC | 1 | 0 | 100% | 0.02% | 0.03% | -0.01% | 73.97% |
| 044365 | MOUNT, FLOOR SWITCH | Ananda Tooling, Inc. | USA | Chino, CA | 1 | 0 | 100% | 0.02% | 0.03% | -0.01% | 73.99% |



| PAK NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY/VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|---------------|--|--------------------------------|---|---|-------------|-----------------|--------------|--------------------|-------|---------|------------|
| 024861-03AA04 | PANEL, ACCESS | Kenson Plastics Inc | USA | Beaver Falls, PA | 1 | 0 | 100% | 0.02% | 0.03% | -0.01% | 74.01% |
| 024926-03AA04 | PANEL, ACCESS | Kenson Plastics Inc | USA | Beaver Falls, PA | 1 | 0 | 100% | 0.02% | 0.03% | -0.01% | 74.03% |
| 049362 | TUBE, COOLANT | Tube Specialties | USA | Troutdale, OR | 1 | 0 | 100% | 0.02% | 0.03% | -0.01% | 74.05% |
| 045452-01AA06 | PANEL, WALL, DRIVER | Kenson Plastics Inc | USA | Beaver Falls, PA | 1 | 0 | 100% | 0.02% | 0.03% | -0.01% | 74.07% |
| 005812 | HITTING, ADAPTER, SWIVEL, 1/2 TO 5/8" 37 DEG FLARE | Hydadyne LLC | USA | USA | 4 | 0 | 100% | 0.02% | 0.03% | -0.01% | 74.09% |
| 049858 | HARNES,LOW VOLTAGE POWER EXTERNAL (EPWR106) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.02% | 0.03% | -0.01% | 74.11% |
| 049249 | TUBE, COOLANT | Tube Specialties | USA | Troutdale, OR | 1 | 0 | 100% | 0.02% | 0.03% | -0.01% | 74.13% |
| 048258 | HARNES, CSDASH (CSDASH) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.02% | 0.03% | -0.01% | 74.15% |
| 024895 | BRACKET, FRAME, SIDE CONSOLE | Laserform and Machine Inc | USA | Columbia, SC | 1 | 0 | 100% | 0.02% | 0.03% | -0.01% | 74.17% |
| 024668 | FIXING PLATE, OMEGA EXTRUSION | Superior Interior Systems | USA | Grand Rapids, MI | 16 | 0 | 100% | 0.02% | 0.03% | -0.01% | 74.19% |
| 049866 | HARNES,LOW VOLTAGE POWER EXTERNAL (EPWR114) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.02% | 0.03% | -0.01% | 74.20% |
| 026309 | BRACKET, AIR BAG, REAR | Dellinger Enterprises, LTD | USA | Belmont, NC | 1 | 0 | 100% | 0.02% | 0.02% | -0.01% | 74.22% |
| 026310 | BRACKET, AIR BAG, REAR | Dellinger Enterprises, LTD | USA | Belmont, NC | 1 | 0 | 100% | 0.02% | 0.02% | -0.01% | 74.24% |
| 026312 | BRACKET | Dellinger Enterprises, LTD | USA | Belmont, NC | 1 | 0 | 100% | 0.02% | 0.02% | -0.01% | 74.26% |
| 026313 | BRACKET | Dellinger Enterprises, LTD | USA | Belmont, NC | 1 | 0 | 100% | 0.02% | 0.02% | -0.01% | 74.28% |
| 034769 | ANTENNA, TELEMETRY | Mobile Mark Inc | USA | Itasca, IL | 1 | 0 | 100% | 0.02% | 0.02% | -0.01% | 74.30% |
| 041139-001 | PLATE, SWITCH, SIDE CONSOLE, FORWARD | Seifert Graphics, Inc. | USA | Oriskany, NY | 1 | 0 | 100% | 0.02% | 0.02% | -0.01% | 74.32% |
| 020746 | FOAM BACKING, WALL .75",FOAM BACKING | Munaco Sealing Solutions, Inc. | USA | Greenville, SC | 44.1 | 0 | 100% | 0.02% | 0.02% | -0.01% | 74.33% |
| 041162 | PLATE, SWITCH, DASH, SS | Seifert Graphics, Inc. | USA | Oriskany, NY | 1 | 0 | 100% | 0.02% | 0.02% | -0.01% | 74.35% |
| 051043 | HARNES, LV BATTERY JUMPER (BATJ) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.02% | 0.02% | -0.01% | 74.37% |
| 019649 | SUPPORT: INVERTER, CAGE | 0 | USA | Fort Payne, AL | 2 | 0 | 100% | 0.02% | 0.02% | -0.01% | 74.39% |
| 044352 | PASS THRU, COOLANT, ROOF | Tube Specialties | USA | Troutdale, OR | 1 | 0 | 100% | 0.02% | 0.02% | -0.01% | 74.41% |
| 044088 | TUBE, COOLANT | Tube Specialties | USA | Troutdale, OR | 1 | 0 | 100% | 0.02% | 0.02% | -0.01% | 74.42% |
| 043648 | TUBE, COOLANT | Tube Specialties | USA | Troutdale, OR | 1 | 0 | 100% | 0.02% | 0.02% | -0.01% | 74.44% |
| 049786 | PLATE, REAR DECK, CS | Watson Engineering | USA | Piedmont, SC | 1 | 0 | 100% | 0.02% | 0.02% | -0.01% | 74.46% |
| 045326 | GUARD, CABLE, HV | Laserform and Machine Inc | USA | Columbia, SC | 1 | 0 | 100% | 0.02% | 0.02% | -0.01% | 74.48% |
| 049787 | PLATE, REAR DECK, SS | Watson Engineering | USA | Piedmont, SC | 1 | 0 | 100% | 0.02% | 0.02% | -0.01% | 74.50% |
| 044775 | PLATE, WW BOX, SS CLOSEOUT | Ananda Tooling, Inc. | USA | Chino, CA | 1 | 0 | 100% | 0.02% | 0.02% | -0.01% | 74.51% |
| 050184 | SUPPORT, WIPER SPINDLE | Spectfab Services, Inc | USA | Greenville, SC | 2 | 0 | 100% | 0.02% | 0.02% | -0.01% | 74.53% |
| 048503 | PLATE, PASS-THRU, REAR, AIR | Metal Solutions, Inc. | USA | Columbia, SC | 1 | 0 | 100% | 0.02% | 0.02% | -0.01% | 74.55% |



| PART NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY/VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|-------------|---|--------------------------------|---|---|-------------|-----------------|--------------|--------------------|-------|---------|------------|
| 040974 | BRACKET, HV RE-DIRECT | Laserform and Machine Inc | USA | Columbia, SC | 1 | 0 | 100% | 0.02% | 0.02% | -0.01% | 74.56% |
| 020405 | PANEL, ADA RAMP CLOSE-OUT | Specfab Services, Inc | USA | Greenville, SC | 1 | 0 | 100% | 0.02% | 0.02% | -0.01% | 74.58% |
| 044863 | BRACKET, POWER STEERING | Ananta Tooling, Inc. | USA | Chino, CA | 1 | 0 | 100% | 0.02% | 0.02% | -0.01% | 74.60% |
| 049845 | HARNESS, LOW VOLTAGE POWER INTERNAL (IPWR108) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | | 100% | 0.02% | 0.02% | -0.01% | 74.61% |
| 038239 | CABLE ASSY, DC LINK, HVAC VFD | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.02% | 0.02% | -0.01% | 74.63% |
| 045743 | PANEL, CEILING, HERON, HATCH | KensonPlastics Inc | USA | Beaver Falls, PA | 2 | 0 | 100% | 0.02% | 0.02% | -0.01% | 74.65% |
| 049867 | HARNESS, LOW VOLTAGE POWER EXTERNAL (EPWR115) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.02% | 0.02% | -0.01% | 74.66% |
| 023108 | CLOSEOUT, HATCH ESCAPE | Specialty Manufacturing Inc | USA | Grand Rapids, MI | 2 | 0 | 100% | 0.02% | 0.02% | -0.01% | 74.68% |
| 049262 | BRACKET, SK7 VALVE | Specfab Services, Inc | USA | Greenville, SC | 1 | 0 | 100% | 0.02% | 0.02% | -0.01% | 74.70% |
| 023800 | SPACER PLATE, GEAR BOX | Dellinger Enterprises, LTD | USA | Belmont, NC | 1 | 0 | 100% | 0.02% | 0.02% | -0.01% | 74.71% |
| 044723 | HARNESS, SS ITS CABINET (SSIT) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | | 100% | 0.02% | 0.02% | -0.01% | 74.73% |
| 050771 | HARNESS, FRONT OF BUS EXTERNAL (FRBP) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.02% | 0.02% | -0.01% | 74.75% |
| 023834 | SPACER, BELT, ADA | Metal Solutions, Inc. | USA | Vandergrift, PA | 2 | 0 | 100% | 0.02% | 0.02% | -0.01% | 74.76% |
| 043156 | BRACKET, BROADWAY COVER, CENTER | Laserform and Machine Inc | USA | Columbia, SC | 4 | 0 | 100% | 0.02% | 0.02% | -0.01% | 74.78% |
| 027880 | ISOLATOR, TUBE | J F Industries Inc | USA | Woburn, MA | 4 | 0 | 100% | 0.02% | 0.02% | -0.01% | 74.79% |
| 000572 | SWITCH, CONTROL, MIRROR | Safe Fleet Bus & Rail | USA | Elkhart, IN | 2 | 0 | 100% | 0.02% | 0.02% | -0.01% | 74.81% |
| 014656 | BROADWAY FRONT COVER | Specfab Services, Inc | USA | Greenville, SC | 1 | 0 | 100% | 0.02% | 0.02% | -0.01% | 74.82% |
| 044676 | BRACKET, MOUNT FRAME, C/S | Lock-Ridge Tool Co., Inc. | USA | Grand Rapids, MI | 1 | 0 | 100% | 0.02% | 0.02% | -0.01% | 74.84% |
| 052583 | HARNESS, FRONT CURBSIDE WHEEL WELL (ABS) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.02% | 0.02% | 0.00% | 74.86% |
| 052585 | HARNESS, FRONT STREETSIDE WHEEL WELL (ABS) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.02% | 0.02% | 0.00% | 74.87% |
| 001162 | HITTING, PIC, COMPOSITE, 90 DEG, SWIVEL, 3/8 MPTX 3/8 TUBE" | Hydradyne LLC | USA | Otsego, MI | 13 | 0 | 100% | 0.02% | 0.02% | 0.00% | 74.89% |
| 029089 | CABLE, 13.5M, TO REAR SIGN | Hanover Displays | USA | ELK GROVE VILLAGE, IL | 1 | 0 | 100% | 0.02% | 0.02% | 0.00% | 74.90% |
| 045120 | ENCLOSURE, HEADLIGHT, SS | KensonPlastics Inc | USA | Beaver Falls, PA | 1 | 0 | 100% | 0.02% | 0.02% | 0.00% | 74.92% |
| 045121 | ENCLOSURE, HEADLIGHT, CS | KensonPlastics Inc | USA | Beaver Falls, PA | 1 | 0 | 100% | 0.02% | 0.02% | 0.00% | 74.93% |
| 046838 | BRACKET, FRONT DESTINATION SIGN, CS | Watson Engineering | USA | Piedmont, SC | 1 | 0 | 100% | 0.02% | 0.02% | 0.00% | 74.95% |
| 046839 | BRACKET, FRONT DESTINATION SIGN, SS | Watson Engineering | USA | Piedmont, SC | 1 | 0 | 100% | 0.02% | 0.02% | 0.00% | 74.96% |
| 020748 | FOAM BACKING, WALL 1", FOAM BACKING | Munaco Sealing Solutions, Inc. | USA | Greenville, SC | 39 | 0 | 100% | 0.02% | 0.02% | 0.00% | 74.98% |
| 051605 | PLATE, WW BOX, CS STORAGE, AFT | Specfab Services, Inc | USA | Greenville, SC | 1 | 0 | 100% | 0.02% | 0.02% | 0.00% | 74.99% |
| 031536 | BRACKET, SUPPORT | Specfab Services, Inc | USA | Greenville, SC | 1 | 0 | 100% | 0.01% | 0.02% | 0.00% | 75.01% |



| PAK NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY / VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|------------|---|-------------------------------|---|---|---------------|-----------------|--------------|--------------------|-------|---------|------------|
| 041781 | POWERTRAIN ECU | PI Inovo, LLC | USA | Auburn Hills, MI | 1 | 0 | 22% | 0.07% | 0.02% | 0.05% | 75.02% |
| 044673 | BRACKET, FRAME, ECAB, CS | Industrial Fabricators, Inc. | USA | Chino, CA | 1 | 0 | 100% | 0.01% | 0.02% | 0.00% | 75.04% |
| 000329 | MIRROR, INTERIOR, CONVEX, 12 ROUND" | Safe Fleet Bus & Rail | USA | Elkhart, IN | 1 | 0 | 100% | 0.01% | 0.02% | 0.00% | 75.05% |
| 052620 | BRACKET, BONDED, CS A-PILLAR, CENTER, HERON | Dixie Rubber & Plastics, Inc. | USA | Greenville, SC | 1 | 0 | 100% | 0.01% | 0.02% | 0.00% | 75.07% |
| 043467 | HINGE BACKPLATE | Metal Solutions, Inc. | USA | Grand Rapids, MI | 4 | 0 | 100% | 0.01% | 0.02% | 0.00% | 75.08% |
| 019367 | AIR LINE, BRAKE 33" AIR LINE | Hydradyne LLC | USA | Greensboro, NC | 2 | 0 | 100% | 0.01% | 0.02% | 0.00% | 75.09% |
| 050622 | BRACKET, AIR TANK, RV-3 VALVE | Dellinger Enterprises, LTD | USA | Belmont, NC | 1 | 0 | 100% | 0.01% | 0.02% | 0.00% | 75.11% |
| 045745 | PANEL, CEILING, HERON, REAR | Kenson Plastics Inc | USA | Beaver Falls, PA | 2 | 0 | 100% | 0.01% | 0.02% | 0.00% | 75.12% |
| 046717 | BRACKET, REAR DECK, CENTER PANEL | Aranda Tooling, Inc. | USA | Chino, CA | 1 | 0 | 100% | 0.01% | 0.02% | 0.00% | 75.14% |
| 057321 | BRACKET, ECU, TRANSMISSION | Metal Solutions, Inc. | USA | Grand Rapids, MI | 1 | 0 | 100% | 0.01% | 0.02% | 0.00% | 75.15% |
| 033222 | WASHER, FLAT, M6 | NSK Industries Inc | USA | Bristol, IN | 145 | 0 | 100% | 0.01% | 0.02% | 0.00% | 75.16% |
| 049868 | HARNES, LOW VOLTAGE POWER EXTERNAL (EPWR116) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.01% | 0.02% | 0.00% | 75.18% |
| 030233 | RELIEF VALVE: PILOT OPERATED: 2100 PSI | Cross Company. | USA | Sarasota, FL | 1 | 0 | 100% | 0.01% | 0.02% | 0.00% | 75.19% |
| 049898 | HARNES, LOW VOLTAGE POWER EXTERNAL (EPWR102) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.01% | 0.02% | 0.00% | 75.21% |
| 050621 | BRACKET, VALVE, AIR | Dellinger Enterprises, LTD | USA | Belmont, NC | 1 | 0 | 100% | 0.01% | 0.02% | 0.00% | 75.22% |
| 053944 | CONTROLLER, VEHICLE, M580, M02 | PI Inovo, LLC | USA | Auburn Hills, MI | 1 | 0 | 11% | 0.12% | 0.02% | 0.10% | 75.23% |
| 044773 | BRACKET, WHEEL WELL BOX, CS, RR | Metal Solutions, Inc. | USA | Vandergrift, PA | 1 | 0 | 100% | 0.01% | 0.02% | 0.00% | 75.25% |
| 044774 | BRACKET, WHEEL WELL BOX, CS, RR | Metal Solutions, Inc. | USA | Vandergrift, PA | 1 | 0 | 100% | 0.01% | 0.02% | 0.00% | 75.26% |
| 045123 | BRACKET, MOUNT, LIGHTING, CS | Laserform and Machine Inc | USA | Columbia, SC | 1 | 0 | 100% | 0.01% | 0.02% | 0.00% | 75.27% |
| 045122 | BRACKET, MOUNT, LIGHTING, SS | Laserform and Machine Inc | USA | Columbia, SC | 1 | 0 | 100% | 0.01% | 0.02% | 0.00% | 75.29% |
| 044255 | FENDER FLARE, FRONT | Dynatect Manufacturing | USA | Tracy, CA | 2 | 0 | 100% | 0.01% | 0.02% | 0.00% | 75.30% |
| 039848 | PLATE, PASS THRU | Watson Engineering | USA | Piedmont, SC | 1 | 0 | 100% | 0.01% | 0.02% | 0.00% | 75.31% |
| 007857 | GRIP TAPE, BLACK, 12 WIDE" | MI Graphics CO, Inc | USA | Fountain Inv, SC | 8 | 0 | 100% | 0.01% | 0.02% | 0.00% | 75.33% |
| 019365 | AIR LINES, BRAKE, 24 | Hydradyne LLC | USA | Greensboro, NC | 2 | 0 | 100% | 0.01% | 0.02% | 0.00% | 75.34% |
| 021691 | LIGHT, BACK UP LED, REAR | Dialight Corporation | Mexico | Ensenada, BC | 2 | 0 | 53% | 0.02% | 0.02% | 0.01% | 75.35% |
| 004318 | HITTING, BRASS, PTC, UNION, BULKHEAD, 1/2 TUBE" | Hydradyne LLC | USA | Okego, MI | 5 | 0 | 100% | 0.01% | 0.02% | 0.00% | 75.36% |
| 042861 | PASS THRU, COOLANT, LOWER DECK | Tube Specialties | USA | Trousdale, OR | 1 | 0 | 100% | 0.01% | 0.02% | 0.00% | 75.38% |
| 052105 | END CAP, OVERHEAD AIR DAM | Superior Interior Systems | USA | Grand Rapids, MI | 1 | 0 | 100% | 0.01% | 0.02% | 0.00% | 75.39% |
| 052106 | END CAP, OVERHEAD AIR DAM | Superior Interior Systems | USA | Grand Rapids, MI | 1 | 0 | 100% | 0.01% | 0.02% | 0.00% | 75.40% |
| 052107 | END CAP, OVERHEAD AIR DAM | Superior Interior Systems | USA | Grand Rapids, MI | 1 | 0 | 100% | 0.01% | 0.02% | 0.00% | 75.41% |
| 052108 | END CAP, OVERHEAD AIR DAM | Superior Interior Systems | USA | Grand Rapids, MI | 1 | 0 | 100% | 0.01% | 0.02% | 0.00% | 75.43% |
| 042485 | PANEL, ENCL, HVJB, COVER, SEALED | Lock-Ridge Tool Co., Inc. | USA | Grand Rapids, MI | 1 | 0 | 100% | 0.01% | 0.02% | 0.00% | 75.44% |



| PART NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY / VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|---------------|---|-------------------------------|---|---|---------------|-----------------|--------------|--------------------|-------|---------|------------|
| 049344 | TUBE, COOLANT | Tube Specialties | USA | Troutdale, OR | 1 | 0 | 100% | 0.01% | 0.02% | 0.00% | 75.45% |
| 049864 | HARNES,LOW VOLTAGE POWER EXTERNAL (EPWR112) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | | 100% | 0.01% | 0.02% | 0.00% | 75.46% |
| 046605 | MUDELAP, FRONT | Dynatec Manufacturing | USA | Tracy, CA | 2 | 0 | 100% | 0.01% | 0.02% | 0.00% | 75.47% |
| 017468 | BRUSH,DOOR | Sealze | USA | Richmond, IN | 1 | 0 | 100% | 0.01% | 0.02% | 0.00% | 75.49% |
| 038508 | GASKET, SIDE MARKER LIGHTS | Dixie Rubber & Plastics, Inc. | USA | Greenville, SC | 14 | 0 | 100% | 0.01% | 0.02% | 0.00% | 75.50% |
| 043909 | BRACKET, SUPPORT | Ananda Tooling, Inc. | USA | Chino, CA | 2 | 0 | 100% | 0.01% | 0.02% | 0.00% | 75.51% |
| 050235 | HARNES, TRUNK (TRUNK) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.01% | 0.02% | 0.00% | 75.52% |
| 000638 | FITTING, STEEL, ADAPTER, 5/8 M 37 DEG FLARE M MET | Hydradyne LLC | USA | USA | 4 | 0 | 100% | 0.01% | 0.02% | 0.00% | 75.53% |
| 043881 | BRACKET, ARMREST, AIR | Lock-Ridge Tool Co., Inc. | USA | Grand Rapids, MI | 1 | 0 | 100% | 0.01% | 0.02% | 0.00% | 75.54% |
| 046718 | BRACKET, REAR DECK, CENTER PANEL, COVER | Ananda Tooling, Inc. | USA | Chino, CA | 1 | 0 | 100% | 0.01% | 0.02% | 0.00% | 75.56% |
| 039860 | BUS BAR | Watson Engineering | USA | Piedmont, SC | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 75.57% |
| 024857-03AA04 | PANEL, ACCESS | Kenson Plastics Inc | USA | Beaver Falls, PA | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 75.58% |
| 034145 | STUD PLATE, COOLANT | Lock-Ridge Tool Co., Inc. | USA | Pomona, CA | 7 | 0 | 100% | 0.01% | 0.01% | 0.00% | 75.59% |
| 051896 | HEADLIGHT BEZEL SS | Kenson Plastics Inc | USA | Beaver Falls, PA | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 75.60% |
| 051897 | HEADLIGHT BEZEL CS | Kenson Plastics Inc | USA | Beaver Falls, PA | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 75.61% |
| 042355 | LABEL, KEY ON | M1 Graphics CO, Inc | USA | Fountain Inv, SC | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 75.62% |
| 042558 | DECAL, DIAGNOSTIC PORT | M1 Graphics CO, Inc | USA | Fountain Inv, SC | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 75.63% |
| 017126 | FITTING, 5/8 PTC, BULKHEAD | Hydradyne LLC | USA | Otsego, MI | 4 | 0 | 100% | 0.01% | 0.01% | 0.00% | 75.64% |
| 045386 | PLATE, SWITCH , SIDE CONSOLE, LWR | Seifert Graphics, Inc. | USA | Oriskany, NY | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 75.65% |
| 037335 | TUBE, COOLANT | Hydradyne LLC | USA | Ravenna, OH | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 75.67% |
| 006363 | FITTING, STAINLESS, TEE, SAE 8, MALLE X FEMALE X MALE | Hydradyne LLC | USA | USA | 2 | 0 | 100% | 0.01% | 0.01% | 0.00% | 75.68% |
| 043700 | BRACKET, SUPPORTS | Ananda Tooling, Inc. | USA | Chino, CA | 7 | 0 | 100% | 0.01% | 0.01% | 0.00% | 75.69% |
| 047457 | BRACKET, PANEL, REAR, OVERHEAD, C/S | Griffiths Coporation | USA | Pineville, NC | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 75.70% |
| 047458 | BRACKET, PANEL, REAR, OVERHEAD, S/S | Griffiths Coporation | USA | Pineville, NC | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 75.71% |
| 000328 | MIRROR, FLAT, 6 ROUND" | Safe Fleet Bus & Rail | USA | Elkhart, IN | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 75.72% |
| 025975 | TRAY, WASHER TANK | Laserform and Machine Inc | USA | Columbia, SC | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 75.73% |
| 019157 | PLATE,AIR SPRING | Lock-Ridge Tool Co., Inc. | USA | Columbia, SC | 4 | 0 | 100% | 0.01% | 0.01% | 0.00% | 75.74% |
| 025140 | SWITCH ASSEMBLY, E/A (EASW) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 75.75% |
| 048984 | FITTING, PTC, BRASS, TEE, BRANCH, RIGID, 1/2" PTC X 1/2" MPT X 3/8" PTC | Hydradyne LLC | USA | Otsego, MI | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 75.76% |
| 017103 | CLOSEOUT ADA, FINISHING | SpecFab Services, Inc | USA | Greenville, SC | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 75.77% |
| 024883 | SUPPORT, FRAME | SpecFab Services, Inc | USA | Greenville, SC | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 75.78% |



| PART NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY/VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|---------------|--|----------------------------|---|---|-------------|-----------------|--------------|--------------------|-------|---------|------------|
| 014658 | BROADWAY COVER REAR | SpecFab Services, Inc | USA | Greenville, SC | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 75.79% |
| 049872 | HARNES,LOW VOLTAGE POWER EXTERNAL (EPWR122) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 75.80% |
| 045017 | HITTING, PTC, COMPOSITE, 90 DEG, SWIVEL, 1/4 MPT X 1/2 PTC | Hydradyne LLC | USA | Otsego, MI | 6 | 0 | 100% | 0.01% | 0.01% | 0.00% | 75.81% |
| 046310 | HARNES, CUSTOMER VFC (CPWR) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 75.82% |
| 049856 | HARNES,LOW VOLTAGE POWER EXTERNAL (EPWR104) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 75.83% |
| 018317 | BELLYPAN,SIDE,CAGE | Lock-Ridge Tool Co., Inc. | USA | Pomona, CA | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 75.84% |
| 018316 | BELLYPAN,SIDE,CAGE | Lock-Ridge Tool Co., Inc. | USA | Pomona, CA | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 75.85% |
| 049871 | HARNES,LOW VOLTAGE POWER EXTERNAL (EPWR121) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 75.86% |
| 024643-03AA04 | BOX, E-RELEASE, EXIT DOOR | KensonPlastics Inc | USA | Beaver Falls, PA | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 75.87% |
| 018773 | WASHER, PLAIN, .53x1.06x.10 | Bossard North America Inc | USA | Milwaukee, WI | 10 | 0 | 100% | 0.01% | 0.01% | 0.00% | 75.88% |
| 025851-002 | TRIM, H-CHANNEL | Seagate Plastics Company | USA | Waterville, OH | 15 | 0 | 100% | 0.01% | 0.01% | 0.00% | 75.89% |
| 043991 | TUBE, COOLANT | Tube Specialties | USA | Troutdale, OR | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 75.90% |
| 041046 | BRACKET, GROUND BLOCK | Lock-Ridge Tool Co., Inc. | USA | Grand Rapids, MI | 2 | 0 | 100% | 0.01% | 0.01% | 0.00% | 75.91% |
| 044797 | BRACKET, ECAB, FOOT | Laserform and Machine Inc | USA | Columbia, SC | 2 | 0 | 100% | 0.01% | 0.01% | 0.00% | 75.92% |
| 050335 | CLOSEOUT, FOOT, RIGHT | SpecFab Services, Inc | USA | Greenville, SC | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 75.93% |
| 039859 | BUS BAR | Watson Engineering | USA | Piedmont, SC | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 75.94% |
| 008559 | EXTINGUISHER, FIRE, 5 LB | Kidde Technologies, Inc. | USA | Mebane, NC | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 75.95% |
| 013914 | BRACKET, FRONT BUMPER | Dellinger Enterprises, LTD | USA | Belmont, NC | 2 | 0 | 100% | 0.01% | 0.01% | 0.00% | 75.96% |
| 044800 | PANEL, CLOSEOUT, WW BOX, CS | Amanda Tooling, Inc. | USA | Chino, CA | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 75.97% |
| 044227 | BRACKET, FILL, AIR | GH Metal Solutions, Inc. | USA | Fort Payne, AL | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 75.98% |
| 025630 | SUPPORT, COLUMN, STEERING | SpecFab Services, Inc | USA | Greenville, SC | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 75.99% |
| 015000 | BRACKET, CROSSMEMBER SUPPORT, CENTER | SpecFab Services, Inc | USA | Greenville, SC | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.00% |
| 025150 | COVER, FASTENER, SIDE SIGN | Dellinger Enterprises, LTD | USA | Belmont, NC | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.01% |
| 045741 | PANEL, CEILING, HERON, FRONT | KensonPlastics Inc | USA | Beaver Falls, PA | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.01% |
| 027472 | BRACKET, BROADWAY COVER, CENTER PASS THRU | Laserform and Machine Inc | USA | Columbia, SC | 2 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.02% |
| 045179 | HARNES, OVERHEAD RAIL (OHRL) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.03% |
| 042678 | BRACKET, SUPPORT | SpecFab Services, Inc | USA | Greenville, SC | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.04% |
| 040959 | PLATE, HV CABLE REDIRECT | Metal Solutions, Inc. | USA | Grand Rapids, MI | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.05% |
| 046886 | KICKPLATE, WW BOX, SS, INBOARD | Griffiths Coporation | USA | Pineville, NC | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.06% |
| 049839 | HARNES, LOW VOLTAGE POWER INTERNAL (IPWR101) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.07% |



| PART NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY / VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|-------------|---|------------------------------|---|---|---------------|-----------------|--------------|--------------------|-------|---------|------------|
| 018422 | WASHER, SNUBBING, STL, HDN, 1000HSS, M16 | Bossard Inc. | USA | Milwaukee, WI | 10 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.08% |
| 038841 | PASSTHROUGH, AIR SYSTEM, FRONT TOW | Metal Solutions, Inc. | USA | Grand Rapids, MI | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.09% |
| 049849 | HARNESS, LOW VOLTAGE POWER INTERNAL (IPWR112) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.10% |
| 043902 | BRACKET, STRAP | Speclab Services, Inc | USA | Greenville, SC | 2 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.10% |
| 029090 | EMERGENCY INPUT AND J1708 CONNECTION | Hanover Displays | USA | ELK GROVE VILLAGE, IL | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.11% |
| 044257 | HENDER, FLARE, REAR (SS) | Dynatect Manufacturing | USA | Tracy, CA | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.12% |
| 044256 | HENDER FLARE, REAR (CS) | Dynatect Manufacturing | USA | Tracy, CA | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.13% |
| 042888 | PLUG VALVE, 1/4" MPT X 1/4" FPT | Hydradyne LLC | USA | Albion, IN | 3 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.14% |
| 045832 | CATCH, LATCH, TRUNK | Dellinger Enterprises, LTD | USA | Belmont, NC | 2 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.15% |
| 044737 | BRACKET, FRAME, ECAB, SHORT-SIDE | Industrial Fabricators, Inc. | USA | Chino, CA | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.16% |
| | INSERT, AW SERIES, M6-1.0 | Bossard North America Inc | USA | Akron, OH | 45 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.16% |
| 040773 | TUBE, COOLANT | Tube Specialties | USA | Troutdale, OR | 1 | 1 | 100% | 0.01% | 0.01% | 0.00% | 76.17% |
| 027032 | BADGE, LOGO | Weston and Company, Inc. | USA | Goddard, KS | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.18% |
| 046769 | BRACKET, REAR DECK, UPPER ACCESS PANEL, SUPPORT | Speclab Services, Inc | USA | Greenville, SC | 2 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.19% |
| 043877 | TUBE, COOLANT | Tube Specialties | USA | Troutdale, OR | 2 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.20% |
| 044950 | BRACKET, MOUNT FRAME, S/S | GH Metal Solutions, Inc. | USA | Fort Payne, AL | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.21% |
| 051606 | PLATE, WW BOX, CS STORAGE, FORE | Speclab Services, Inc | USA | Greenville, SC | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.21% |
| 046743 | BRACKET, MUDDLAP | Dynatect Manufacturing | USA | Tracy, CA | 2 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.22% |
| 044029 | SPACER, PANEL, ENCL, ALUM, BOD | Dellinger Enterprises, LTD | USA | Belmont, NC | 2 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.23% |
| 051044 | HARNESS, LOW VOLTAGE EQUALIZER (LVEQ) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.24% |
| 043914 | PLATE, PASSTHRU, ECAB | Amanda Tooling, Inc. | USA | Chino, CA | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.24% |
| 044801 | MOUNT, BRACKET, WHEEL WELL, SS | Amanda Tooling, Inc. | USA | Chino, CA | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.25% |
| 053065 | PLATE, JACKING POINT, CS-SS | Watson Engineering | USA | Piedmont, SC | 2 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.26% |
| 049850 | HARNESS, LOW VOLTAGE POWER INTERNAL (IPWR113) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.27% |
| 000326 | MIRROR, INT. FLAT, 4.75 X 15.875 (REAR VIEW)" | Safe Fleet Bus & Rail | USA | Elkhart, IN | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.28% |
| 006043 | MANIFOLD, LINE-MOUNT, RELIEF, 2 PORT, 90 DEGREE | Cross Company. | USA | Sarasota, FL | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.28% |
| 021992 | CABLE, SIGN, POINT TO POINT STANDARD | Hanover Displays | USA | ELK GROVE VILLAGE, IL | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.29% |
| 044942 | PLATE, ITS, SWITCHES | Dellinger Enterprises, LTD | USA | Belmont, NC | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.30% |



| PART NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY/VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|---------------|--|--------------------------------------|---|---|-------------|-----------------|--------------|--------------------|-------|---------|------------|
| 044437 | BRACKET, CHECK VALVE, DRIVERS ARMREST | Amada Tooling, Inc. | USA | Chino, CA | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.31% |
| 044168 | TUBE, COOLANT | Tube Specialties | USA | Troutdale, OR | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.31% |
| 047047 | KICKPLATE, WW BOX, SS, REAR | Griffiths Corporation | USA | Pineville, NC | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.32% |
| 014948 | BRACKET, ADA RAMP | SpecFab Services, Inc | USA | Greenville, SC | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.33% |
| 020088 | ADAPTER,FAN | Kerson Plastics Inc | USA | Beaver Falls, PA | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.34% |
| 044126 | TUBE, COOLANT | Tube Specialties | USA | Troutdale, OR | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.34% |
| 044692 | HARNES, MIRROR (MIRS) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | | 100% | 0.01% | 0.01% | 0.00% | 76.35% |
| 019737-003 | PLATE, STUD, 1/4-20X.25, M6-1.0X16 | Rotaloc Intl, LLC | Taiwan | Taiwan | 69 | 0 | 50% | 0.01% | 0.01% | 0.00% | 76.36% |
| 041218 | HARNES,PRODRIVE SWITCH(PDSW) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | | 100% | 0.01% | 0.01% | 0.00% | 76.37% |
| 042217 | PLATE, STUD | Metal Solutions, Inc. | USA | Grand Rapids, MI | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.37% |
| 045932 | PLATE, DRIVERS SEAT, HERON | Amada Tooling, Inc. | USA | Chino, CA | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.38% |
| 016087 | BRACKET, CROSSMEMBER, FRONT | SpecFab Services, Inc | USA | Greenville, SC | 2 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.39% |
| 046272 | HARN,AUX FUSE BUS,POSITIVE | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.39% |
| 033673 | BRACKET, STUD | Metal Solutions, Inc. | USA | Grand Rapids, MI | 4 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.40% |
| 018048 | SPACER | Metal Solutions, Inc. | USA | Vandergrift, PA | 2 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.41% |
| 044543 | BRACKET, SUPPORT, DEFROSTER | G.H.Metal Solutions, Inc. | USA | Fort Payne, AL | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.41% |
| 052443 | BRACKET, CS A-PILLAR, UPPER, HERON | Amada Tooling, Inc. | USA | Chino, CA | 1 | | 100% | 0.01% | 0.01% | 0.00% | 76.42% |
| 050063 | DECAL, 50/50 ETHYLENE GLYCOL | Seifert Graphics, Inc. | USA | Oriskany, NY | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.43% |
| 045453-01AA01 | PANEL, WALL, FLAT, C/S REAR | Kerson Plastics Inc | USA | Beaver Falls, PA | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.43% |
| 045454-01AA01 | PANEL, WALL, FLAT, S/S REAR | Kerson Plastics Inc | USA | Beaver Falls, PA | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.44% |
| 043009-012 | FORMED AIRLINE, 5/8" OD, .09" WALL, RED | HydraDyne LLC | USA | Ravenna, OH | 2 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.45% |
| 017093 | SCR, TEK, PH, TORX, #8 HD, 410 SS, BLK OX, # 10-16x1 | Bossard North America Inc | USA | Rockford, IL | 334 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.45% |
| 021990 | ERIC POWER/COMMS STANDARD | Hanover Displays | USA | ELK GROVE VILLAGE, IL | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.46% |
| 021991 | CABLE, SPLITTER, FRONT SIGN TO CONTROLLER | Hanover Displays | USA | ELK GROVE VILLAGE, IL | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.47% |
| 021569 | HARNES, ADA RAMP 4.1 JUMPER | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.47% |
| 040216 | CABLE ASSEMBLY,OH CHARGE ANTENNA (W/H) | Mobile Mark Inc | USA | Itasca, IL | 1 | | 100% | 0.01% | 0.01% | 0.00% | 76.48% |
| 030294 | BRACKET, SIDE SIGN | Griffiths Corporation | USA | Pineville, NC | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.49% |
| 019183 | BRACKET, BUMPER, FRONT | Dellinger Enterprises, LTD | USA | Belmont, NC | 2 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.49% |
| 031710 | SHIP KIT | Danfoss Power Solutions (US) Company | USA | Lomont, CO | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.50% |
| 000657 | FITTING, PTC, BRASS 1/2 MPT 5/8 INCH OD TUBE | HydraDyne LLC | USA | Otsego, MI | 4 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.50% |
| 017704 | DECAL, DO NOT TOUCH, VERTICAL | M1 Graphics CO, Inc | USA | Fountain Inn, SC | 4 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.51% |



| PART NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY / VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|-------------|--|--------------------------------|---|---|---------------|-----------------|--------------|--------------------|-------|---------|------------|
| 044505 | HOSE, 2.5", DEFROSTER | Dixie Rubber & Plastics, Inc. | USA | Abbeville, SC | 0.48 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.52% |
| 052442 | BRACKET, CS A-PILLAR, LOWER, HERON | Aranda Tooling, Inc. | USA | Chino, CA | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.52% |
| 023797 | STUD PLATE | Dellinger Enterprises, LTD | USA | Belmont, NC | 2 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.53% |
| 046215 | FOAM, BACKING, WALL, .75" | Munaco Sealing Solutions, Inc. | USA | Greenville, SC | 24 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.53% |
| 044246 | HITTING, COMPOSITE, RUN TEE, 1/2 MPT X 1/2 PTC X 1/2 PTC | Hydradyne LLC | USA | Oshego, MI | 2 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.54% |
| 052825 | PLATE, JACKING POINT, SS-CS | Watson Engineering | USA | Piedmont, SC | 2 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.54% |
| 017232 | TUBE, NYLON, 6MM OD, IMM WALL | Hydradyne LLC | USA | Ravenna, OH | 600 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.55% |
| 027985 | NUT, INSERT, M8-1.25 | J F Industries Inc | USA | Valencia, CA | 49 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.56% |
| 051916 | PLATE, MOUNTING, BASE PEDAL, FRONT | Aranda Tooling, Inc. | USA | Chino, CA | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.56% |
| 014968 | BRACKET, CROSSMEMBER, CENTER | GH Metal Solutions, Inc. | USA | Fort Payne, AL | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.57% |
| 020697 | COVER, SPEAKER, OUTSIDE | Aranda Tooling, Inc. | USA | Chino, CA | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.57% |
| 038178 | BRACKET, TIE-DOWN, HV CABLE | Metal Solutions, Inc. | USA | Vandegrift, PA | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.58% |
| 043009-011 | FORMED AIRLINE, 1/2" OD, .06" WALL, RED | Hydradyne LLC | USA | Ravenna, OH | 2 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.59% |
| 040845 | BRACKET, LIGHT | Industrial Fabricators, Inc. | USA | Piedmont, SC | 2 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.59% |
| 049862 | HARNESS, LOW VOLTAGE POWER EXTERNAL (EPWR110) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.60% |
| 027288 | BRACKET, SUPPORT, GAS SHOCK | Dellinger Enterprises, LTD | USA | Belmont, NC | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.60% |
| 027289 | BRACKET, SUPPORT, GAS SHOCK | Dellinger Enterprises, LTD | USA | Belmont, NC | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.61% |
| 044966 | CLOSEOUT, STEERING SHAFT | Specfab Services, Inc | USA | Greenville, SC | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.61% |
| 008797 | SWITCH KNOB FOR DEFROSTER (8795 AND 8796) | Therma-Tech (A.R. Lintern) | USA | Carol Stream, IL | 4 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.62% |
| 038177 | BRACKET, TIE-DOWN, HV CABLE | Metal Solutions, Inc. | USA | Vandegrift, PA | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.62% |
| 018015 | BRACKET, MUDBLAP | Dellinger Enterprises, LTD | USA | Belmont, NC | 2 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.63% |
| 045742 | PANEL, CEILING, HERON, END | KensonPlastics Inc | USA | Beaver Falls, PA | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.63% |
| 049846 | HARNESS, LOW VOLTAGE POWER INTERNAL (IPWR110) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.64% |
| 039698 | PLATE, PASSTHRU | Dellinger Enterprises, LTD | USA | Belmont, NC | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.65% |
| 043009-009 | FORMED AIRLINE, 3/8" OD, .06" WALL, RED | Hydradyne LLC | USA | Ravenna, OH | 2 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.65% |
| 024186 | LOOP | Lock-Ridge Tool Co., Inc. | USA | Pomona, CA | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.66% |
| 033325 | BRACKET, SUPPORT, CONNECTOR | Metal Solutions, Inc. | USA | Grand Rapids, MI | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.66% |
| 037424 | COVER, HANDLE | Laserform and Machine Inc | USA | Columbia, SC | 2 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.67% |



| PART NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY / VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|-------------|--|-------------------------------|---|---|---------------|-----------------|--------------|--------------------|-------|---------|------------|
| 019043 | SPACER,STEER CAM | Griffiths Coporation | USA | Pineville, NC | 2 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.67% |
| 020988 | LIGHT, CLEARANCE, REAR | Dialight Coporation | Mexico | Ersenada, BC | 5 | 0 | 62% | 0.01% | 0.01% | 0.00% | 76.68% |
| 049865 | HARNES,LOW VOLTAGE POWER EXTERNAL (EPWR113) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.68% |
| 034544 | CABLE ASSEMBLY, TELEMETRY, GPS ANTENNA, 15' | Mobile Maak Inc | USA | Itasca, IL | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.69% |
| 041667 | BRACKET, SPLIT BLOCK | Dixie Rubber & Plastics, Inc. | USA | Greenville, SC | 2 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.69% |
| 044869 | PLATE, STUD, ARMREST, AIR | Amanda Tooling, Inc. | USA | Chino, CA | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.70% |
| 044694 | HARNES, ROOFTOP FRONT (RTFT) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.70% |
| 018892 | DECAL, WINDOW AHEAD, EMERGENCY EXIT | M1 Graphics CO, Inc | USA | Fountain Inn, SC | 6 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.71% |
| 045112 | PLATE, PASS THRU | Metal Solutions, Inc. | USA | Vandergrift, PA | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.71% |
| 044691 | HARNES, BUMPER (BMPN) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.72% |
| 004521 | HITTING, BULKHEAD, BRASS, 1/4 X 1/4" FPT" | Hydradyne LLC | USA | Otsego, MI | 11 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.72% |
| 014969 | BRACKET, CROSSMEMBER SUPPORT, CENTER | SpecFab Services, Inc | USA | Greenville, SC | 2 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.73% |
| 041676 | BRACKET, SPLIT BLOCK | Metal Solutions, Inc. | USA | Vandergrift, PA | 2 | 0 | 100% | 0.01% | 0.01% | 0.00% | 76.73% |
| 021689 | LIGHT, TAIL LAMP, REAR | Dialight Coporation | Mexico | Ersenada, BC | 2 | 0 | 34% | 0.01% | 0.01% | 0.01% | 76.74% |
| 033534 | BRACKET, SUPPORT, CONNECTOR | Amanda Tooling, Inc. | USA | Chino, CA | 2 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.74% |
| 046884 | KICKPLATE, WW BOX, CS, INBOARD | Griffiths Coporation | USA | Pineville, NC | 1 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.75% |
| 036317-001 | TRIM , WALL PANEL CAP MOLDING | Seagate Plastics Company | USA | Waterville, OH | 1 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.75% |
| 039719 | BRACKET, DEFROSTER, TOP | Dellinger Enterprises, LTD | USA | Belmont, NC | 2 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.76% |
| 052410 | BRACKET, ECAB, SS WHEEL WELL BOX | Laserform and Machine Inc | USA | Columbia, SC | 1 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.76% |
| 012265 | HITTING, BARB, ELBOW, #12FJIC, 3/4HOSE " | Hydradyne LLC | USA | Manitowac, WI | 2 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.77% |
| 020987 | LIGHT, CLEARANCE, FRONT | Dialight Coporation | Mexico | Ersenada, BC | 5 | 0 | 58% | 0.01% | 0.01% | 0.00% | 76.77% |
| 051915 | PLATE, MOUNTING, BASE PEDAL, REAR | Amanda Tooling, Inc. | USA | Chino, CA | 1 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.78% |
| 008796 | SWITCH, 3-WAY WITH OFF (OFF, LOW, MED, HI) DEFROST | Therma-Tech (A.R. Lintern) | USA | Dahlonega, GA | 4 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.78% |
| 033606 | TUBE, COOLANT | Tube Specialties | USA | Troutdale, OR | 1 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.79% |
| 000321 | VALVE, SINGLE CHECK, SC-3 | Bendix CVS LLC | USA | 0 | 3 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.79% |
| 027475 | BRACKET, BROADWAY COVER, CORNER PASS THRU | Griffiths Coporation | USA | Pineville, NC | 2 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.80% |
| 036317-006 | TRIM , WALL PANEL CAP MOLDING | Seagate Plastics Company | USA | Waterville, OH | 1 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.80% |
| 037959 | BRACKET, BATTERY BOX | GH Metal Solutions, Inc. | USA | Fort Payne, AL | 1 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.81% |



| PAK NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY / VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|------------|--|----------------------------|---|---|---------------|-----------------|--------------|--------------------|-------|---------|------------|
| 001150 | HITTING, PTC, COMPOSITE, UNION Y, 3/8OD TUBE | Hydradyne LLC | USA | Otsego, MI | 2 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.81% |
| 049874 | HARNES-LOW VOLTAGE POWER EXTERNAL (EPWR124) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.82% |
| 048533 | PLATE, HILL HOLD, FRONT | Watson Engineering | USA | Piedmont, SC | 1 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.82% |
| 026383 | PLATE, STUD, M8 | Speclab Services, Inc | USA | Greenville, SC | 1 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.83% |
| 052920 | PLATE, ACCESS | Dellinger Enterprises, LTD | USA | Belmont, NC | 1 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.83% |
| 045279 | BRACKET, HV CABLE SECUREMENT | Ananda Tooling, Inc. | USA | Chino, CA | 1 | 0 | 45% | 0.01% | 0.01% | 0.00% | 76.83% |
| 043969 | TUBE, COOLANT | Tube Specialties | USA | Troutdale, OR | 1 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.84% |
| 044287 | CLOSEOUT, FOOT, LEFT | Speclab Services, Inc | USA | Greenville, SC | 1 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.84% |
| 008083 | PLATE, SPACER, ADA SEAT BELTS | Metal Solutions, Inc. | USA | Vandergrift, PA | 2 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.85% |
| 020939 | SPACER, MODESTY PANEL | Metal Solutions, Inc. | USA | Vandergrift, PA | 2 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.85% |
| 000655 | HITTING, PTC, BRASS 1/2 MPT 1/2" OD TUBE | Hydradyne LLC | USA | Otsego, MI | 6 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.86% |
| 000650 | HITTING, PTC, BRASS 1/4 MPT 3/8" OD TUBE | Hydradyne LLC | USA | Otsego, MI | 6 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.86% |
| 045633 | BRACKET, REAR MOUNT, UPPER, CS | Ananda Tooling, Inc. | USA | Chino, CA | 1 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.87% |
| 014471 | HITTING, 90DEG, 3/8 MNPT X 3/8 HOSE BARB | Hydradyne LLC | USA | Lakeview, MI | 7 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.87% |
| 026176 | PLATE, STUD, EMERGENCY RELEASE | Metal Solutions, Inc. | USA | Vandergrift, PA | 1 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.87% |
| 047574 | TUBE, COOLANT | Tube Specialties | USA | Troutdale, OR | 1 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.88% |
| 046647 | BRACKET, SWITCH | Metal Solutions, Inc. | USA | Grand Rapids, MI | 1 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.88% |
| 045638 | BRACKET, SIDE MOUNT, UPPER, SS | Ananda Tooling, Inc. | USA | Chino, CA | 1 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.89% |
| 045632 | BRACKET, SIDE MOUNT, LOWER, SS | Ananda Tooling, Inc. | USA | Chino, CA | 1 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.89% |
| 038433 | PANEL, LOW VOLTAGE CONTROLLER \ TELEMETRY | Griffiths Coporation | USA | Pineville, NC | 1 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.89% |
| 045635 | BRACKET, REAR MOUNT, LOWER, CS | Ananda Tooling, Inc. | USA | Chino, CA | 1 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.90% |
| 033794 | PLATE, PASSTHRU, REAR DECK | Dellinger Enterprises, LTD | USA | Belmont, NC | 1 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.90% |
| 033493 | ANTENNA, TELEMETRY, WI-FI | Mobile Mark Inc | USA | Itasca, IL | 1 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.91% |
| 045636 | BRACKET, REAR MOUNT, LOWER, SS | Ananda Tooling, Inc. | USA | Chino, CA | 1 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.91% |
| 025068 | VENTILATION, OUTLET, 2.7, THREADED | SPAL USA | USA | Fort Worth, TX | 3 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.91% |
| 045634 | BRACKET, REAR MOUNT, UPPER, SS | Ananda Tooling, Inc. | USA | Chino, CA | 1 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.92% |
| 045631 | BRACKET, SIDE MOUNT, LOWER, CC ASSY | Ananda Tooling, Inc. | USA | Chino, CA | 1 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.92% |
| 049870 | HARNES-LOW VOLTAGE POWER EXTERNAL (EPWR120) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.93% |
| 039878 | PLATE, BLANK, ROOFTOP | Dellinger Enterprises, LTD | USA | Belmont, NC | 1 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.93% |
| 045214 | STANDOFF, SIDE MOUNT, LOWER, CS | Ray Products Company, Inc. | USA | Ontario, California | 2 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.93% |



| PART NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY / VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|-------------|--|----------------------------|---|---|---------------|-----------------|--------------|--------------------|-------|---------|------------|
| 034545 | CABLE ASSEMBLY, TELEMETRY, CELL ANTENNA, 15' | Mobile Mark Inc | USA | Itasca, IL | 1 | | 100% | 0.00% | 0.01% | 0.00% | 76.94% |
| 000686 | BUSHING, AIR SPRING, REAR | Metal Solutions, Inc. | USA | Vandergrift, PA | 4 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.94% |
| 019082 | BRACKET, BALL STUD, MOUNT SHOCK | Dellinger Enterprises, LTD | USA | Belmont, NC | 2 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.95% |
| 048106 | BRACKET, OVERHEAD LIGHTING, FAN | Metal Solutions, Inc. | USA | Grand Rapids, MI | 1 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.95% |
| 034204 | ADJUSTER BRKT, FRONT | Metal Solutions, Inc. | USA | Grand Rapids, MI | 2 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.95% |
| 034721 | ADJUSTER BRKT, REAR | Metal Solutions, Inc. | USA | Grand Rapids, MI | 2 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.96% |
| 046180 | BRACKET, MOUNTING, UPPER FRAME | SpecFab Services, Inc | USA | Greenville, SC | 1 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.96% |
| 046186 | BRACKET, MOUNTING, UPPER FRAME | SpecFab Services, Inc | USA | Greenville, SC | 1 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.97% |
| 049861 | HARNES, LOW VOLTAGE POWER EXTERNAL (EPWR109) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.97% |
| 044795 | BRACKET, ECAB, WW MOUNT | Laserform and Machine Inc | USA | Columbia, SC | 1 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.97% |
| 025977 | BRACKET, WASHER TANK | SpecFab Services, Inc | USA | Greenville, SC | 1 | 0 | 100% | 0.00% | 0.01% | 0.00% | 76.98% |
| 044794 | BRACKET, ECAB, WW MOUNT | Laserform and Machine Inc | USA | Columbia, SC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 76.98% |
| 014999 | BRACKET, CROSSMEMBER SUPPORT, CENTER | SpecFab Services, Inc | USA | Greenville, SC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 76.99% |
| 001134 | COUPLING, MOTOR SHAFT | Cross Company. | USA | Alpena, MI | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 76.99% |
| 009844 | COUPLING, PUMP SHAFT | Cross Company. | USA | Alpena, MI | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 76.99% |
| 027346 | LIGHT, TAIL LAMP, REAR | Dialight Corporation | Mexico | Eresnada, BC | 2 | 0 | 23% | 0.02% | 0.00% | 0.01% | 77.00% |
| 020215 | STUD PLATE, BUMPER | Dellinger Enterprises, LTD | USA | Belmont, NC | 2 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.00% |
| 039885 | DECAL, PROHIBITED ITEMS / ACTIVITIES | M1 Graphics CO, Inc | USA | Fountain Inn, SC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.00% |
| 000662 | HITTING, PTC, COMPOSITE, 45 DEG, SWIVEL, 1/2 OD TUBE, 1/2 MPT" | Hydradyne LLC | USA | Otsego, MI | 2 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.01% |
| 045257 | HITTING, PTC, COMPOSITE, 90 DEG, SWIVEL, 1/8 MPT X 3/8 PTC | Hydradyne LLC | USA | Otsego, MI | 4 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.01% |
| 000661 | HITTING, PTC, COMPOSITE, 45 DEG, SWIVEL, 1/2 OD TUBE, 3/8 MPT" | Hydradyne LLC | USA | Otsego, MI | 2 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.01% |
| 016509 | GRILL, VENT | Coyote International L.L.C | USA | Fort Worth, TX | 8 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.02% |
| 016641 | BRACKET, END, DRIVE SHAFT LOOP | Dellinger Enterprises, LTD | USA | Belmont, NC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.02% |
| 016642 | BRACKET, END, DRIVE SHAFT LOOP | Dellinger Enterprises, LTD | USA | Belmont, NC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.03% |
| 043200 | HARNES,CHARGE PORT HVIL (CPHL) | Precisionworks MFG LLC | USA | Loveland, PA | 2 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.03% |
| 037169 | MOUNT,NUT PLATE,MIRROR | Axanda Tooling, Inc. | USA | Chino, CA | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.03% |



PROTERRA

| PART NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY / VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|-------------|--|-------------------------------|---|---|---------------|-----------------|--------------|--------------------|-------|---------|------------|
| 016508 | DEFROSTER, DEFUSER | Coyote International L.L.C | USA | Fort Worth, TX | 8 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.04% |
| 043199 | HARNESS,BATTERY STRING HWIL (BSHL) | Precisionworks MFG LLC | USA | Loveland, PA | 3 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.04% |
| 019110 | SPACER | Metal Solutions, Inc. | USA | Vandergrift, PA | 4 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.04% |
| 043460 | BRACKET, BROADWAY COVER, CORNER | Metal Solutions, Inc. | USA | Grand Rapids, MI | 2 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.05% |
| 049869 | HARNESS,LOW VOLTAGE POWER EXTERNAL (EPWR119) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.05% |
| 000653 | HITTING, PTC, BRASS 1/4MPT, 1/2OD TUBE | Hydradyne LLC | USA | Otsego, MI | 3 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.05% |
| 023061 | BRACKET, BEVEL BOX, STEERING | GH Metal Solutions, Inc. | USA | Fort Payne, AL | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.06% |
| 049855 | HARNESS,LOW VOLTAGE POWER EXTERNAL (EPWR103) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.06% |
| 001172 | HITTING, PTC, COMPOSITE, 90DEG, SWIVEL, 1/4 M PT3/8 OD TUBE" | Hydradyne LLC | USA | Otsego, MI | 3 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.06% |
| 045178 | HITTING, PTC, COMPOSITE, 90 DEG, SWIVEL, 1/2 MPT X 1/2 PTC | Hydradyne LLC | USA | Otsego, MI | 2 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.07% |
| 046885 | KICKPLATE, WW BOX, CS, REAR | Griffiths Coporation | USA | Pineville, NC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.07% |
| 046887 | KICKPLATE, WW BOX, SS, REAR | Griffiths Coporation | USA | Pineville, NC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.07% |
| 023793 | PLATE, HV CABLE RESTRAINT | Dellinger Enterprises, LTD | USA | Belmont, NC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.08% |
| 047573 | TUBE, COOLANT | Tube Specialties | USA | Troutdale, OR | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.08% |
| 038008 | TUBE, COOLANT | Tube Specialties | USA | Troutdale, OR | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.08% |
| 017404 | DECAL, WATCH YOUR STEP, ENG/SP | MI Graphics CO, Inc | USA | Mountain Invt, SC | 3 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.09% |
| 025371 | BRACKET, ESM | Dellinger Enterprises, LTD | USA | Belmont, NC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.09% |
| 044896 | GASKET, PANEL, FLUID HLL | Dixie Rubber & Plastics, Inc. | USA | Greenville, SC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.09% |
| 002270 | HITTING, ELBOW, MALE 3/4-16 X 1/2 IPT | Hydradyne LLC | USA | USA | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.10% |
| 018593 | MOUNT, KNEELING LIGHT | Dellinger Enterprises, LTD | USA | Belmont, NC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.10% |
| 046883 | KICKPLATE, WW BOX, CS, FRONT | Griffiths Coporation | USA | Pineville, NC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.10% |
| 024965 | PASS-THROUGH, CONDENSATION DRAIN LINE, HVAC | Dixie Rubber & Plastics, Inc. | USA | Greenville, SC | 2 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.11% |
| 053124 | BRACKET, FIRST AID KIT | Laserform and Machine Inc | USA | Columbia, SC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.11% |
| 041996 | HITTING, PTC, 45° ELBOW, 1/2 MPT X 3/8 PTC | Hydradyne LLC | USA | Otsego, MI | 2 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.11% |
| 037238 | BRACKET, STRIKER LH | Metal Solutions, Inc. | USA | Grand Rapids, MI | 2 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.12% |
| 012115 | BRACKET, ADA, SHOULDER BELT | American Seating Company | USA | Grand Rapids, MI | 2 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.12% |
| 048092 | BRACKET, OVERHEAD LIGHTING, FAN | Metal Solutions, Inc. | USA | Grand Rapids, MI | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.12% |



| PART NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY / VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|-------------|--|-----------------------------|---|---|---------------|-----------------|--------------|--------------------|-------|---------|------------|
| 024884 | BRACKET, MOUNTING, FRAME | Laserform and Machine Inc | USA | Columbia, SC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.12% |
| 018904 | DECAL, EMERGENCY EXIT | M1 Graphics CO, Inc | USA | Fountain Inn, SC | 5 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.13% |
| 016503 | TUBE, COOLANT, BATTERY | Tube Specialties | USA | Troutdale, OR | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.13% |
| 054403 | COVER, CCS CHARGER INLET | REMA USA LLC | USA | Fountain Inn, SC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.13% |
| 002107 | HIGHWAY WARNING TRIANGLES | Eagle Plastics & Rubber Co. | USA | Dover, OH | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.14% |
| 008324 | DECAL, SECUREMENT, WHEELCHAIR | M1 Graphics CO, Inc | USA | Fountain Inn, SC | 2 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.14% |
| 008698-001 | DECAL, WATCH YOUR STEP, VERTICAL (BLACK ON CLEAR) | M1 Graphics CO, Inc | USA | Fountain Inn, SC | 2 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.14% |
| 008699-001 | DECAL, PISE CON CUIDADO, VERTICAL (BLACK ON CLEAR) | M1 Graphics CO, Inc | USA | Fountain Inn, SC | 2 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.15% |
| 008700 | DECAL, PRIORITY SEATING, ENG/SP | M1 Graphics CO, Inc | USA | Fountain Inn, SC | 2 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.15% |
| 017696 | DECAL, NO JACKING POINT | M1 Graphics CO, Inc | USA | Fountain Inn, SC | 6 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.15% |
| 000625 | TUBE, AIRBREAK, NYLON, Ø.38 OD, .06 WALL, BLK | Hydradyne LLC | USA | Ravenna, OH | 240 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.15% |
| 000656 | FITTING, PTC, BRASS 3/8 MPT 5/8" OD TUBE | Hydradyne LLC | USA | Otsego, MI | 2 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.16% |
| 050633 | HARNES, LOW VOLTAGE POWER EXTERNAL (EPWR118) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.16% |
| 017128 | BRACKET, FULL CLOSEOUT ADA RAMP | Specfab Services, Inc | USA | Greenville, SC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.16% |
| 025006 | PLATE, MOUNTING, DOORWAY LIGHT | Metal Solutions, Inc. | USA | Vandegrift, PA | 2 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.17% |
| 044575 | HARNES, ADA JUMPER, RICON 4_1 (ADA4_1) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.17% |
| 046855 | PLATE, BACKING, E-RELEASE | Aranda Tooling, Inc. | USA | Chino, CA | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.17% |
| 044870 | FITTING, MALE, 90°, 1/2 JIC, SAE #8, LONG | Hydradyne LLC | USA | USA | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.18% |
| 049863 | HARNES, LOW VOLTAGE POWER EXTERNAL (EPWR111) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.18% |
| 039185 | FITTING, PTC, COMP, TEE, BRANCH, 5/8 PTC X 1/2 MPT X 5/8 PTC | Hydradyne LLC | USA | Otsego, MI | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.18% |
| 007271 | DECAL, WATCH YOUR HEAD, WHITE TEXT ON RED | M1 Graphics CO, Inc | USA | Fountain Inn, SC | 2 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.18% |
| 017408 | PLACARD, UNNECESSARY CONVERSATIONS | M1 Graphics CO, Inc | USA | Fountain Inn, SC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.19% |
| 047572 | TUBE, COOLANT | Tube Specialties | USA | Troutdale, OR | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.19% |
| 025172 | PLATE, GROMMET, RESERVOIR | Dellinger Enterprises, LTD | USA | Belmont, NC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.19% |
| 050632 | HARNES, LOW VOLTAGE POWER EXTERNAL (EPWR117) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.19% |
| 000651 | FITTING, PTC, BRASS 3/8MPT, 3/8OD TUBE | Hydradyne LLC | USA | Otsego, MI | 4 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.20% |



| PAK NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY/VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|------------|---|-------------------------------|---|---|-------------|-----------------|--------------|--------------------|-------|---------|------------|
| 000660 | FITTING, PTC COMPOSITE, 45 DEG, SWIVEL, 3/8 OD TUBE, 3/8 MPT" | Hydradyne LLC | USA | Otsego, MI | 2 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.20% |
| 039720 | PLATE, STUD | Laserform and Machine Inc | USA | Columbia, SC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.20% |
| 000659 | FITTING, PTC COMPOSITE, 45 DEG, SWIVEL, 3/8 ODTUBE, 1/4 MPT" | Hydradyne LLC | USA | Otsego, MI | 2 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.21% |
| 041912 | HARNESS, FOOT SWITCH (FTSW) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.21% |
| 050286 | PLATE, ITS, CONNECTOR BRACKET | Dellinger Enterprises, LTD | USA | Belmont, NC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.21% |
| 034484 | TUBE, COOLANT | Tube Specialties | USA | Troutdale, OR | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.21% |
| 017856 | DECAL, EMERGENCY EXIT, REAR DOOR | M1 Graphics CO, Inc | USA | Fountain Inn, SC | 5 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.22% |
| 052582 | PLATE, BACKING, WWB STRUT MOUNT | 0 | USA | Belmont, NC | 4 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.22% |
| 014946 | BRACKET, CROSSMEMBER SUPPORT, FRONT | SpecFab Services, Inc | USA | Greenville, SC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.22% |
| 049859 | HARNESS, LOW VOLTAGE POWER EXTERNAL (EPWR107) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.22% |
| 004768 | MOUNT, LINKAGE, HEIGHT SENSOR, FRONT, STREET SIDE | Dellinger Enterprises, LTD | USA | Belmont, NC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.23% |
| 039225 | FITTING, PLUG-IN RUN TEE, 3/8 PTC | Hydradyne LLC | USA | Otsego, MI | 2 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.23% |
| 018087 | GASKET, LIGHT, AMBER, WW | Dixie Rubber & Plastics, Inc. | USA | Greenville, SC | 4 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.23% |
| 017129 | BRACKET, FRONT FULL CLOSEOUT ADA RAMP | SpecFab Services, Inc | USA | Greenville, SC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.23% |
| 004828 | BRACKET, HORN MOUNT, DUAL TUNE | Dellinger Enterprises, LTD | USA | Belmont, NC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.23% |
| 036425 | HARNESS, FRONT CHARGE PORT JUNCTION BOX -2 (FCPT2) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.24% |
| 048833 | FITTING, PTC, BRASS, STRAIGHT, 1/2 FPT X 1/2 PTC | Hydradyne LLC | USA | Otsego, MI | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.24% |
| 020764 | GASKET, SPEAKER, OUTSIDE | Dixie Rubber & Plastics, Inc. | USA | Greenville, SC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.24% |
| 049857 | HARNESS, LOW VOLTAGE POWER EXTERNAL (EPWR105) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.24% |
| 014945 | BRACKET, CROSSMEMBER SUPPORT, FRONT | SpecFab Services, Inc | USA | Greenville, SC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.25% |
| 047463-001 | TRIM, PANEL CAP | Seagate Plastics Company | USA | Waterville, OH | 2 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.25% |
| 018013 | MUDEFLAP, REAR, LEFT | Eagle Plastics & Rubber Co. | USA | Dover, OH | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.25% |
| 018306 | MUD FLAP, REAR, RIGHT | Eagle Plastics & Rubber Co. | USA | Dover, OH | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.25% |
| 042557 | DECAL, WORKLIGHT | M1 Graphics CO, Inc | USA | Fountain Inn, SC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.25% |



| PART NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY / VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|-------------|---|-------------------------------|---|---|---------------|-----------------|--------------|--------------------|-------|---------|------------|
| 000663 | HITTING, PTC, COMPOSITE, 45 DEG, SWIVEL, 5/8 OD TUBE, 1/2 MPT | Hydradyne LLC | USA | Otsego, MI | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.26% |
| 018776 | WASHER, PLAIN, .81x1.47x.13 | Bossard North America Inc | USA | Mundelein, IL | 4 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.26% |
| 020747 | FOAM BACKING, WALL 1",FOAM BACKING | Dixie Rubber & Plastics, Inc. | USA | Greenville, SC | 6 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.26% |
| 042884 | WASHER, SEAT | Watson Engineering | USA | Piedmont, SC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.26% |
| 025064 | HOSE, ADAPTER, Y, 2.5 INCH W/BABBLE | Coyote International L.L.C | USA | Fort Worth, TX | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.27% |
| 004773 | BUSHING, LINKAGE, HEIGHT SENSOR | Dixie Rubber & Plastics, Inc. | USA | Greenville, SC | 2 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.27% |
| 021517 | PLATE, MOUNTING | Dellinger Enterprises, LTD | USA | Belmont, NC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.27% |
| 049860 | HARNES, LOW VOLTAGE POWER EXTERNAL (EPWR108) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.27% |
| 022336 | SCR,M5x8,BTN,STL,ZnNi,P-5T3 | Bossard North America Inc | USA | Elk Grove, IL | 36 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.27% |
| 039770 | HARNES,GRAHAM-WHITE AIR DRYER JUMPER | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.28% |
| 045215 | STANDOFF, SIDE MOUNT, UPPER, CS | Ray Products Company, Inc. | USA | Ontario, California | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.28% |
| 045217 | STANDOFF, SIDE MOUNT, UPPER, SS | Ray Products Company, Inc. | USA | Ontario, California | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.28% |
| 046709 | STANDOFF, REAR MOUNT, LOWER, CS | Ray Products Company, Inc. | USA | Ontario, California | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.28% |
| 046710 | STANDOFF, REAR MOUNT, UPPER, CS | Ray Products Company, Inc. | USA | Ontario, California | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.28% |
| 046711 | STANDOFF, REAR MOUNT, LOWER, SS | Ray Products Company, Inc. | USA | Ontario, California | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.29% |
| 046712 | STANDOFF, REAR MOUNT, UPPER, SS | Ray Products Company, Inc. | USA | Ontario, California | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.29% |
| 027041 | VENTILATION OUTLET, 3.0 | Coyote International L.L.C | USA | Fort Worth, TX | 2 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.29% |
| 004767 | MOUNT, LINKAGE, HEIGHT SENSOR, FRONT, CURB SIDE | Watson Engineering | USA | Piedmont, SC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.29% |
| 044254 | HITTING, PTC, COMPOSITE, 90 DEG, SWIVEL, 1/2 MPT X 5/8 PTC | Hydradyne LLC | USA | Otsego, MI | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.29% |
| 024600 | LKNT, DIN 980, STL, CL10, 1000HSS-SILVER M12-1.75 | NSK Industries Inc | USA | Flint, MI | 8 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.30% |
| 036317-008 | TRIM , WALL PANEL CAP MOLDING | Seagate Plastics Company | USA | Waterville, OH | 2 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.30% |
| 026207 | BRACKET, E-CAB MTG | Laserform and Machine Inc | USA | Columbia, SC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.30% |
| 037373 | GASKET, CLEARANCE LIGHT | Dixie Rubber & Plastics, Inc. | USA | Greenville, SC | 5 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.30% |



| PART NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY / VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|-------------|---|-------------------------------|---|---|---------------|-----------------|--------------|--------------------|-------|---------|------------|
| 018086 | GASKET, LIGHT, AMBER, WW, INTERNAL | Dixie Rubber & Plastics, Inc. | USA | Greenville, SC | 4 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.30% |
| 036228 | AIRLINE, FORMED, 3/8 OD .06 WALL YELLOW | Hydradyne LLC | USA | Ravenna, OH | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.30% |
| 046058 | FITTING, PTC, BRASS, 90 DEG, RIGID, 3/8 MPT X 3/8 PTC | Hydradyne LLC | USA | Otsego, MI | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.31% |
| 014031 | LIGHT, YELLOW LED FLAT LENS 24V | Dialight Corporation | Mexico | Ersenada, BC | 2 | 0 | 55% | 0.00% | 0.00% | 0.00% | 77.31% |
| 017472 | PLACARD, EMERGENCY DOOR RELEASE | M1 Graphics CO, Inc | USA | Fountain Inn, SC | 2 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.31% |
| 051913 | HARNESS, LOW VOLTAGE POWER INTERNAL (IPWR116) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.31% |
| 043201 | HARNESS, HVJB_HVIL JUMPER (HVIL) | Precisionworks MFG LLC | USA | Loveland, PA | 5 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.31% |
| 037162 | PLATE, NUT, MIRROR | Amanda Tooling, Inc. | USA | Chino, CA | 1 | 0 | 67% | 0.00% | 0.00% | 0.00% | 77.31% |
| 036227 | AIRLINE, FORMED, 3/8 OD .06 WALL YELLOW | Hydradyne LLC | USA | Ravenna, OH | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.32% |
| 044891 | BRACKET, DRIVERS PANEL MOUNTING | Amanda Tooling, Inc. | USA | Chino, CA | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.32% |
| 039771 | HARNESS, BENDIX AIR DRYER JUMPER | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.32% |
| 006946 | DECAL, EMERGENCY EXIT, EGRESS WINDOW, BILINGUAL | Seifert Graphics, Inc. | USA | Oriskany, NY | 4 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.32% |
| 023849 | BRACKET, DRAIN LINE, AIR TANK | Lock-Ridge Tool Co., Inc. | USA | Pomona, CA | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.32% |
| 024947 | BRACKET, E-CAB MTG | Laserform and Machine Inc | USA | Columbia, SC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.32% |
| 048834 | FITTING, PTC, COMPOSITE, PLUG-IN 90° ELBOW, 1/2 MALE PTC X 1/2 FEMALE PTC | Hydradyne LLC | USA | Otsego, MI | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.33% |
| 019920 | PLATE, NUT, POWER STEERING TANK | Lock-Ridge Tool Co., Inc. | USA | Fort Payne, AL | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.33% |
| 001164 | FITTING, PTC, CMPST, 90, SWIVEL, 3/8MPT, 1/2OD | Hydradyne LLC | USA | Otsego, MI | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.33% |
| 016974 | BRACKET ASSY, LOWER, E RELEASE BOX | Dellinger Enterprises, LTD | USA | Belmont, NC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.33% |
| 035374 | BRACKET, COVER RH | Laserform and Machine Inc | USA | Columbia, SC | 2 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.33% |
| 045338 | PLATE, LV TRAY | Laserform and Machine Inc | USA | Columbia, SC | 2 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.33% |
| 028635 | LIGHT: OVERHEAD: DIMMING | Dialight Corporation | Mexico | Ersenada, BC | 1 | 0 | 10% | 0.02% | 0.00% | 0.01% | 77.34% |
| 001136 | INSERT, SPIDER | Cross Company. | USA | Alpers, MI | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.34% |
| 000654 | FITTING, PTC, BRASS, 3/8 MPT 1/2" OD TUBE | Hydradyne LLC | USA | Otsego, MI | 2 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.34% |
| 014523 | PLATE, GROMMET, WASHER LINES | Lock-Ridge Tool Co., Inc. | USA | Pomona, CA | 2 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.34% |
| 015733 | MOUNTING BRACKET, DUMP VALVE | Laserform and Machine Inc | USA | Columbia, SC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.34% |



| PART NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY / VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|-------------|--|-----------------------------------|---|---|---------------|-----------------|--------------|--------------------|-------|---------|------------|
| 014472 | HITTING, 45° ELBOW, 3/8 MNPT, 3/8 HOSE BARB | Hydadyne LLC | USA | Albion, IN | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.34% |
| 020954 | BRACKET, RIGHT | LockRidge Tool Co., Inc. | USA | Pomona, CA | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.35% |
| 028577 | PCB, RESISTOR & 5V SUPPLY | Silicon Forest Electronics | USA | Vancouver, WA | 1 | 0 | 5% | 0.03% | 0.00% | 0.03% | 77.35% |
| 051970 | FOAM, BACKING, WALL, 1.5" | Munaco Sealing Solutions, Inc. | USA | Greenville, SC | 2 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.35% |
| 034211 | BRACKET, COVER LH | Laserform and Machine Inc | USA | Columbia, SC | 2 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.35% |
| 019656 | DECAL, SYMBOL, HIGH VOLTAGE | M1 Graphics CO, Inc | USA | Fountain Im, SC | 2 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.35% |
| 017406 | DECAL, POWER STEERING FLUID | M1 Graphics CO, Inc | USA | Fountain Im, SC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.35% |
| 017436 | LABEL, WASHER FLUID | M1 Graphics CO, Inc | USA | Fountain Im, SC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.35% |
| 046817 | Gasket, Head Light, SS | Dixie Rubber & Plastics, Inc. | USA | Greenville, SC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.36% |
| 046818 | Gasket, Head Light, CS | Dixie Rubber & Plastics, Inc. | USA | Greenville, SC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.36% |
| 006857 | HITTING, HOSE, BARBED, 3/8 X 1/4 NPT | Hydadyne LLC | USA | Lakeview, MI | 3 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.36% |
| 020834 | BRACKET, LEFT | LockRidge Tool Co., Inc. | USA | Pomona, CA | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.36% |
| 006722 | HITTING, PTC, COMPOSITE, 90 DEG, SWIVEL, 1/2 MPT X 3/8 TUBE | Hydadyne LLC | USA | Otsego, MI | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.36% |
| 026047 | SEAL, TURN SIGNAL | Dixie Rubber & Plastics, Inc. | USA | Greenville, SC | 2 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.36% |
| 039628 | SPACER, CONTACTOR | Griffiths Corporation | USA | Pineville, NC | 2 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.36% |
| 049844 | HARNES, LOW VOLTAGE POWER INTERNAL (IPWR107) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.37% |
| 006951 | DECAL, WHEELCHAIR ICON | M1 Graphics CO, Inc | USA | Fountain Im, SC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.37% |
| 049843 | HARNES, LOW VOLTAGE POWER INTERNAL (IPWR105) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.37% |
| 009539 | DECAL, HAZARDOUS VOLTAGE | M1 Graphics CO, Inc | USA | Fountain Im, SC | 2 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.37% |
| 039773 | HARNES-STANCHION STOP REQUEST (SSRQ) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.37% |
| 016468 | PLATE, PASS THRU, POWER STEERING | Laserform and Machine Inc | USA | Columbia, SC | 2 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.37% |
| 044248 | HITTING, COMPOSITE, PLUG-IN 90° ELBOW, 1/2 MALE PTC X 3/8 FEMALE PTC | Hydadyne LLC | USA | Otsego, MI | 2 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.37% |
| 016525 | BRACKET, MOUNTING, DUMP VALVE, EXIT DOOR | Dellinger Enterprises, LTD | USA | Belmont, NC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.37% |
| 018364 | BRACKET, R14 VALVE, FRONT | Dellinger Enterprises, LTD | USA | Belmont, NC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.38% |
| 047927 | CABLE, XLR M TO F, 10' | Radio Engineering Industries, Inc | USA | Grand Rapids, MI | 1 | 0 | 15% | 0.01% | 0.00% | 0.01% | 77.38% |
| 017405 | DECAL, JACKING POINT | Seifert Graphics, Inc. | USA | Oriskany, NY | 4 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.38% |
| 052411 | SPACER, ECAB, SS WHEEL WELL BOX | Laserform and Machine Inc | USA | Columbia, SC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.38% |



| PAK NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY / VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|------------|--|--------------------------------|---|---|---------------|-----------------|--------------|--------------------|-------|---------|------------|
| 051966 | FOAM, BACKING, WALL, 1.5" | Munaco Sealing Solutions, Inc. | USA | Greenville, SC | 2 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.38% |
| 051967 | FOAM, BACKING, WALL, 0.75" | Munaco Sealing Solutions, Inc. | USA | Greenville, SC | 2 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.38% |
| 043243 | HARNESS,PULL CORD (PCRD) | Precisionworks MFG LLC | USA | Loveland, PA | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.38% |
| 017427 | PLACARD, EMERGENCY EQUIPMENT | M1 Graphics CO, Inc | USA | Fountain Inv, SC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.38% |
| 042206 | LABEL, START | M1 Graphics CO, Inc | USA | Fountain Inv, SC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.38% |
| 042556 | DECAL, 12V 240W MAX | M1 Graphics CO, Inc | USA | Fountain Inv, SC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.39% |
| 013577 | LKNT, HEX, M12-1.75 | Bossard North America Inc | USA | Addison, IL | 10 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.39% |
| 052412 | SPACER, ECAB, SS WHEEL WELL BOX, SLOTTED | Laserform and Machine Inc | USA | Columbia, SC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.39% |
| 017136 | BRACE, BRACKET | Dellinger Enterprises, LTD | USA | Belmont, NC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.39% |
| 017218-003 | PLATE, STUD, M6 X 16MM ROTALOC | Retaloc Intl, LLC | Taiwan | Taiwan | 7 | 0 | 50% | 0.00% | 0.00% | 0.00% | 77.39% |
| 024976-004 | SCREW, DRILLING, MODIFIED TRUSS, #8-18x1.25 | NSK Industries Inc | USA | Bristol, IN | 44 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.39% |
| 056317-004 | TRIM , WALL PANEL CAP MOLDING | Seagate Plastics Company | USA | Waterville, OH | 2 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.39% |
| 056236 | FITTING, 90° ELBOW, 3/8 MNPT, 1/4 MNPT | HydraDyne LLC | Mexico | Mexico | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.39% |
| 018173 | GASKET, MIRROR, EXTERIOR | Dixie Rubber & Plastics, Inc. | USA | Greenville, SC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.39% |
| 019534 | NUT, RIVET, M6-1.0 | Bossard North America Inc | USA | Akron, OH | 2 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.39% |
| 023169 | LIGHT, GREEN, LED, 5V | Dialight Corporation | Mexico | Ensenada, BC | 1 | 0 | 52% | 0.00% | 0.00% | 0.00% | 77.39% |
| 016973 | BRACKET ASSY, UPPER, E RELEASE BOX | Griffiths Corporation | USA | Pineville, NC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.40% |
| 000647 | FITTING, PTC, BRASS 1/4 FPT 3/8" OD TUBE | HydraDyne LLC | USA | Olsego, MI | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.40% |
| 017409 | PLACARD, BUS DRIVERS CARRY NO CASH OR TOKENS, ENG/SP | M1 Graphics CO, Inc | USA | Fountain Inv, SC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.40% |
| 033155 | DECAL, EMERGENCY BATTERY DISCONNECT SWITCHES | M1 Graphics CO, Inc | USA | Fountain Inv, SC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.40% |
| 039715 | GASKET, EXT. SPEAKER 35' | Dixie Rubber & Plastics, Inc. | USA | Greenville, SC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.40% |
| 024888 | VENT, 2.5 | Coyote International L.L.C | USA | Fort Worth, TX | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.40% |
| 052205 | GASKET, GRILLE, REAR | Dixie Rubber & Plastics, Inc. | USA | Greenville, SC | 8 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.40% |
| 014525 | GASKET, GROMMET PLATE, WASHER LINES | Dixie Rubber & Plastics, Inc. | USA | Greenville, SC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.40% |
| 039737 | PLATE, COVER, SPLIT BLOCK | Laserform and Machine Inc | USA | Columbia, SC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.40% |



| PART NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY / VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|-------------|---|---|---|---|---------------|-----------------|--------------|--------------------|-------|---------|------------|
| 036317-003 | TRIM , WALL PANEL CAP MOLDING | Seagate Plastics Company | USA | Waterville, OH | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.40% |
| 016527 | PLATE, BACKING, E-RELEASE, EXIT DOOR | Dellinger Enterprises, LTD | USA | Belmont, NC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.40% |
| 027352 | GASKET, LIGHT, TAIL LAMP, REAR | Dialight Corporation | USA | Hazlet, NJ | 6 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.40% |
| 003777 | PIPE PLUG, BRASS, 1/4 | Hydradyne LLC | USA | Lakeview, MI | 8 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.41% |
| 045015 | HITTING, BRASS, ELBOW, 90 DEG, 1/4 FPT X 1/4 FPT | Hydradyne LLC | USA | Albion, IN | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.41% |
| 031389 | HITTING, BRASS, REDUCER, BRASS, 1/2" MNPT, 3/8" MNPT | Hydradyne LLC | USA | Lakeview, MI | 2 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.41% |
| 004902 | HITTING, PTC, BRASS, 3/8 MPT/HITTING, PTC, BRASS, 3/8 MPT | Hydradyne LLC | USA | Otsego, MI | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.41% |
| 017218-005 | PLATE, STUD, M6 X 25MM ROTALOC | Rotaloc Intl, LLC | Taiwan | Taiwan | 5 | 0 | 50% | 0.00% | 0.00% | 0.00% | 77.41% |
| 000649 | HITTING, PTC, BRASS 1/8 MPT 3/8" OD TUBE | Hydradyne LLC | USA | Otsego, MI | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.41% |
| 004903 | HITTING, BRASS, TEE, 3/8FPT | Hydradyne LLC | USA | Otsego, MI | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.41% |
| 017410 | PLACARDS, FIRE EXTINGUISHER | M1 Graphics CO, Inc | USA | Fountain Im, SC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.41% |
| 020897 | M17500, 45 DEG, ST, RD, O | Kongsberg Power Products Systems I, LLC | USA | Novi, MI | 1 | 0 | 2% | 0.03% | 0.00% | 0.03% | 77.41% |
| 025069 | ADAPTER, THREADED, 2.5 | Coyote International L.L.C | USA | Fort Worth, TX | 3 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.41% |
| 009066 | HT, BRASS, TEE, 1/4 FNPT" | Hydradyne LLC | USA | Otsego, MI | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.41% |
| 000643 | HITTING, BRASS, PLUG, SKT HEAD, 3/8 NPT | Hydradyne LLC | USA | Otsego, MI | 3 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.41% |
| 013375-021 | BOLT, HEX, FLG, .44x1.42.00x1.13 | NSK Industries Inc | USA | Flint, MI | 2 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.41% |
| 019767 | NUT, SWITCH MOUNTING | Therma-Tech (A.R. Lintern) | USA | Dahlona, GA | 8 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.41% |
| 042209 | LABEL, DRIVE DISABLE | M1 Graphics CO, Inc | USA | Fountain Im, SC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.41% |
| 039186 | HITTING, COUPLING, BRASS, 1/2 FNPT X 1/2 FNPT | Hydradyne LLC | USA | Otsego, MI | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.41% |
| 036317-007 | TRIM , WALL PANEL CAP MOLDING | Seagate Plastics Company | USA | Waterville, OH | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.41% |
| 000641 | HITTING, BRASS, NIPTLE, HEX, 1/4 MPT 3/8" MPT | Hydradyne LLC | USA | Lakeview, MI | 2 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.41% |
| 018777 | WASHER, PLAIN, .94x1.75x.13 | Bossard North America Inc | USA | Mundelein, IL | 4 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.41% |
| 024780 | CAP, FRONT BUMPER | Caplugs | USA | Buffalo, NY | 2 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.41% |
| 039111 | BRACKET, AMBIENT TEMPERATURE SENSOR MOUNTING | Griffiths Coporation | USA | Columbia, SC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.41% |
| 019241 | BOLT, HEX HEAD, ~20, HADLEY | Superior Interior Systems | USA | Grand Rapids, MI | 32 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.41% |
| 017437 | LABEL, MAINTENANCE LIGHT | M1 Graphics CO, Inc | USA | Fountain Im, SC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.42% |
| 025065 | VENTILATION OUTLET, RETAINER, 2.7 | Coyote International L.L.C | USA | Fort Worth, TX | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.42% |
| 039738 | PLATE, COVER, SPLIT BLOCK | Griffiths Coporation | USA | Pineville, NC | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.42% |



| PART NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY / VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|-------------|---|---------------------------------------|---|---|---------------|-----------------|--------------|--------------------|-------|---------|------------|
| 045016 | HITTING, BRASS, HEX NIPPLE, 1/4 MPT X 1/4 MPT | Hydadyne LLC | USA | Lakeview, MI | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.42% |
| 001161 | HITTING, BRASS, PLUG, SOCKET HEAD, 1/2 PT" | Hydadyne LLC | USA | Otsego, MI | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.42% |
| 027318 | NUT, RIVET, M3-0.5, LOW-PROFILE | Bossard North America Inc | USA | Danboro, PA | 4 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018241 | NUT, INSERT, M6-1.0 | Bossard North America Inc | USA | Akron, OH | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.42% |
| 022350 | SCR,M8X20,BTN,STL,ZnNi,P-593S | Bossard Inc. | USA | Carol Stream, IL | 4 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.42% |
| 027042 | CLIP, HOSE | Coyote International L.L.C | USA | Fort Worth, TX | 4 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.42% |
| 016522 | THREAD-FORMING TORX SCREW FOR PLASTICS, FLAT HEAD | Bossard Inc. | USA | Deconah, IA | 20 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.42% |
| 010194 | SNAP RING, TRANSMISSION SIDE | Bossard Inc. | USA | Tustin, CA | 1 | 0 | 100% | 0.00% | 0.00% | 0.00% | 77.42% |
| 000002 | BEVEL BOX, TRW | TRW Automotive U.S. LLC | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.05% | 0.00% | 0.05% | 77.42% |
| 000003 | GEAR BOX, TRW | TRW Automotive U.S. LLC | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.26% | 0.00% | 0.26% | 77.42% |
| 000259 | CONTACT, PIN, #18-20 AWC, WPM-19 (12089040)089040 | Mouser Electronics | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 000297 | SPRING, AIR, REAR 1T15L-4 | Firestone Industrial Products Company | Certificate not available | Certificate not available | 4 | 0 | 0% | 0.06% | 0.00% | 0.06% | 77.42% |
| 000306 | VALVE, PUSH-PULL, PP-1 | Bendix CVS LLC | Mexico | 0 | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 000309 | VALVE, PRESSURE REDUCING, RV-3 | Bendix CVS LLC | Mexico | 0 | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 000315 | SENSOR, INDUCTION, SPEED, WS-24, STRAIGHT | Bendix CVS LLC | Mexico | 0 | 2 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 000320 | VALVE, DOUBLE CHECK, DC-4 | Bendix CVS LLC | Mexico | 0 | 4 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 000323 | TRANSDUCER, PRESSURE | Bendix CVS LLC | Mexico | 0 | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 000393-004 | P-CLAMP, 1",P-CLAMP | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 16 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 000460 | HOUSING, STANCHION MOUNT, 35MM YELLOW, EAO 84-95000.4 | EAO Switch Corporation | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 000637 | HITTING, STEEL, ADAPTER, 1/2 M 37 DEG FLARE M ME | Hydadyne LLC | Poland | Poland | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 000696 | NUT, LUG, REAR, ALUMINUM WHEEL, GEOMET | Haltec Corporation | Certificate not available | Certificate not available | 20 | 0 | 0% | 0.06% | 0.00% | 0.06% | 77.42% |
| 000725 | NUT, LUG, FRONT, ALUMINUM WHEEL, GEOMET | Haltec Corporation | Certificate not available | Certificate not available | 20 | 0 | 0% | 0.05% | 0.00% | 0.05% | 77.42% |
| 000739 | DRYER, AIR, EP, BENDIX | Bendix CVS LLC | Mexico | 0 | 1 | 0 | 0% | 0.06% | 0.00% | 0.06% | 77.42% |
| 000880-AA | BATTERY, 12V, 100AH, GROUP 31 | Batteries Plus | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.13% | 0.00% | 0.13% | 77.42% |
| 001137 | SWITCH, FLOOR, DIMMER, HEADLAMP | Wes-Garde Components Group, Inc. | Mexico | Mexico | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 001139 | SWITCH, FLOOR, TURN SIGNAL | Wes-Garde Components Group, Inc. | Mexico | Mexico | 2 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |



| PAK NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY/VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|------------|--|---------------------------|---|---|-------------|-----------------|--------------|--------------------|-------|---------|------------|
| 001153 | HITTING, BRASS, ADAPTER, 1/8M PT, 1/4F PT | Hydraayne LLC | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 001165 | HITTING, PIC, UNION TEE, 5/8 OD TUBE" | Hydraayne LLC | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 001167 | HITTING, ADAPTER, 1/2M PT, 3/4M 37DEG FLARE | Hydraayne LLC | Taiwan | Taiwan | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 001259 | CONNECTOR, PLUG, 2 POSITION, DEUTSCH #DT06-25 | LADD Distribution | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 001260 | WEDGELOCK, 2 POSITION, FOR DT06-25, DEUTSCH | LADD Distribution | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 001262 | SEALING PLUG, SIZE 12-16G) DEUTSCH #114017 | LADD Distribution | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 001269 | CONNECTOR, RECEPTACLE, 2 POSITION, DEUTSCH #DT04-2P | LADD Distribution | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 001270 | WEDGE LOCK, 2 PIN RECEPT. DT SERIES | LADD Distribution | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 001295 | CONNECTOR, RECEPTACLE, 6 POSITION, DEUTSCH # | LADD Distribution | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 001298 | CONTACT, PIN, SOLID, SIZE 16, 16-20 AWG | Mouser Electronics | Certificate not available | Certificate not available | 26 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 001300 | TERMINAL, SIZE 16, PIN, 14 AWG | LADD Distribution | Certificate not available | Certificate not available | 6 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 001301 | TERMINAL, SIZE 16, SOCKET, 16-20 AWGH | LADD Distribution | Certificate not available | Certificate not available | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 001356 | WEDGELOCK, 6 POSITION, FOR DT04-6P RECEPTACLE, DEUTSCH # | Mouser Electronics | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 001773 | WEDGELOCK, 12 POSITION, FOR DT04-12P, RECEPTACLE | LADD Distribution | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 001911 | CABLE TIE, 5T STANDARD CROSS SECTION, 7.5 BLACK" | Vallen Distribution, Inc. | NA | Unable to provide | 208 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 001920 | CABLE TIE MOUNT, 9/16 #8 SCREW 100 PER PACK | Vallen Distribution, Inc. | Unable to provide | Unable to provide | 9 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 001935 | BRAIDED EXPANDABLE SLEEVING (SNAKESKIN), 1/8- 3/8" | Allied Electronics, Inc. | Certificate not available | Certificate not available | 448 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 001939 | SLEEVING, BRAIDED EXPANDABLE | Vallen Distribution, Inc. | NA | Unable to provide | 8 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 001976 | TERMINAL, MALE, MINIFT CRIMP TERMINAL SERIES 5558, MOLEX | Mouser Electronics | Certificate not available | Certificate not available | 32 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 002070-002 | TUBING, GAROLITE, G10, 5/8ID | McMaster-Carr Supply Co. | Certificate not available | Certificate not available | 8 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 002331 | CONNECTOR, BUTT SPLICE, NON INSULATED, #18-22 AWG | Waytek Inc | Certificate not available | Certificate not available | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 002513 | TEE BOLT, .44-20 X 1.00 | NSK Industries Inc | Unable to provide | Unable to provide | 76 | 0 | 0% | 0.02% | 0.00% | 0.02% | 77.42% |
| 002514 | NUT, HEX, FLANGE, SERRATED .44-20 | Bossard North America Inc | Unable to provide | Unable to provide | 76 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 002828 | SEAL, EDGE-GRIP, RUBBER, 0.25"EDGE, 0.75" BULB | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |



PROTERRA

| PART NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY / VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|-------------|--|---------------------------------------|---|---|---------------|-----------------|--------------|--------------------|-------|---------|------------|
| 002987 | WASHER, M4 | Bossard North America Inc | Unable to provide | Unable to provide | 5 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 002996-001 | CLAMP, WORM, 2-9/16TO 3-1/2 | Bossard North America Inc | Unable to provide | Unable to provide | 12 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 003669-004 | NOSING, GRAY, 12" | | Certificate not available | Certificate not available | 156 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 003796 | TRIM, EDGING, STEP, YELLOW, 1 X 2-3/8" X 9FT" | Altro Transfloor | Canada | Canada | 300 | 0 | 0% | 0.03% | 0.00% | 0.03% | 77.42% |
| 004092 | VELCRO CINCHING STRAP, 1 WIDE X 18" LENGTH" | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 3 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 004137 | PUSH BUTTON, ILLUMINATED | EAO Switch Corporation | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 004138 | LENS, RED PUSH BUTTON SWITCH | EAO Switch Corporation | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 004139 | SWITCH ELEMENT, 24DC WHITE LED, INO, EAO 84-8511.9640 | EAO Switch Corporation | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 004317 | HITTING, BRASS, PTC, UNION, BULKHEAD, 3/8 TUBE" | Grainger | Certificate not available | Certificate not available | 5 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 004365 | HT, STEEL, 90, SWIVEL, FLARE, 1/2M37 | Bossard North America Inc | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 004408 | HYDROVANE V2T TRANSIT PACKAGE | Ron White's Air Compressor Sales | United Kingdom | Redditch, UK | 1 | 0 | 0% | 0.88% | 0.00% | 0.88% | 77.42% |
| 004411 | VALVE, AIR, SCHRAEDER, 1/4 NPT" | Vallen Distribution, Inc. | NA | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 004666 | VALVE, SYNCHRO, SV-1, 21 PSI OPEN PRESSURE | Bendix CVS LLC | Mexico | 0 | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 004703 | COUPLING, RUBBER, W/CLAMPS, 2TO 1-1/2 REDUCERR, 2 X 1.5" | Vallen Distribution, Inc. | NA | Unable to provide | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 004747 | SPRING, AIR, FRONT, 1T19L-5 BELLOW | Firestone Industrial Products Company | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.05% | 0.00% | 0.05% | 77.42% |
| 004781 | CAP, RADIATOR, 13PSI | NAPA AUTO PARTS | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 004837 | DUCT, Y-FITTING, 3" | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 004896 | SEALANT, LOCTITE 5900 | Vallen Distribution, Inc. | NA | Unable to provide | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 005015 | NUT, HEX, MACHINE SCREW, #10-32 | NSK Industries Inc | Taiwan | Taiwan | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 005078 | WASHER, PLAIN, .41x.81x.07 | Bossard North America Inc | Unable to provide | Unable to provide | 102 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 005129-019 | BOLT, HEX, M6-1.0x65x18 | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 6 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 005251 | WASHER, FLAT, M4 | McMaster-Carr Supply Co. | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 005442-003 | BOLT, HEX, M6-1.0x16x16 | Bossard North America Inc | Unable to provide | Unable to provide | 38 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 005442-004 | BOLT, HEX, M6-1.0x20x20 | Bossard North America Inc | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 005442-005 | BOLT, HEX, M6-1.0x25x18 | Bossard North America Inc | Unable to provide | Unable to provide | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 005442-006 | BOLT, HEX, M6-1.0x30x30 | Bossard North America Inc | Unable to provide | Unable to provide | 3 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |



| PART NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY / VEHICLE | UNIT OF MEASURE | % U.S. CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|-------------|---|------------------------------|---|---|---------------|-----------------|----------------|--------------------|-------|---------|------------|
| 005442-012 | BOLT, HEX, M6-1.0x45x45 | Bossard North America Inc | Unable to provide | Unable to provide | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 005443-001 | BOLT, HEX, M8-1.25x12x12 | Bossard North America Inc | Unable to provide | Unable to provide | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 005443-002 | BOLT, HEX, M8-1.25x16x16 | Bossard North America Inc | Unable to provide | Unable to provide | 30 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 005443-003 | BOLT, HEX, M8-1.25x20x20 | Bossard North America Inc | Unable to provide | Unable to provide | 62 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 005443-005 | BOLT, HEX, M8-1.25x30x30 | Bossard North America Inc | Unable to provide | Unable to provide | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 005443-015 | BOLT: HEX, M8-1.25X55X22 | NSK Industries Inc | Taiwan | Taiwan | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 005444-002 | BOLT, HEX, M10-1.50X20X20 | Bossard North America Inc | Unable to provide | Unable to provide | 20 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 005444-003 | BOLT, HEX, FLANGE, STL, XZPL, CLASS 10.9, M10-1.5X25X25 | Bossard Inc. | Unable to provide | Unable to provide | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 005448 | LKNT, HEX, FLANGE, STL, ZPL, CLASS 10, M6-1.0 | Bossard North America Inc | Unable to provide | Unable to provide | 8 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 005449 | LKNT, HEX, M8-1.25 | Bossard North America Inc | Unable to provide | Unable to provide | 38 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 005450 | LKNT, HEX, M10-1.50 | Bossard North America Inc | Unable to provide | Unable to provide | 47 | 0 | 0% | 0.02% | 0.00% | 0.02% | 77.42% |
| 005598-007 | SCREW, PAN, PHIL, STL, ZPL, CLASS 4.8, M4-.7X12X12 | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 5 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 005599-001 | SCREW, MACHINE, M6-1.0x10x10 | NSK Industries Inc | Unable to provide | Unable to provide | 6 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 005801 | BREATHER VENT, 1/8 NPT" | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 006093 | GASKET, NEOPRENE FOAM RUBBER, 1/8 X 1" ADHESIVE | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 3 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 006362 | FITTING, STAINLESS, ADAPTER, SAE 8, MALE X MALE | Hydadyne LLC | Taiwan | Taiwan | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 006430 | TAPE, 3M VHB, DOUBLE SIDED, 1 X .09" THICK" | Vallen Distribution, Inc. | NA | Unable to provide | 46 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 006731 | ADHESIVE, PRIMERLESS URETHANE, CARTRIDGE DGES P/ CASE) | Yokohama Industries Americas | Certificate not available | Certificate not available | 10 | 0 | 0% | 0.02% | 0.00% | 0.02% | 77.42% |
| 006732 | PRIMER, GLASS, YH AMERICA | Yokohama Industries Americas | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 006806 | SEAT TRACK FILLER, VINYL TRIM EXTRUSION, GREY | Keller Products | Certificate not available | Certificate not available | 576 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 006904-001 | WASHER, SS, METAL/ RUBBER BONDED, #10 | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 007268 | VALVE, CHECK, WINDSHIELD WASHER FLUID, W-634 | Commercial Vehicle Group | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 007306 | COVER, TOGGLE SWITCH, RED | Bossard North America Inc | Unable to provide | Unable to provide | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |



| PART NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY / VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|-------------|---|--------------------------------|---|---|---------------|-----------------|--------------|--------------------|-------|---------|------------|
| 007755 | CONNECTOR, PLUG, 3 POSITION, DEUTSCH #DTM04-3P | LADD Distribution | Certificate not available | Certificate not available | 3 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 007788 | CONNECTOR, PLUG, 2 POSITION, DEUTSCH #DTM04-2P | LADD Distribution | Certificate not available | Certificate not available | 9 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 007997 | 2P MALE BLK 20 AMP WEATHER PACK SHROUD | Mouser Electronics | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 008294 | HEAT SHRINK, DOUBLE WALL, ADHESIVE, 1/4" 4" STICK | Vallen Distribution, Inc. | NA | Unable to provide | 30 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 008298 | GASKET, RUBBER, 0.125X1.5"WX22.5"L" | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 95 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 008322 | TERMINAL, SPADE, FEMALE, 22-18 AWG, .25 TAB | Newark Element 14 | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 008471 | RECEPTICAL, 12VDC, CIG STYLE | Vallen Distribution, Inc. | NA | Unable to provide | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 008652 | TRAILER SOCKET, 7-WAY, FLUSH MOUNT RECEPTACLE | Vallen Distribution, Inc. | NA | Unable to provide | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 008864 | VENT FILTER HK MOTOR | Hydadyne LLC | Certificate not available | Certificate not available | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 008867 | SENSOR, LIQUID LEVEL, SOLID STATE, 1/8 NPT" | Omega Engineering, Inc. | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.02% | 0.00% | 0.02% | 77.42% |
| 008945 | CONNECTOR, RECEPT, 6 POSITION, DTM SERIES | LADD Distribution | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 008946 | WEDGELOCK, 6 POSITION, DTM SERIES | LADD Distribution | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 009356 | RCPT, DT, 12 WAY, A KEY | Mouser Electronics | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 009475 | TRANSMISSION FLUID, DEXRON VI (FOR POWER STEERING) | Latitude Applied Technologies | Certificate not available | Certificate not available | 21 | 0 | 0% | 0.03% | 0.00% | 0.03% | 77.42% |
| 010195 | SNAP RING, MOTOR SIDE | Bossard Inc. | Unable to provide | Unable to provide | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 010462 | HOSE, RADIATOR, 1.5 ID" | Dixie Rubber & Plastics, Inc. | Italy | Italy | 20 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 010484 | VALVE, DUMP, VENTURA DOORS | Ventura Inc | Europe | Europe | 3 | 0 | 0% | 0.04% | 0.00% | 0.04% | 77.42% |
| 010485 | FILTER, AIR, VENTURA DOORS | 0 | Europe | Europe | 2 | 0 | 0% | 0.05% | 0.00% | 0.05% | 77.42% |
| 010775 | HITTING, PTC, COMPOSITE, UNION Y, 3/8OD TUBE | Vallen Distribution, Inc. | NA | Unable to provide | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 010811 | RCPT, 12WAY, ENHA, A KEY, RDS, FLNG, FCAP | LADD Distribution | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 010867 | ROXTEC, E/ZENTRY 16 | Bonder States Industries, Inc. | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.02% | 0.00% | 0.02% | 77.42% |
| 010970 | LOCK, WDG, DTM, 2 WAY, RCPT | LADD Distribution | Certificate not available | Certificate not available | 8 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 011013 | MOUNTING BASE, CABLE TIE, .25 STUD, 2X SADDLE, GRAY | Bossard North America Inc | Unable to provide | Unable to provide | 164 | 0 | 0% | 0.02% | 0.00% | 0.02% | 77.42% |
| 011014 | MOUNTING BASE, CABLE TIE, .25 STUD, SINGLE, BLACK | Bossard North America Inc | Unable to provide | Unable to provide | 225 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 011083 | TRANSMISSION FLUID, EATON | Jesus Aucar | Certificate not available | Certificate not available | 8.8 | 0 | 0% | 0.03% | 0.00% | 0.03% | 77.42% |
| 011313 | TAPE, RUBBER, WATERPROOF/SEALING (50FT) BUTYL | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 012108 | SWIVEL BUNDLE, SPACER | Vallen Distribution, Inc. | NA | Unable to provide | 33 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |



| PART NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY / VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|-------------|---|-----------------------------------|---|---|---------------|-----------------|--------------|--------------------|-------|---------|------------|
| 012125 | VELCRO 3M 250 6 STRIPS' | Latitude Applied Technologies | Certificate not available | Certificate not available | 6 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 012138 | CABLE TIE, HEAVY DUTY .5WIDE 9.1" BLACK | Bossard Inc. | Unable to provide | Unable to provide | 617 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 012140 | ELBOW, IID 90 DEG SILICONE | VenaAir, Inc. | USA | Grand Rapids, MI | 3 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 012175 | HR TREE SADDLE MOUNT (HELLERMAN TITAN) | Vallen Distribution, Inc. | NA | Unable to provide | 16 | | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 012255 | CHECK VALVE, COOLANT, BRASS | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 012264 | FITTING, ADAPTER, 1/2 MBSP, #12 MJIC | HydraLyne LLC | Poland | Poland | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 012269 | ELBOW, IID 45 DEG. SILICONE | VenaAir, Inc. | USA | Grand Rapids, MI | 3 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 012487 | WELD ROD- FOG / ORE / SUMMIT / PEWTER GREY / ALPINE | Altro Transfloor | England | Leitchworth England | 64 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 012502 | FITTING, HOSE, BARBED, BRASS, 3/8X 1/8 MNPT | Vallen Distribution, Inc. | NA | Unable to provide | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 012504 | MOUNT, #10 ZIP TIE | Di-Key Corporation | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 012508 | SEAL MP GREEN IND LOOSE 1W CABLE | Mouser Electronics | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 012628 | TERMINAL, PIN, SIZE 20, DEUTSCH, 16-18 AWG | LADD Distribution | Certificate not available | Certificate not available | 34 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 013007 | 30 PANEL MOUNT GOOSENECK MICROPHONE" | Radio Engineering Industries, Inc | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.02% | 0.00% | 0.02% | 77.42% |
| 013282 | SWITCH, STOP ACKNOWLEDGE | Wes-Garde Components Group, Inc. | Mexico | Mexico | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 013283 | SWITCH, INTERIOR EXTERIOR SELECT | Wes-Garde Components Group, Inc. | Mexico | Mexico | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 013284 | SWITCH, DRIVERS LIGHT | Wes-Garde Components Group, Inc. | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 013289 | SWITCH, KNEEL CONTROL | Wes-Garde Components Group, Inc. | Mexico | Mexico | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 013290 | SWITCH, RIDE HEIGHT CONTROL | Wes-Garde Components Group, Inc. | Mexico | Mexico | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 013291 | SWITCH, RAMP CONTROL | Wes-Garde Components Group, Inc. | Mexico | Mexico | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 013293 | SWITCH, INTERIOR LIGHTS | Wes-Garde Components Group, Inc. | Mexico | Mexico | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 013294 | SWITCH, MIRROR HEATER | Wes-Garde Components Group, Inc. | Mexico | Mexico | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 013297 | SWITCH, SHUTDOWN OVERRIDE | Wes-Garde Components Group, Inc. | Mexico | Mexico | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 013369-008 | BOLT, HEX, FLG, .25-20x.75x.75 | Bossard North America Inc | Unable to provide | Unable to provide | 8 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |



| PAK NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY / VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|------------|---|---------------------------------|---|---|---------------|-----------------|--------------|--------------------|-------|---------|------------|
| 013373-001 | BOLT, HEX, FLG, .38-16x1.00x1.00 | Bossard North America Inc | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 013373-004 | SCREW,HEX,FLG,STL,1000HSS,GRD8, .38-16x1.25x1.25 | Bossard Inc. | Unable to provide | Unable to provide | 6 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 013375-019 | BOLT, HEX, FLG, .44-14x1.75x1.75 | Bossard North America Inc | Unable to provide | Unable to provide | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 013377-001 | BOLT, HEX, FLG, .50-13x1.00x1.00 | Bossard North America Inc | Unable to provide | Unable to provide | 8 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 013368-002 | BOLT, DIN 6921, Cl. 10.9, 1000HSS, M6-1.0x12x12 | Bossard North America Inc | 0 | Unable to provide | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 013368-005 | BOLT, HEX, M6-1.0x25x18 | Carsons Nut-Bolt & Tool Co, Inc | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 013368-006 | BOLT, HEX, M6-1.0x30x30 | Bossard North America Inc | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 013368-015 | BOLT, HEX, M6-1.0x50x18 | Bossard North America Inc | Unable to provide | Unable to provide | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 013369-001 | BOLT, HEX, M8-1.25x12x12 | Bossard North America Inc | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 013369-002 | BOLT, HEX, M8-1.25x16x16 | Bossard North America Inc | Unable to provide | Unable to provide | 20 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 013369-003 | BOLT,HEX,FLG,STL,1000HSS,CLASS10.9, M8-1.25X20X20 | Bossard Inc. | Unable to provide | Unable to provide | 12 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 013369-004 | BOLT, HEX, M8-1.25x25x25 | Bossard North America Inc | Unable to provide | Unable to provide | 8 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 013369-005 | BOLT, HEX, M8-1.25x30x30 | Bossard North America Inc | Unable to provide | Unable to provide | 31 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 013369-015 | BOLT, HEX, M8-1.25x55x22 | Bossard North America Inc | Unable to provide | Unable to provide | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 013370-001 | BOLT,HEX,FLG,STL,1000HSS,CLASS10.9, M10-1.5X16X16 | Bossard Inc. | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 013370-002 | BOLT, HEX, M10-1.50X20X20 | Bossard North America Inc | Unable to provide | Unable to provide | 56 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 013370-003 | BOLT,HEX,FLG,STL,1000HSS,CLASS10.9, M10-1.5X25X25 | Bossard Inc. | Unable to provide | Unable to provide | 18 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 013370-004 | BOLT,HEX,FLG,STL,1000HSS,CLASS10.9, M10-1.5X30X30 | Bossard Inc. | Unable to provide | Unable to provide | 24 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 013370-005 | BOLT, HEX, M10-1.50x35x35 | Bossard North America Inc | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 013370-011 | BOLT,HEX,FLG,STL,1000HSS,CLASS10.9, M10-1.5X50X26 | Bossard Inc. | Unable to provide | Unable to provide | 7 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 013370-013 | BOLT, HEX, M10-1.50x55x26 | Bossard North America Inc | Unable to provide | Unable to provide | 98 | 0 | 0% | 0.03% | 0.00% | 0.03% | 77.42% |
| 013370-019 | BOLT,HEX,FLG,STL,1000HSS,CLASS10.9, M10-1.5X70X26 | Bossard Inc. | Unable to provide | Unable to provide | 20 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |



PROTERRA

| PART NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY / VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|-------------|---|----------------------------------|---|---|---------------|-----------------|--------------|--------------------|-------|---------|------------|
| 013570-021 | BOLT,HEX,FLG,STL,1000HSS,CLASS10.9, M10-1.5X80X26 | Bossard Inc. | Unable to provide | Unable to provide | 6 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 013570-025 | BOLT, HEX, M10-1.50x100x26 | Bossard North America Inc | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 013571-001 | BOLT, HEX, M12-1.75x20x20 | Bossard North America Inc | Unable to provide | Unable to provide | 8 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 013571-003 | BOLT, HEX, M12-1.75x30x30 | Vallen Distribution, Inc. | Unable to provide | Unable to provide | 16 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 013571-005 | BOLT, HEX, M12-1.75x40x40 | Bossard North America Inc | Unable to provide | Unable to provide | 6 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 013571-007 | BOLT, HEX, M12-1.75x45x30 | Bossard North America Inc | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 013571-008 | BOLT, HEX, M12-1.75x50x50 | Bossard North America Inc | Unable to provide | Unable to provide | 8 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 013571-013 | BOLT, HEX, M12-1.75x60x30 | Bossard North America Inc | Unable to provide | Unable to provide | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 013573-004 | BOLT, HEX, M16-2.0x40x40 | Bossard North America Inc | Unable to provide | Unable to provide | 12 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 013573-006 | BOLT, HEX, M16-2.0x50x50 | Bossard North America Inc | Unable to provide | Unable to provide | 28 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 013573-016 | BOLT, HEX, M16-2.0x80x38 | Bossard North America Inc | Unable to provide | Unable to provide | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 013573-020 | BOLT,HEX,FLG,STL,1000HSS,CLASS10.9, M16-2X100X38 | Bossard Inc. | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 013574 | LKNT,HEX,FLANGE,STL,1000HSS,CLASS 10, M6-1.0 | Bossard Inc. | Unable to provide | Unable to provide | 13 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 013575 | LKNT, HEX, M8-1.25 | Bossard North America Inc | Unable to provide | Unable to provide | 49 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 013576 | LKNT,HEX,FLANGE,STL,1000HSS,CLASS 10, M10-1.5 | Bossard Inc. | Unable to provide | Unable to provide | 44 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 013579 | LKNT,HEX,FLANGE,STL,1000HSS,CLASS 10, M16 X 2.0 | Bossard Inc. | Unable to provide | Unable to provide | 8 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 013697 | CONNECTOR, OBD, 16F | Mouser Electronics | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 013834 | LIGHT, FRONT, TURN SIGNAL | S. Sterling Company | Not Provided | Not Provided | 2 | 0 | 0% | 0.02% | 0.00% | 0.02% | 77.42% |
| 013843 | LIGHT, SIDE MARKER, YELLOW | S. Sterling Company | Certificate not available | Certificate not available | 8 | 0 | 0% | 0.03% | 0.00% | 0.03% | 77.42% |
| 013844 | LIGHT, SIDE, MARKER, RED | S. Sterling Company | Certificate not available | Certificate not available | 4 | 0 | 0% | 0.02% | 0.00% | 0.02% | 77.42% |
| 013848 | LIGHT, TURN SIGNAL, AMBER | S. Sterling Company | Not Provided | Not Provided | 4 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 013849 | LIGHT, REGEN LAMP, AMBER | S. Sterling Company | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 013940 | BUSBAR, 8 POS. 3/8 X 16 600AMP" | Wes-Garde Components Group, Inc. | Mexico | Mexico | 2 | 0 | 0% | 0.03% | 0.00% | 0.03% | 77.42% |
| 013953 | INTERFACE FLANGE, CONNECTOR | LADD Distribution | Certificate not available | Certificate not available | 4 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 013957 | INTERFACE FLANGE, CONNECTOR | LADD Distribution | Certificate not available | Certificate not available | 6 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 014021 | SWITCH, 400A, HIGH VOLTAGE DISCONNECT | Gigavac | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 014030 | LIGHT, GREEN LED FLAT LENS 24V | Mouser Electronics | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |



| PART NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY / VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|-------------|---|----------------------------------|---|---|---------------|-----------------|--------------|--------------------|-------|---------|------------|
| 014058-006 | SCREW, MACHINE, M4x16x16 | Bossard North America Inc | Unable to provide | Unable to provide | 6 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 014061-004 | SCREW: MACHINE: M8x20x20 | NSK Industries Inc | Taiwan | Taiwan | 6 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 014061-006 | SCREW, MACHINE, M8x30x30 | Bossard North America Inc | Unable to provide | Unable to provide | 6 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 014146 | ELBOW CONNECTOR, WINDSHIELD WASHER | Doga USA, Corp | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 014163 | SWITCH, ROTARY, WINDSHIELD WIPER, 4 POSITION | Wes-Garde Components Group, Inc. | Mexico | Mexico | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 014201-006 | SCREW, FLAT HEAD, M4x12x12 | Bossard North America Inc | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 014201-012 | SCREW, FLAT HEAD, M4x25x25 | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 32 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 014202-014 | SCREW, FLAT HEAD, M5x30x30 | Bossard North America Inc | Unable to provide | Unable to provide | 26 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 014203-010 | SCREW, FLAT HEAD, M6x20x20 | Bossard North America Inc | Certificate not available | Certificate not available | 8 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 014204-006 | SCREW, FLAT HEAD, M8x16x16 | Bossard Inc. | Unable to provide | Unable to provide | 9 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 014204-008 | SCREW, FLAT, SS, M8-1.25X20X20 | Bossard Inc. | Unable to provide | Unable to provide | 11 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 014204-010 | SCREW, FLAT HEAD, M8x25x25 | NSK Industries Inc | Taiwan | Taiwan | 3 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 014253 | SWITCH, BLANK, 1623 SERIES (PANEL, PLUG) | Wes-Garde Components Group, Inc. | Certificate not available | Certificate not available | 6 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 014391 | VFD, DUAL 30KW OUTPUT | Lenze-Schmidhauser | Germany | Germany | 1 | 0 | 0% | 0.41% | 0.00% | 0.41% | 77.42% |
| 014488 | SWITCH, SPST TOGGLE SEALED 15A 2POS | Allied Electronics, Inc. | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 014538 | HIGH TEMP SPLIT LOOM, 1/4 ID BLACK | TTL Inc | Unable to provide | Unable to provide | 91.5 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 014542 | TUBE,CNVL,ID,SLIT,1/2ID | Vallen Distribution, Inc. | Unable to provide | Unable to provide | 16 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 014659 | TERMINAL, MALE, 18-22 AWG, INSL, RED, 2-520103-2 | Mouser Electronics | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 014781 | GROMMET, PUSH-IN 5/16 ID 1/2" HOLE X 1/16" PANEL" | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 014782 | GROMMET, PUSH-IN, 1.125ID, 1.5HOLE X .06PANEL | Bossard North America Inc | Unable to provide | Unable to provide | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 014891 | ELBOW, 1.75 ID 90° SILICONE | VenAir, Inc. | USA | Grand Rapids, MI | 4 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 014928 | LIGHT, WHITE SPOT, LED SWIVEL | S. Sterling Company | USA | Arlington Heights, IL | 2 | 0 | 0% | 0.02% | 0.00% | 0.02% | 77.42% |
| 015007 | JAM NUT, 3/4 NPT | Bossard North America Inc | Unable to provide | Unable to provide | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 015169-005 | SCREW, MACHINE, M3x10x10 | Bossard North America Inc | Unable to provide | Unable to provide | 3 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 015169-006 | SCREW, MACHINE, M3x12x12 | Bossard North America Inc | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 015172-004 | SCREW, MACHINE, M6x16x16 | Bossard North America Inc | Unable to provide | Unable to provide | 11 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |



| PAK NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY/VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|------------|---|--------------------------------|---|---|-------------|-----------------|--------------|--------------------|-------|---------|------------|
| 015208 | CONDUIT, PASS THRU, SEALED | Border States Industries, Inc. | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.06% | 0.00% | 0.06% | 77.42% |
| 015209 | FLANGE, G FRAME, 4X1, 30MM, ROXTEC | Border States Industries, Inc. | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.05% | 0.00% | 0.05% | 77.42% |
| 015942-004 | SCREW, PAN, PHIL, STL, ZPL, CLASS 4.8, M5-8X12X12 | Bossard Inc. | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 015947 | U-NUT, M6, 3.4 - 6.3 THICK | Bossard North America Inc | Unable to provide | Unable to provide | 91 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 015357 | WEDGELOCK, DTM, 3WAY, RECEPACLE | LADD Distribution | Certificate not available | Certificate not available | 3 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 015393 | SWITCH, MOM, SPST, SPADE | Allied Electronics, Inc. | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 015433 | LUG,RNG,NO-INSUL,3.8XHD,2/0 AWG | Allied Electronics, Inc. | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 015520-005 | SCR, PAN, TRI-LOB, #10-14x.50 | Bossard North America Inc | Unable to provide | Unable to provide | 20 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 015520-007 | SCR, PAN, TRI-LOB, #10-14x.625 | Bossard North America Inc | Unable to provide | Unable to provide | 12 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 015661 | FOAM, ADHESIVE BACK, CLOSE CELL, .1875x.375 | Vallen Distribution, Inc. | NA | Unable to provide | 6 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 015673 | PIN,SOLID,SZ,20,20 AWG,NCKL | LADD Distribution | Certificate not available | Certificate not available | 3 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 015723 | LKNT, HEX, M5-0.8 | Bossard North America Inc | Certificate not available | Certificate not available | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 015880 | WHSR, SNUB, STL, CL, 10.9, ZPL, Ø9.9xØ39.6x2.3 | Bossard North America Inc | Unable to provide | Unable to provide | 200 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 015996 | BUZZER, MINATURE SPEAKER | Vallen Distribution, Inc. | NA | Unable to provide | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 016098 | 8MM SQUARE KEY, LATCH, ACCESS HATCH | Austin Hardware & Supply, Inc | 0 | 0 | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 016206 | NUT, RIVET, M6-1.0, 4.2-6.6 GRIP | Bossard North America Inc | Unable to provide | Unable to provide | 28 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 016237 | WHSR, DIN 125A, NYL, M8 | Bossard North America Inc | Unable to provide | Unable to provide | 20 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 016244 | COVER ASSEMBLY, E-RELEASE, ENG/FRENCH | Plastic Creations Ltd. | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.03% | 0.00% | 0.03% | 77.42% |
| 016255 | WASHER, SPRING, M5 | Bossard North America Inc | Unable to provide | Unable to provide | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 016256 | WASHER, SPRING, M6 | Bossard North America Inc | Unable to provide | Unable to provide | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 016270-004 | SCREW, BUTTON, M4-0.7X16 | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 016328-002 | SCREW, SHC, M4-0.7X10X10 | NSK Industries Inc | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 016328-005 | SCREW, SHC, S5, M4-0.7X20X20 | NSK Industries Inc | Taiwan | Taiwan | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 016328-010 | SCREW, SHC, M4-0.7x40x20 | Bossard North America Inc | Unable to provide | Unable to provide | 7 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 016329-004 | SCREW, SHC, M5-0.8x16x16 | Bossard North America Inc | Unable to provide | Unable to provide | 10 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |



| PART NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY / VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|-------------|---|--------------------------------|---|---|---------------|-----------------|--------------|--------------------|-------|---------|------------|
| 016329-005 | SCREW, SHC, M5-0.8x20x20 | Bossard North America Inc | Unable to provide | Unable to provide | 12 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 016330-002 | SCREW, SHC, M6-1.0x12x12 | Bossard North America Inc | Unable to provide | Unable to provide | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 016330-003 | SCREW, SHC, M6-1.0x16x16 | Bossard North America Inc | Unable to provide | Unable to provide | 21 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 016330-006 | SCREW, SHC, SS, M6-1.0x30x30 | Bossard Inc. | Unable to provide | Unable to provide | 8 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 016330-010 | SCREW, SHC, M6-1.0x40x24 | Bossard North America Inc | Unable to provide | Unable to provide | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 016330-012 | SCREW, SHC, M6-1.0x45X24 | Bossard Inc. | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 016330-018 | SCREW, SHC, M6-1.0x60X24 | Bossard Inc. | Unable to provide | Unable to provide | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 016331-006 | SCREW, SHC, M8-1.25x35x35 | Bossard North America Inc | Unable to provide | Unable to provide | 10 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 016385 | FOAM TAPE, .25W X .125" THICK" | Vallen Distribution, Inc. | NA | Unable to provide | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 016498 | CABLE CLAMP, SELF ADHESIVE, 0.315 "LD" | Vallen Distribution, Inc. | NA | Unable to provide | 17 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 016536 | HARD LINE, POWER STEER | Cline Hose and Hydraulics, LLC | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 016538 | FITTING, 1/2JC O-RING X 1/2AN | Cline Hose and Hydraulics, LLC | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 016540 | SENSOR, INDUCTION, SPEED, WS-24, 90DEG | Bendix CVS LLC | Mexico | 0 | 2 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 016605 | 1/2 NPT TO -8 AN BLACK ANODIZED" | Hydrahyne LLC | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 016606 | COMPRESSION TO 90 DEG 1/2 AN" | Cline Hose and Hydraulics, LLC | Certificate not available | Certificate not available | 3 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 016710-003 | BOLT, DIN 6921, CL. 10.9, 1000HSS, M5-0.8x12x12 | Bossard North America Inc | Unable to provide | Unable to provide | 9 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 016734 | BOOT, RECEPTACLE, 2PIN DTM SERIES, GRAY | LADD Distribution | Certificate not available | Certificate not available | 9 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 016813 | FITTING, AIR, 3/4 AN TO 1/2" BSP" | Machine Shop Services, LLC | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 016854 | WASHER, FLAIN, .22x.50x.05 | Bossard North America Inc | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 016873 | WASHER, FLAT, SS, M3 | NSK Industries Inc | Taiwan | Taiwan | 6 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 016874 | WASHER, FLAT, SS, M4 | Bossard Inc. | Unable to provide | Unable to provide | 44 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 016875 | WASHER, FLAT, SS, M5 | NSK Industries Inc | Taiwan | Taiwan | 13 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 016876 | WASHER, FLAT, SS, M6 | Bossard Inc. | Unable to provide | Unable to provide | 11 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 016877 | WASHER, FLAT, M8 | Bossard North America Inc | Unable to provide | Unable to provide | 34 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 016880 | WASHER, FLAT, M14 | NSK Industries Inc | Taiwan | Taiwan | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 016900 | WASHER, SPRING, #10 | Bossard North America Inc | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 016919 | WASHER, SPRING, M4 | Bossard North America Inc | Unable to provide | Unable to provide | 3 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |



| PART NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY / VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|-------------|--|----------------------------------|---|---|---------------|-----------------|--------------|--------------------|-------|---------|------------|
| 016921 | WASHER, SPRING, M6 | Bossard North America Inc | Unable to provide | Unable to provide | 5 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 016936-005 | STRIKER BOLT | Bossard North America Inc | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 016944 | HITTING, TEE, HOSE BARB, 4MM | Doga USA, Corp | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 016977 | CORR GRIP, .75 NPT X .562 - .688 | Vallen Distribution, Inc. | NA | Unable to provide | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 017011 | HOSE, COOLANT, EPDM, SAE J20R3 D2, 1.0 ID" | Vallen Distribution, Inc. | NA | Unable to provide | 33 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 017012 | HOSE, COOLANT, EPDM, SAE J20R3 D2, 3/4 ID" | Vallen Distribution, Inc. | NA | Unable to provide | 57 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 017013 | HOSE, COOLANT, EPDM, SAE J20R3 D2, 3/8 ID" | Vallen Distribution, Inc. | NA | Unable to provide | 58 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 017029-029 | BOLT, HEX, M6-1.0x110x18 | Bossard North America Inc | Unable to provide | Unable to provide | 3 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 017030-012 | BOLT, DIN 931, SST 18-8, M8-1.25x50x22 | NSK Industries Inc | Taiwan | Taiwan | 27 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 017030-022 | BOLT, HEX, M8-1.25x80x80 | Bossard North America Inc | Unable to provide | Unable to provide | 6 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 017030-028 | BOLT, HEX CAP, SS, M8-1.25X75X75 | Bossard Inc. | Unable to provide | Unable to provide | 6 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 017043-001 | SIKAFLEX SEALANT (300ML) | Vallen Distribution, Inc. | NA | Unable to provide | 2.6 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 017043-003 | SEALANT,POLYURETHANE,WHITE | Vallen Distribution, Inc. | NA | Unable to provide | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 017070 | CLAMP, WORM DRIVE, .75X1.5X | Bisco Industries | Certificate not available | Certificate not available | 13 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 017130 | PLUG, WHITE | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 017143-005 | SCREW, CAP, #10-32x.50x.50 | Bossard North America Inc | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 017242 | SPRING, HOSE, CLAMP, 0.375 | Mubea, Inc. | Certificate not available | Certificate not available | 43 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 017243 | SPRING, HOSE, CLAMP, 0.75 | Mubea, Inc. | Certificate not available | Certificate not available | 17 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 017244 | SPRING CLAMP, 1.00" ID HOSE | Mubea, Inc. | Certificate not available | Certificate not available | 96 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 017366 | BOOT, RECEPTACLE, 2PIN, DT SERIES, GRAY | LADD Distribution | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 017480 | LKNT, HEX, M5-0.8 | Bossard North America Inc | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 017491 | FILTER DRIER 480CM3-13/16 ORHS" | Eberspächer Sitrak GmbH & Co. | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 017497-012 | SCREW, BUTTON, PIN-IN-TORX, M4x0.7x12MM | Bossard North America Inc | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 017526 | SWITCH, RAMP ENABLE | Wes-Garde Components Group, Inc. | Mexico | Mexico | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 017585 | 2.5 LOCKING RIGID PLASTIC PLUGS 2-1/2" | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 017620 | TRANSMISSION, 1.5, OIL COOLED, CV SHAFT | Eaton Truck Components Sp | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.54% | 0.00% | 0.54% | 77.42% |
| 017629 | WIPER BLADE, WINDSHIELD, 1000MM | Doga USA, Corp | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |



| PAK NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY / VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|------------|---|---------------------------|---|---|---------------|-----------------|--------------|--------------------|-------|---------|------------|
| 017642-016 | BOLT, HEX, M5-0.8x50x50 | Bossard North America Inc | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 017652-003 | BOLT,HEX,FLANGE,STL, YZPL, CLASS 8.8, M6-1.0x16x16 | NSK Industries Inc | Taiwan | Taiwan | 8 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 017652-004 | BOLT,HEX,FLANGE,STL, YZPL, CLASS 8.8, M6-1.0x20x20 | NSK Industries Inc | Taiwan | Taiwan | 3 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 017653-003 | BOLT,HEX,FLANGE,STL, YZPL, CLASS 8.8, M8-1.25x20x20 | NSK Industries Inc | Taiwan | Taiwan | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 017653-009 | SCR, HEX, M8-1.25x40x22 | Bossard North America Inc | Unable to provide | Unable to provide | 12 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 017653-013 | BOLT,HEX,FLANGE,STL, YZPL, CLASS 8.8, M8-1.25x50x22 | NSK Industries Inc | Taiwan | Taiwan | 10 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 017653-015 | BOLT, HEX, M8-1.25x55x22 | NSK Industries Inc | Taiwan | Taiwan | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 017654-004 | BOLT, HEX, M5-0.8x16x16 | Bossard North America Inc | Unable to provide | Unable to provide | 12 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 017655-002 | BOLT, HEX, M6-1.0x12x12 | Bossard North America Inc | Unable to provide | Unable to provide | 5 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 017655-003 | BOLT, HEX, M6-1.0x16x16 | Bossard North America Inc | Unable to provide | Unable to provide | 24 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 017655-004 | BOLT,HEX,FLG,STL,1000HSS,CLASS 8.8,M6-1.0x20x20 | Bossard North America Inc | Unable to provide | Unable to provide | 6 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 017655-005 | BOLT, HEX, M6-1.0x25x18 | Bossard North America Inc | Unable to provide | Unable to provide | 32 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 017655-006 | BOLT, HEX, M6-1.0x30x30 | Bossard North America Inc | Unable to provide | Unable to provide | 64 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 017655-007 | BOLT, HEX, M6-1.0x30x18 | Bossard North America Inc | Unable to provide | Unable to provide | 6 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 017655-009 | BOLT, HEX, M6-1.0x35x18 | Bossard North America Inc | Certificate not available | Certificate not available | 5 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 017656-002 | BOLT,HEX,FLG,STL,1000HSS,CLASS 8.8,M8-1.25X16X16 | Bossard North America Inc | Unable to provide | Unable to provide | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 017656-003 | BOLT, HEX, M8-1.25x20x20 | Bossard North America Inc | Unable to provide | Unable to provide | 37 | 0 | 0% | 0.02% | 0.00% | 0.02% | 77.42% |
| 017656-004 | BOLT, HEX, M8-1.25x25x25 | Bossard North America Inc | Unable to provide | Unable to provide | 8 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 017656-005 | BOLT, HEX, M8-1.25x30x30 | Bossard North America Inc | Unable to provide | Unable to provide | 14 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 017656-015 | BOLT,HEX,FLG,STL,1000HSS,CLASS 8.8,M8-1.25X55X22 | Bossard Inc. | Unable to provide | Unable to provide | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 017656-021 | BOLT,HEX,FLG,STL,1000HSS,CLASS 8.8,M8-1.25X70X22 | Bossard Inc. | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 017722 | INSULATOR, CYLINDRICAL, MALE-MALE, 304 SS | Vallen Distribution, Inc. | NA | Unable to provide | 4 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 017748 | BOOT, RECEPTACLE, 3PIN, DTM SERIES, GRAY | LADD Distribution | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |



| PART NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY / VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|-------------|--|-----------------------------------|---|---|---------------|-----------------|--------------|--------------------|-------|---------|------------|
| 017774 | BUS BAR, VEC DUAL POST (BUSSMAN B109-7081) | Vallen Distribution, Inc. | NA | Unable to provide | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 017787 | LUG,RNG,NO-INS,3/8XHD,6AWG | Allied Electronics, Inc. | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 017814 | PLUG, DRAIN, M12 x 1.5" | NAPA AUTO PARTS | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 017820 | HARNES, OPTIONAL SPEAKER JUMPER (SPKOPT) | Heritage Wire Harness, LLC | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 017822 | CHECK VALVE, BRASS, 3/8 FNPT X 3/8" FNPT" | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 017891 | TAPESWITCH, 10 WITH 36" LEAD" | Tapeswitch Corporation | Certificate not available | Certificate not available | 14 | 0 | 0% | 0.12% | 0.00% | 0.12% | 77.42% |
| 018018-012 | SCREW, C19K, PIN-IN-TORX, M6-1.0x25x25 | Bossard North America Inc | Unable to provide | Unable to provide | 26 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018081-005 | SCREW, BUTTON FLANGE, TORX, M6-1.0x25x25 | Vallen Distribution, Inc. | NA | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018094 | SPKR, 4A POLYLCONE & RUBB SURRND, 4 OHM | Radio Engineering Industries, Inc | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018130 | BALL VALVE, 3-WAY | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 018134 | ISOLATOR, WATER PUMP | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 12 | 0 | 0% | 0.03% | 0.00% | 0.03% | 77.42% |
| 018166 | INSERT, AW SERIES, M5-0.8 | Vallen Distribution, Inc. | NA | Unable to provide | 16 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018200-012 | SCREW; MACHINE: M4-0.7x45x45 | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018218 | WASHER, FLAT, M6 | Bossard North America Inc | Unable to provide | Unable to provide | 36 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018220 | WASHER, FLAT, M10 | Bossard North America Inc | Unable to provide | Unable to provide | 66 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018242 | INSERT, AW SERIES, M4-0.7 | Bossard Inc. | Unable to provide | Unable to provide | 52 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018246 | LKNT, HEX, M6 | Bossard North America Inc | Unable to provide | Unable to provide | 16 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018255 | LKNT, HEX NYLON, SS, M4-0.7 | Bossard Inc. | Unable to provide | Unable to provide | 32 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018256 | LKNT, HEX, M5 | Bossard North America Inc | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018257 | LKNT, HEX NYLON, SS, M6-1.0 | Bossard Inc. | Unable to provide | Unable to provide | 6 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018268 | NUT, HEX, STL, YZPL, CLASS 10, M3-.05 | Bossard North America Inc | Unable to provide | Unable to provide | 16 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018269 | NUT, HEX, STL, YZPL, CLASS 10, M4-0.7 | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 3 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018282 | NUT, HEX, M4 | Bossard North America Inc | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018307-003 | SCREW, TAPPING, M5.5x19 | Bossard North America Inc | Unable to provide | Unable to provide | 65 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018307-009 | SCREW, TAPPING, M5.5X50 | Bossard Inc. | Unable to provide | Unable to provide | 8 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018308-003 | SCREW, TAPPING, M6.3x19 | Bossard North America Inc | Unable to provide | Unable to provide | 57 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 018309 | COVER, SCREW CAP, WASHER, M6 | PRO-DEC.com | Certificate not available | Certificate not available | 48 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |



| PART NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY / VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|-------------|--|---------------------------|---|---|---------------|-----------------|--------------|--------------------|-------|---------|------------|
| 018310 | COVER, SCREW CAP, WHITE M6 | PRO-DEC.com | Certificate not available | Certificate not available | 48 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018373-001 | SCREW, BUTTON, 34-0.7X8 | NSK Industries Inc | Taiwan | Taiwan | 16 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018373-004 | SCREW, BUTTON, M4-0.7X16 | NSK Industries Inc | Taiwan | Taiwan | 19 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018373-005 | SCREW, BUTTON, M4-0.7X20 | NSK Industries Inc | Taiwan | Taiwan | 20 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018373-008 | SCREW: BUTTON: M4-0.7x35 | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018374-002 | SCREW, BUTTON, M5-0.8X12 | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018374-003 | SCREW: BUTTON: M5-0.8x16 | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018375-006 | SCREW, SOCKET BUTTON HEAD CAP, SS, M6-1.0X30 | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 8 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018397 | GROMMET, SEAL, 3/4ID X 7/8" HOLE 3/32" THK PANEL | Bossard Inc. | Unable to provide | Unable to provide | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018417 | R-14 VALVE, 4.0 CRACK PRESSURE | Bendix CV5 LLC | Mexico | 0 | 1 | 0 | 0% | 0.02% | 0.00% | 0.02% | 77.42% |
| 018460 | NUT, RIVET, M4-0.7, 2.0-3.3 GRIP | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 6 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018568 | LKNT, HEX FLANGE NYLON, STL, YZPL, CLASS 10, M6-1.0 | Vallen Distribution, Inc. | NA | Unable to provide | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018575 | LKNT, HEX, M6-1.0 | Bossard North America Inc | Unable to provide | Unable to provide | 395 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018576 | LKNT, HEX, M8-1.25 | Bossard North America Inc | Unable to provide | Unable to provide | 25 | 0 | 0% | 0.03% | 0.00% | 0.03% | 77.42% |
| 018598-006 | SCREW: MACHINE: M3-0.5x12x12 | NSK Industries Inc | Taiwan | Taiwan | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018598-007 | SCREW, PAN, PHIL, SS, M3-0.5X16X16 | Bossard North America Inc | Unable to provide | Unable to provide | 28 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018598-017 | SCREW, PAN, PHIL, SS, M3-0.5X45X45 | Bossard North America Inc | Unable to provide | Unable to provide | 3 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018599-005 | SCREW, MACHINE, M4-0.7x12x12 | Bossard North America Inc | Unable to provide | Unable to provide | 5 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018599-006 | SCREW, PAN, PHIL, SS, M4-0.7X16X16 | Bossard North America Inc | Taiwan | Taiwan | 24 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018599-007 | SCREW, MACHINE, PAN HEAD, PHILLIPS, SST M4-0.7X20X20 | Bossard North America Inc | Unable to provide | Unable to provide | 20 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018599-008 | SCREW, PAN, PHIL, SS, M4-0.7X25X25 | Bossard Inc. | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018599-015 | SCREW, PAN, PHIL, SS, M4-0.7X70X70 | Bossard North America Inc | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018600-005 | SCREW, PAN, PHIL, SS, M5-0.8X16X16 | Bossard North America Inc | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018600-006 | SCREW, PAN, PHIL, SS, M5-0.8X20X20 | Bossard North America Inc | NA | Unable to provide | 14 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018601-004 | SCREW, MACHINE, M6-1.0x16x16 | Bossard North America Inc | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018632 | LKNT, LOCK, M3-0.5 | Bossard North America Inc | Unable to provide | Unable to provide | 6 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |



| PAK NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY / VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|------------|---|---------------------------|---|---|---------------|-----------------|--------------|--------------------|-------|---------|------------|
| 018634-020 | BOLT, HEX, M18-2.5x120x42 | Bossard North America Inc | Unable to provide | Unable to provide | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018645 | WSHR, DIN 125A, STL, HDN, 1000HSS, M10 | Bossard Inc. | Unable to provide | Unable to provide | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018646 | WASHER, FLAT, M12 | Bossard North America Inc | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018648 | WASHER, FLAT, M16 | Bossard North America Inc | Unable to provide | Unable to provide | 8 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018649 | WASHER, FLAT, M18 | Bossard North America Inc | Unable to provide | Unable to provide | 12 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018650 | WASHER, FLAT, M20 | Bossard North America Inc | Unable to provide | Unable to provide | 8 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018651 | WASHER, FLAT, M24 | Bossard North America Inc | Unable to provide | Unable to provide | 8 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018652-002 | BOLT, HEX, M18-1.5x35x35 | Bossard North America Inc | Unable to provide | Unable to provide | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018652-007 | BOLT, HEX, M18-1.5x60x60 | Bossard North America Inc | Unable to provide | Unable to provide | 8 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 018653-005 | SCR: PAN: TRI-LOB: #10-14X.50 | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 8 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018657 | RIVNUT, M5 | Vallen Distribution, Inc. | NA | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018754 | LKNT, HEX, .44-14 | Bossard North America Inc | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018757 | LOCKNUT, HEX, STL, 1000HSS, CLASS 10, M18-2.5 | Vallen Distribution, Inc. | NA | Unable to provide | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018758-031 | BOLT, HEX, .88-9x4.75x2.00 | Bossard North America Inc | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018830-024 | BOLT, HEX, M20-2.5x60x60 | Bossard North America Inc | Unable to provide | Unable to provide | 8 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018831-024 | BOLT, HEX, M24-3.0x65X65 | Bossard North America Inc | Unable to provide | Unable to provide | 8 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 018897-002 | BOLT, HEX, M16-1.5x35x35 | Bossard North America Inc | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018897-026 | BOLT, HEX, M16-1.5x130x44 | Bossard North America Inc | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 018901 | SUN SHADE, MESH, 30" | Auto Motion Shade Inc. | Canada | Markham, ON | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 018908 | SCREW, CAP, UNDERCUT, .38-16x2.25x1.25 | Safe Fleet Bus & Rail | China | China | 11 | 0 | 0% | 0.02% | 0.00% | 0.02% | 77.42% |
| 018921 | INSERT, KNIFE EDGE, M3 | Vallen Distribution, Inc. | NA | Unable to provide | 28 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 018933 | WASHER, FLAT, M6 | Bossard North America Inc | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018956 | TERMINAL BLOCK, 3-CONDUCTOR, 28-12 AWG | Vallen Distribution, Inc. | Certificate not available | Certificate not available | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 018975-007 | SCR, SHC, LOW HEAD, .31-18x.75 | Bossard North America Inc | Unable to provide | Unable to provide | 102 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |



| PART NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY / VEHICLE | UNIT OF MEASURE | % U.S. CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|-------------|---|-------------------------------------|---|---|---------------|-----------------|----------------|--------------------|-------|---------|------------|
| 019064 | LKNT, HEX, NYLON-INSERT, .50-13 | Bossard North America Inc | Unable to provide | Unable to provide | 10 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 019071 | LKNT, HEX, NYLON-INSERT, .75-16 | Bossard North America Inc | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 019075-007 | SCREW, BUTTON, TORX, M4-0.7x20x20 | Bossard North America Inc | Unable to provide | Unable to provide | 27 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 019080 | HITTING, PTC, BRASS 1/4MPT, 3/8OD TUBE | Barker Air & Hydraulics, Inc. | Certificate not available | Certificate not available | 3 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 019229 | LKNT, HEX, .75-16 | Bossard North America Inc | Unable to provide | Unable to provide | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 019240 | WASHER, FLAT, 1/4 | Bossard North America Inc | Unable to provide | Unable to provide | 32 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 019242 | PIN, COLLIER, SPLIT | ZF SERVICES NORTH AMERICA, LLC | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 019276-003 | BOLT, HEX, M6-1.0x16x16 | Bossard North America Inc | Unable to provide | Unable to provide | 6 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 019276-004 | BOLT, HEX, M6-1.0x20x20 | Bossard North America Inc | Unable to provide | Unable to provide | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 019276-020 | BOLT, HEX, M6-1.0x25x25 | Bossard North America Inc | Unable to provide | Unable to provide | 23 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 019354-005 | SCREW, TRUSS, SS, PHIL, .25-20X.50X.50 | Bossard Inc. | Unable to provide | Unable to provide | 6 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 019423 | NUT, RIVET, M4-0.7, 0.5-2.5 GRIP | Bossard North America Inc | Unable to provide | Unable to provide | 5 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 019438 | SIMULATOR,TACHOGRAPH,DTCO SIM CCVS | MKP Parts | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.02% | 0.00% | 0.02% | 77.42% |
| 019468 | NUT, PUSH, M10 | Bossard North America Inc | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 019473 | CLAMP, SPRING | Mubea, Inc. | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 019483 | STUD, BALL, SS, 10MM | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 6 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 019493-003 | SCREW, BUTTON FLANGE, TORX, M6-1.0x16x16 | Bossard North America Inc | Unable to provide | Unable to provide | 26 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 019493-005 | SCREW, BUTTON FLANGE, TORX, M6-1.0x25x25 | Bossard North America Inc | Unable to provide | Unable to provide | 300 | 0 | 0% | 0.02% | 0.00% | 0.02% | 77.42% |
| 019493-007 | SCREW, BUTTON FLANGE, TORX, M6-1.0x35x35 | Bossard Inc. | Unable to provide | Unable to provide | 28 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 019527 | CLAMP, COMPRESSION/ 2 HOSE" | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 6 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 019528 | HITTING, BARBED, .75X.50" FEMALE NPTF" | Commerce Hose & Industrial Products | Certificate not available | Certificate not available | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 019529 | HITTING, BARB, 90° ELBOW, 3/8HOSE X 1/2" MALE NPTF" | Commerce Hose & Industrial Products | Certificate not available | Certificate not available | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 019530 | HITTING, BARBED, TEE, .50X.50X.38" | Vallen Distribution, Inc. | NA | Unable to provide | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |



| PART NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY / VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|-------------|--|-------------------------------------|---|---|---------------|-----------------|--------------|--------------------|-------|---------|------------|
| 019531 | FITTING, BARBED, 900 ELBOW, 3/8 HOSE X 1/2" HOSE" | Commerce Hose & Industrial Products | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 019580-002 | SCREW, BUTTON, TORX, M3-0.5X10X10, ZPL, CL.8.8 | Bossard North America Inc | Unable to provide | Unable to provide | 8 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 019580-006 | SCREW, BUTTON, TORX, M3-0.5x25 | Bossard North America Inc | Unable to provide | Unable to provide | 6 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 019581 | EXHAUST FILTER, SOLENOID, 1/4 MPT HI FLOW | HydraDyne LLC | Certificate not available | Certificate not available | 2 | | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 019661 | INSERT, POTTED, M8-1.25X10 (WITTEN) | Vallen Distribution, Inc. | NA | Unable to provide | 4 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 019734 | HANDLE, DEEP, 5.75x 3.125 | Ventura Inc | Europe | Europe | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 019800 | LED LINEAR MEDALLION LIGHT, 12 INTERIOR" | S. Sterling Company | Not Provided | Not Provided | 4 | 0 | 0% | 0.03% | 0.00% | 0.03% | 77.42% |
| 019830 | CABLE TIE, EDGE CLIP, 8 | Bossard North America Inc | Unable to provide | Unable to provide | 33 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 019842 | LOCKNUT, NYLOCK, 3/8-16, 18-8 SST A2 | Bossard Inc. | Unable to provide | Unable to provide | 8 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 020014 | LIGHT, STEP, WHITE LED, 24V | S. Sterling Company | Not Provided | Not Provided | 2 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 020083 | HOSE, DUCT, 3ID CLEAR FLEXIBLE | Dixie Rubber & Plastics, Inc. | Certificate not available | Certificate not available | 114 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 020382 | SENSOR, LEVEL | Gems Sensors, Inc. | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 020416 | NUT, PUSH, M12 | Bossard North America Inc | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 020463 | INDICATOR, NUT, WHEEL | WHEEL-CHECK | Certificate not available | Certificate not available | 40 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 020474 | AIR LINES, BRAKE, 48 | Dixie Rubber & Plastics, Inc. | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.02% | 0.00% | 0.02% | 77.42% |
| 020512 | FOAM, ADHESIVE BACKING, 0.5 T 0.5" W | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 43.8 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 020525 | THERMISTOR, PROBE, 1/2-20 X 2.75" | Litel fuse, Inc. | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 020657 | CABLE TIE, .18X 12 | Bossard North America Inc | Unable to provide | Unable to provide | 8 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 020743 | SLIDE, BATTERY BOX, SUPPORT | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 2 | 0 | 0% | 0.05% | 0.00% | 0.05% | 77.42% |
| 020754 | SOLENOID, 1/4 NPT, 24 V | HydraDyne LLC | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.03% | 0.00% | 0.03% | 77.42% |
| 020763 | COOLANT, FLUID, 50/50 | Jesus Aucar | Certificate not available | Certificate not available | 25 | 0 | 0% | 0.04% | 0.00% | 0.04% | 77.42% |
| 020766 | TIE STRAP, BATTERY BOX | Vallen Distribution, Inc. | NA | Unable to provide | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 020836 | MOUNT, AXIAL, OVAL, 0.31 | Vallen Distribution, Inc. | NA | Unable to provide | 8 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 020859 | FLEX LINE, POWER STEERING | Dixie Rubber & Plastics, Inc. | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 020891 | WASHER, DIN 9021, SST, M8 | Bossard Inc. | Unable to provide | Unable to provide | 70 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 020904 | ASSY, PEDAL, BRAKE 450 | Bendix CVS LLC | Mexico | 0 | 1 | 0 | 0% | 0.04% | 0.00% | 0.04% | 77.42% |
| 020933 | SPACER, 1/4 DI / 2" OD | Bossard Inc. | Unable to provide | Unable to provide | 3 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 020955 | MOUNTING BASE, CABLE TIE, M10 STUD, 1X SADDLE, BLK | Bossard Inc. | Unable to provide | Unable to provide | 7 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |



| PAK NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY/VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|------------|--|----------------------------|---|---|-------------|-----------------|--------------|--------------------|-------|---------|------------|
| 020967 | CABLE TIE, FIR TREE | Vallen Distribution, Inc. | NA | Unable to provide | 7 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 020980 | RING, TIE-DOWN | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 021025 | NUT, HEX, THIN, M10-1.5, 1000HSS | Bossard Inc. | Unable to provide | Unable to provide | 7 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 021280 | TAPE, NVH, 1WIDE, | McMaster-Carr Supply Co. | Certificate not available | Certificate not available | 1200 | 0 | 0% | 0.04% | 0.00% | 0.04% | 77.42% |
| 021284 | LOCKNUT, HEX, FLG, NYLON-INSERT, .31-18 | Bossard North America Inc | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 021420 | REFLECTOR, REFLEX, RED | S. Sterling Company | Not Provided | Not Provided | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 021467 | FOAM, ADHESIVE BACKING,0.75 TO.75W | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 17.99 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 021535 | SEALER,CAULK, PEWTER GREY, ELAN, STRADA, SPIDER | Altro Transfloor | England | Letchworth, England | 8 | 0 | 0% | 0.05% | 0.00% | 0.05% | 77.42% |
| 021632 | MOUNT, FIRTREE, 9MM | Bisco Industries | Certificate not available | Certificate not available | 12 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 021719 | PLUG FREE HNG 2P DUAL ROW, MOLEX 43020-0201 | Newark Element 14 | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 021722 | MALE 20-24AWG, CONTACT MOLEX 43031-0007 | Newark Element 14 | Certificate not available | Certificate not available | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 021854 | RIV NUT, M4, 3.80-6.85 GRIP RANGE | NSK Industries Inc | USA | USA | 8 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 021885 | BATTERY BOOT, 3/0-4/0 AWG, RED | Bossard Inc. | Unable to provide | Unable to provide | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 021886 | BATTERY BOOT, 3/0-4/0 AWG, BLACK | Bossard North America Inc | Unable to provide | Unable to provide | 3 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 021974 | LIGHT, KNEELING, 24V | S. Sterling Company | Not Provided | Not Provided | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 022143 | TANK, WASHER FLUID, 4.5 GAL | Doga USA, Corp | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.02% | 0.00% | 0.02% | 77.42% |
| 022188 | RIVET, DOMED, 5/32DIA., .188-.25MATL, THK | Bossard North America Inc | Unable to provide | Unable to provide | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 022229 | HITTING, E37, RAYCOM | RedE Parts Inc. | France | France | 8 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 022266 | NUT, M6-1.0,HEX,STL,ZnNi,DSEMS | Bossard North America Inc | Unable to provide | Unable to provide | 14 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 022267 | SCR,M5x20,BTN,STL,ZnNi,P-ST3 | Bossard Inc. | Unable to provide | Unable to provide | 11 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 022323 | SCR,M4x10,BTN,SST,DSEMS,P-ST3 | Bossard Inc. | Unable to provide | Unable to provide | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 022355 | NUT, M8-1.25,HEX,STL,ZnNi,DSEMS | Bossard Inc. | Unable to provide | Unable to provide | 17 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 022382 | NUT, M4-0.7,HEX,STL,ZnNi | Bossard Inc. | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 022383 | SCR,M4x14,BTN,STL,ZnNi,P-ST3 | Bossard North America Inc | Unable to provide | Unable to provide | 36 | 0 | 0% | 0.03% | 0.00% | 0.03% | 77.42% |
| 022398 | CLIP, FIR TREE, M5 | Digi-Key Coporation | Certificate not available | Certificate not available | 20 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 022453 | LOCKWASHER, INTERNAL/EXTERNAL TOOTH, .45x1.07x.045 | Bossard North America Inc | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 022506 | CONTROLLER, WIPERS | Doga USA, Corp | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.06% | 0.00% | 0.06% | 77.42% |
| 022532 | M5X30,STANDOFF | Bossard Inc. | Unable to provide | Unable to provide | 8 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 022600 | ENERGY STORAGE MASTER, CHARGE CONTROLLER, 1772 | Silicon Forest Electronics | USA | Vancouver, WA | 1 | 0 | 0% | 0.13% | 0.00% | 0.13% | 77.42% |



PROTERRA

| PART NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY / VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|-------------|--|----------------------------------|---|---|---------------|-----------------|--------------|--------------------|-------|---------|------------|
| 022604-005 | SCREW, BUTTON, FLANGED, M6-2.14 X 25 | Bossard North America Inc | Unable to provide | Unable to provide | 12 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 022661 | SOLENOID, VALVE, AIR | Gems Sensors, Inc. | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.04% | 0.00% | 0.04% | 77.42% |
| 022763-018 | BOLT, HEX, M12-1.75x90x30 | Bossard North America Inc | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 022936 | GREASE, FRONT SUSPENSION (TUBE) | Grainger | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 022967 | NUT, RIVET, HEAVY, OPEN, STL, ZPL, M6-1.0, 0.7-4.2 | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 022970 | WASHER, FENDER, .281x1.00x.063 | Bossard North America Inc | Unable to provide | Unable to provide | 3 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 023155 | MOTOR, WIPE, 1 SPEED | Doga USA, Corp | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.03% | 0.00% | 0.03% | 77.42% |
| 023156 | LINKAGE, WIPE, W/ HARDWARE | Doga USA, Corp | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.03% | 0.00% | 0.03% | 77.42% |
| 023157 | WIPE ARM | Doga USA, Corp | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 023158 | WIPE ARM | Doga USA, Corp | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 023170 | LIGHT, RED, LED, FLAT LENS SV | Allied Electronics, Inc. | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 023221 | SEAL, 1 WIPE 3/16" EDGE | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 3 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 023237 | SCR,M6x16,HEX,STL,ZnNi,DSEMS,P-ST3 | Bossard Inc. | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 023241 | CONNECTOR,DC LINK | TE Connectivity Corporation | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 023242 | HEAT-SHRINK,TUBING,0.81" ID | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 230 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 023253 | SCR,M8x16,PAN,STL,ZnNi,DSEMS,P-ST3 | Bossard North America Inc | Unable to provide | Unable to provide | 5 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 023278 | MOUNT,HOLDER,FUSE | China Yexing Auto Part Limited | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 023411 | CLIP, 6.7MM, PUSH, POM, t1-4MM | Bossard North America Inc | Unable to provide | Unable to provide | 36 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 023820 | HEADLIGHT, LED | Simcona Electronics Corporation | Canada | Burlington, Ontario | 2 | 0 | 0% | 0.17% | 0.00% | 0.17% | 77.42% |
| 023831 | CABLE TIE, EDGE CLIP, 8" | Wes-Garde Components Group, Inc. | Germany | Germany | 10 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 023844 | BUMPER, LOWER ACCESS PANEL | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 023938-004 | BOLT, HEX, M8-1.25x25x25 | Vallen Distribution, Inc. | NA | Unable to provide | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 023938-005 | BOLT, HEX, M8-1.25x30x30 | Bossard Inc. | Unable to provide | Unable to provide | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 024148 | SENSOR, LEVEL, CAPACITANCE | Gems Sensors, Inc. | 0 | 0 | 2 | 0 | 0% | 0.03% | 0.00% | 0.03% | 77.42% |
| 024771 | SEALANT, SILICONE, BLACK, RTV 732 | MSC Industrial Supply Co. | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 024976-002 | SCREW, DRILLING, MODIFIED TRUSS, #8-18x.75 | Bossard North America Inc | Unable to provide | Unable to provide | 92 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 025017 | VALVE, DUCKBILL, 0.459" | Vernay Laboratories, Inc. | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 025025 | CLAMP, PINCH, SINGLE, .5--.5781ID RANGE | Bossard North America Inc | Unable to provide | Unable to provide | 8 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |



| PART NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY / VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|-------------|--|--|---|---|---------------|-----------------|--------------|--------------------|-------|---------|------------|
| 025080 | SEAL, FLAP, 1 | Echo Engineering & Production Supplies, Inc. | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 025082 | SEAL, EDGE, 3/16 PANEL" | Echo Engineering & Production Supplies, Inc. | Certificate not available | Certificate not available | 3.3 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 025127-006 | SCREW: BUTTON FLANGE: TORX: M5-0.8x16x16 | Bossard Inc. | Unable to provide | Unable to provide | 40 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 025129-002 | SCREW: BUTTON FLANGE, TORX, M6-1.0x12x12 | Bossard North America Inc | Unable to provide | Unable to provide | 22 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 025129-003 | SCREW: BUTTON FLANGE, TORX, M6-1.0x16x16 | NSK Industries Inc | Europe | Europe | 125 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 025132-005 | SCREW: BUTTON FLANGE: TORX: M4-0.7x16x16 | NSK Industries Inc | Taiwan | Taiwan | 6 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 025133-005 | SCREW: BUTTON FLANGE: TORX: M5-0.8x12x12 | NSK Industries Inc | Taiwan | Taiwan | 8 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 025133-006 | SCREW: BUTTON FLANGE: TORX: M5-0.8x16x16 | NSK Industries Inc | Taiwan | Taiwan | 12 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 025134-003 | SCREW: BUTTON FLANGE, TORX, M6-1.0x16x16 | NSK Industries Inc | Taiwan | Taiwan | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 025135-004 | SCREW: BUTTON FLANGE: TORX: M8-1.25x20x20 | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 025173 | GROMMET: RESERVOIR | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 025376 | BRACKET, COOLANT FILTER, REMOTE MOUNT HEAD | Barker Air & Hydraulics, Inc. | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 025377 | BAR, GROUND | Storm Manufacturing Corporation | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 025378 | FILTER, COOLANT, SPIN-ON | NAPA AUTO PARTS | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 025607-002 | BOLT, HEX, M10-1.50X20X20 | Bossard Inc. | Unable to provide | Unable to provide | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 025757 | TAPE, FOAM, VHB, DOUBLE-SIDED, 1/2X.09" THICK" | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 7 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 025788 | PUSH BUTTON, MOMENTARY, N/O (RED BUTTON) | Wes-Gardle Components Group, Inc. | France | France | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 025798 | FLUID, WINDSHIELD WASHER | Grainger | Certificate not available | Certificate not available | 4.5 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 025811 | LATCH, COMPRESSION, SQUARE KEY | Allegis Corporation | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 025922 | SENSOR, TEMPERATURE, AIR, -30C +80C | Mouser Electronics | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 026277 | SHAFT, STEERING, INTERMEDIATE | THK Rhythm Automotive Michigan Corporation | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.04% | 0.00% | 0.04% | 77.42% |
| 026308 | BRACKET, LATCH, ACCESS | Allegis Corporation | Certificate not available | Certificate not available | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 026314 | T-BOLT, DROP-IN, W/STUD, 25-20 | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 15 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 026559 | WHEEL, STEERING, LEATHER, 18 INCH | Vehicle Improvement Products, Inc. | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.03% | 0.00% | 0.03% | 77.42% |



| PAK NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY/VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|------------|---|-----------------------------------|---|---|-------------|-----------------|--------------|--------------------|-------|---------|------------|
| 026837 | SEAL: NEOPRENE/EPDM: 0.25" SQUARE | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 026842 | FITTING, ELBOW, 1 NPTX1" HOSE BARB | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 026861 | HOSE, FILL, WASHER TANK | Doga USA, Corp | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 026895 | AMPLIFIER, TRANSIT, 2-CHANNEL | Radio Engineering Industries, Inc | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.04% | 0.00% | 0.04% | 77.42% |
| 026928 | HANDLE, LOCKING | Allegis Corporation | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.02% | 0.00% | 0.02% | 77.42% |
| 026931 | RETAINER, LINK | Allegis Corporation | Certificate not available | Certificate not available | 8 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 026932 | LATCH, LEFT HAND | Allegis Corporation | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 026933 | LATCH, RIGHT HAND | Allegis Corporation | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 026935 | HINGE, TYPE-B, REMOVABLE | Allegis Corporation | Certificate not available | Certificate not available | 3 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 026936 | HINGE, TYPE-A, REMOVABLE | Allegis Corporation | Certificate not available | Certificate not available | 3 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 027027 | VALVE, BALL, 3/8 MNPT X 3/8" FNPT | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 027031 | BADGE, LOGO | Weston and Company, Inc. | USA | Goddard, KS | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 027143 | RIVET: CLOSED: AL: .31 X .50-.62 | NSK Industries Inc | Taiwan | Taiwan | 8 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 027276 | COTTER PIN, DIN 94, M5 x 40 | Bossard North America Inc | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 027277 | COTTER PIN, DIN 94, M4 x 36 | Bossard North America Inc | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 027304 | COVER, TOGGLE SWITCH, RED | Waytek Inc | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 027387 | SLEEVE, SPEED SENSOR | Bendix CV5 LLC | Germany | 0 | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 027404 | FUSE BOX, VEC 325, RDECK, 24V | Wes-Garde Components Group, Inc. | China | China | 1 | 0 | 0% | 0.05% | 0.00% | 0.05% | 77.42% |
| 027453 | NUT, RIVET, HEAVY, OPEN, STL, ZPL, M8-1.25, 3.8 - | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 26 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 027464 | COVER, LIGHTING, PANEL | Ningbo Wego Machinery Co., Ltd | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 027465 | HOUSING, LIGHT, PANEL | Ningbo Wego Machinery Co., Ltd | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 027516 | BRUSH 1, ASSEMBLED (G690CL44BL-50) | Sealeze | USA | Richmond, IN | 1 | 0 | 0% | 0.03% | 0.00% | 0.03% | 77.42% |
| 027517 | BRUSH, ASSEMBLED (G690CL A26BL-42) | Sealeze | USA | Richmond, IN | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 027597 | SWITCH, MUSHROOM, GREEN | EAO Switch Corporation | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 027598 | SWITCH, MUSHROOM, RED | EAO Switch Corporation | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 027736 | WASHER, SINGLE-WAVE, M8 | Bossard Inc. | Unable to provide | Unable to provide | 14 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 027762 | GAS SPRING, 26.43EXTENDED LENGTH (110 LBS FORCE) | Industrial Gas Springs Inc | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 028111 | PLUG: CAP: COOLANT FILL PORT | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |



| PART NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY/VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|-------------|---|------------------------------------|---|---|-------------|-----------------|--------------|--------------------|-------|---------|------------|
| 028123 | ZF BRAKE WEAR SENSOR CABLE - 2.5M | Zf Services North America LLC | Germany | Knoor-Brense | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 028356 | RTV SEALANT, WHITE | Grainger | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 028369 | LIGHT, LED | Allied Electronics, Inc. | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 028567 | CABLE, LATCH: 850MM | Allegis Corporation | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 028638 | P-CLAMP: RATCHET | Vallen Distribution, Inc. | NA | Unable to provide | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 029116 | VALVE, QR-1, 3/8 NPT, 1PSI MAX CRACK PRESSURE | Bendix CVS LLC | Mexico | 0 | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 030010 | SHIELD, PACK VENT, BODY | Specfab Services, Inc | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.04% | 0.00% | 0.04% | 77.42% |
| 030011 | SHIELD, PACK VENT, BODY | Specfab Services, Inc | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.04% | 0.00% | 0.04% | 77.42% |
| 030266 | U-NUT, M6, 0.8-4.0mm THICK | Grainger | Certificate not available | Certificate not available | 231 | 0 | 0% | 0.02% | 0.00% | 0.02% | 77.42% |
| 030573 | SWITCH, HAZARD LIGHT | Wes-Garde Components Group, Inc. | Mexico | Mexico | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 030575 | PLUG, BODY, BRAKE CANISTER | Grainger | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 031469 | EDGE TRIM, 7/16" BULB, 3/8" PANEL | Trim-Lok, Inc. | Unable to provide | Unable to provide | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 031743-002 | SCREW, DRILLING, MODIFIED TRUSS, #8-18x.75 | Bossard North America Inc | Unable to provide | Unable to provide | 14 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 032365 | EXPANSION, TANK, COOLANT | Resource Ind. Inc. | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.10% | 0.00% | 0.10% | 77.42% |
| 032608 | FLOOR ADHESIVE, 94 CA SPRAY-IN | Vallen Distribution, Inc. | NA | Unable to provide | 320 | 0 | 0% | 0.04% | 0.00% | 0.04% | 77.42% |
| 032785 | WASHER, FLAT, M6 | Bossard Inc. | Unable to provide | Unable to provide | 95 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 032929 | HSG, PLG, MINIHTJR, 4.2MM, 2WAY, 2RW, ML | Digi-Key Corporation | Certificate not available | Certificate not available | 16 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 033366 | CONTACTOR, 50 AMP, 24 VDC COIL, GIGAVAC P115CDA | Gigavac | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.02% | 0.00% | 0.02% | 77.42% |
| 033750 | INTERLOCK, FEMALE | Steven Engineering Group, Inc. | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 033997 | BACK-UP ALARM, 97 DB | Wes-Garde Components Group, Inc. | China | China | 2 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 034047 | SPRING, HOSE, CLAMP, 20.625 | Mubea, Inc. | Certificate not available | Certificate not available | 8 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 034068 | DRIVESHAFT, CARDAN | Universal Technical Services | Germany | Germany | 1 | 0 | 0% | 0.20% | 0.00% | 0.20% | 77.42% |
| 034083 | CONNECTOR, HVA280, KEY A | Mouser Electronics | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 034089 | BUSBAR, HVJB, TYPE 6 | China Yexing Auto Part Limited | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 034093 | BUSBAR, HVJB, TYPE 10 | China Yexing Auto Part Limited | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 034100 | FUSE, 30A, MEV100C30-S | Mersen USA Newburyport MA, LLC | Certificate not available | Certificate not available | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 034515 | ELBOW, 91" ID, 90° SILICONE | VenAir, Inc. | USA | Grand Rapids, MI | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 034677 | CABLE TIE, T30R, 148MMx3.8MM | Heilind Electronics, Inc. | Certificate not available | Certificate not available | 19 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 034714 | HORN PAD, 4 SPOKE, VIP LOGO | Vehicle Improvement Products, Inc. | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 034910 | WASHER, FLAT, RUBBER EPDM, 0.49" ID, 1.06" OD | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 8 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 035080 | CONNECTOR, HVA280, KEY D | Mouser Electronics | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |



PROTERRA

| PART NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY / VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|-------------|--|-------------------------------|---|---|---------------|-----------------|--------------|--------------------|-------|---------|------------|
| 035246 | SPRING, LOCKING GAS, 5.5" STROKE, 30 LBS | Allegis Corporation | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 035812 | BUMPER, ROUND, EMBEDDED WASHER, M4 | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 035864 | CONTROLLER, ABS, ECU | Bendix CVS LLC | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.08% | 0.00% | 0.08% | 77.42% |
| 035956 | VENT,M12,SCREW-IN | Sealing Devices INC | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 035999 | PLUG, 1/4" ID, EXPANSION | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 036155 | CONTACTOR, AUTOMATIC LOW-VOLTAGE DISCONNECT, 24V | Gigavac | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.03% | 0.00% | 0.03% | 77.42% |
| 036156 | CONTACTOR, AUTOMATIC LOW-VOLTAGE DISCONNECT, 12V | Gigavac | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.03% | 0.00% | 0.03% | 77.42% |
| 036592 | RAIL, GRAB, YELLOW | Manson International LLC | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.02% | 0.00% | 0.02% | 77.42% |
| 036593 | RAIL, GRAB, YELLOW | Manson International LLC | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.02% | 0.00% | 0.02% | 77.42% |
| 036594 | RAIL, GRAB, YELLOW | Manson International LLC | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 036597 | CONNECTOR,HVA280,KEY E | Mouser Electronics | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 036599 | CONNECTOR,HVA280,3-BA | LADD Distribution | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 036841 | NUT,M10-1.5,HEX,STL,ZnNi,DSEMS | Bossard Inc. | Unable to provide | Unable to provide | 5 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 036842 | SCR,M5x30,BTN,STL,P-ST3 | Bossard North America Inc | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 037183 | HSG,PLG,MINIHTJR,4.2MM,4WAY,1RW ,ML | Mouser Electronics | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 037215 | BRACKET, SIDE MOUNT, UPPER, CS | Aranda Tooling, Inc. | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 037225 | CORD GRIP, M25 X 1.5, 10-14MM CABLE | Newark Element 14 | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 037239 | BRACKET, STRIKER RH | Metal Solutions, Inc. | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 037345 | MASTER SELECTOR SWITCH | Kissing Electrotec, Inc. | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.02% | 0.00% | 0.02% | 77.42% |
| 037391 | NEOPRENE ADHESIVE-BACK STRIP, 1" x 1/16" THICK | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 037617 | PUMP, FILL | Depco Pump Company | Mexico | Mexico | 1 | 0 | 0% | 0.02% | 0.00% | 0.02% | 77.42% |
| 037646 | WATER HEATER, 20kW | Grayson Thermal Systems Corp. | United Kingdom | Birmingham, UK | 1 | 0 | 0% | 0.16% | 0.00% | 0.16% | 77.42% |
| 037897 | PLATE, STUD | LockRidge Tool Co., Inc. | USA | Grand Rapids, MI | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 038182 | MODULATOR VALVE, M-40QR, 24VDC | Bendix CVS LLC | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.04% | 0.00% | 0.04% | 77.42% |
| 038240 | CABLE ASSY, HVAC HEAT | TE Connectivity Corporation | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.04% | 0.00% | 0.04% | 77.42% |
| 038242 | CABLE ASSY, DEFROSTER HEAT | TE Connectivity Corporation | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.07% | 0.00% | 0.07% | 77.42% |
| 038245 | CABLE ASSY, DC LINK, AIR COMP/PWR STEERING VFD | era-contact USA LLC | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 038246 | CABLE ASSY, DC/DC CONVERTER 1 | era-contact USA LLC | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.02% | 0.00% | 0.02% | 77.42% |



| PAK NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY/VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|------------|--|--|---|---|-------------|-----------------|--------------|--------------------|-------|---------|------------|
| 038560 | RELAY, HIGH CURRENT, HCR 150 | LADD Distribution | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.02% | 0.00% | 0.02% | 77.42% |
| 038769 | SHOCK,REAR | Koni NA, Inc | Netherlands | Netherlands | 2 | 0 | 0% | 0.04% | 0.00% | 0.04% | 77.42% |
| 038833 | HANDLE, GRAB, STANCHION, GRAY | Baijiang Rubber & Plastic Technology Co., Ltd | Certificate not available | Certificate not available | 6 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 038857 | DCC65M24-WBIS(CONVERTER, DC-DC) | InMotion US LLC | Sweden | Sweden | 1 | 0 | 0% | 0.34% | 0.00% | 0.34% | 77.42% |
| 038910 | 22.5 X 9.00 HP 10-HOLE 32MM BOLT HOLE 335MM BC MF-BUJF | Advanced Wheel Sales LLC | Mexico | Mexico | 6 | 0 | 0% | 0.40% | 0.00% | 0.40% | 77.42% |
| 038913 | TIRE,MICHELIN@X@INCITY ENERGY Z.315/80R22.5, PROCURED | Michelin North America, Inc. | Certificate not available | Certificate not available | 6 | 0 | 0% | 0.57% | 0.00% | 0.57% | 77.42% |
| 039003 | CONTROLLER E-C IF SWINT 12V/24V PS000 | Eberspaecher Climate Control Systems U.S.A. Inc. | USA | Monteney | 1 | 0 | 0% | 0.55% | 0.00% | 0.55% | 77.42% |
| 039092 | LIGHT, FOOTWELL, LED, 24V, BLACK W/O CONNECTOR | Luminator Technology Group, Inc. | Certificate not available | Certificate not available | 4 | 0 | 0% | 0.06% | 0.00% | 0.06% | 77.42% |
| 039219 | SPRING, GAS, 5.5" STROKE, 30LB. | Allegis Corporation | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 039245 | FUSE HOLDER | TTI, Inc | Certificate not available | Certificate not available | 10 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 039284 | FUSE BOX, VEC 325 DUAL, ECAB | Wes-Garde Components Group, Inc. | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.04% | 0.00% | 0.04% | 77.42% |
| 039384 | SWITCH, BATT DISC 500A DP5T 48VDC | Kiasling Electrotec, Inc. | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.03% | 0.00% | 0.03% | 77.42% |
| 039394 | FAN, DRIVER, EMI Filtered | SPAL USA | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 039399 | HORN, KIT HIGH AND LOW NOTE, 24V | S. Sterling Company | Not Provided | Not Provided | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 039501 | CONNECTOR,HVSL1200,KEY A | Heiland Electronics, Inc. | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 039512 | SHUNT,500A 1000V,CP1 SENSOR | Testco Incorporated | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.03% | 0.00% | 0.03% | 77.42% |
| 039513 | SENSOR,CURRENT,HAHIBVW S/01 | LEM U.S.A., Inc | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 039514 | SENSOR,CURRENT,HAHIBVW S/02 | LEM U.S.A., Inc | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 039515 | CONNECTOR,HVA630,KEY A | LADD Distribution | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 039544 | BRACKET,FUSE BLOCK | US Prototype, Inc. | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 039693 | FUSE HOLDER | TTI, Inc | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 039930 | VEHICLE ELECTRICAL CENTER PROTERRA | Wes-Garde Components Group, Inc. | China | China | 1 | 0 | 0% | 0.02% | 0.00% | 0.02% | 77.42% |
| 040148 | FUSES, 80A | TTI, Inc | Certificate not available | Certificate not available | 5 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 040149 | FUSE, 150A | TTI, Inc | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 040150 | FUSE, 300A | Mouser Electronics | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 040245 | FUSE,GFP420 | Gigavac | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 040246 | FUSE,GFP410 | Gigavac | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 040479 | SCR,M10x20,PAN,STL,ZnNi,DSEMS,P-ST3 | Bosand Inc. | Unable to provide | Unable to provide | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 040483 | NUT, RIVET, HEAVY, OPEN, STL, ZPL, M4-0.7, 2.0-3.3 | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |



| PART NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY / VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|-------------|--|-----------------------------------|---|---|---------------|-----------------|--------------|--------------------|-------|---------|------------|
| 040544 | SCR,M5-2.24x10,PT,BTNL,STL,ZnNi | Bossard North America Inc | Unable to provide | Unable to provide | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 040588 | CABLE ENTRY, ICOTEK | McNaughton-McKay Electric Company | Germany | Germany | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 040592 | MOUNTING BASE, CABLE TIE, 8MM, SINGLE, BLACK | IEWC CORP. | Certificate not available | Certificate not available | 23 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 040617 | NUT,M4-0.7,HEX,STL,Zn,KEPS,TOOTH-LOCK | Bossard Inc. | Unable to provide | Unable to provide | 8 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 040656 | SPLIT BLOCK, 16MM | Hydadyne LLC | Certificate not available | Certificate not available | 39 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 040993 | SEAL, CABLE | McNaughton-McKay Electric Company | Germany | Germany | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 040994 | SEAL, CABLE | McNaughton-McKay Electric Company | Germany | Germany | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 040995 | SEAL, CABLE | McNaughton-McKay Electric Company | Germany | Germany | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 041028 | PANEL,ENCL,ALUM,HVJB,DC LINK DISCONNECT | Ningbo Wego Machinery Co.,Ltd | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 041030 | PANEL,ENCL,ALUM,HVJB,REAR | Ningbo Wego Machinery Co.,Ltd | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.02% | 0.00% | 0.02% | 77.42% |
| 041031 | PANEL,ENCL,ALUM,HVJB,LV COMM | Ningbo Wego Machinery Co.,Ltd | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 041124 | SWITCH, LVD OVERRIDE | Wes-Garde Components Group, Inc. | Mexico | Mexico | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 041346 | MOUNTING BASE, CABLE TIE, M6 STUD MOUNT | Digi-Key Corporation | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 041347 | SPACER, CABLE TIE | Digi-Key Corporation | Certificate not available | Certificate not available | 3 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 041803 | SCR,M5x16,BTNL,STL,ZnNi,P-ST3 | Bossard North America Inc | Unable to provide | Unable to provide | 12 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 041804 | SCR,M6x20,CAP,STL,ZnNi,MATPOINT | Bossard Inc. | Unable to provide | Unable to provide | 24 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 041805 | SCR,M4x30,CAP,LOW,STL,Zn,P-ST3 | Bossard Inc. | Unable to provide | Unable to provide | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 041842 | PANEL,ENCL,ALUM,HVJB,BODY INTEREACE,TYPE A | Ningbo Wego Machinery Co.,Ltd | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.02% | 0.00% | 0.02% | 77.42% |
| 041991 | HITTING, PTC, BRASS, 45° ELBOW, SWIVEL, 1/4 MNPT X 3/8 PTC | Hydadyne LLC | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 042205 | LABEL, WORK LIGHT | M1 Graphics CO, Inc | USA | Fountain Inn, SC | 5 | 0 | 0% | 0.05% | 0.00% | 0.05% | 77.42% |
| 042594 | SHOCK, FRONT, KONI RHS | Koni NA, Inc | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.08% | 0.00% | 0.08% | 77.42% |
| 042595 | SHOCK, REAR, KONI RHS | Koni NA, Inc | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.08% | 0.00% | 0.08% | 77.42% |
| 042610 | PLATE, SWITCH, SIDE CONSOLE, AFT | Lock-Ridge Tool Co., Inc. | USA | Grand Rapids, MI | 1 | 0 | 0% | 0.02% | 0.00% | 0.02% | 77.42% |
| 042616 | MANIFOLD, RIDE HEIGHT | Parker Hamfin Corporation | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.10% | 0.00% | 0.10% | 77.42% |
| 042617 | ECU, RIDE HEIGHT | Parker Hamfin Corporation | USA | Richland, MI | 2 | 0 | 0% | 0.11% | 0.00% | 0.11% | 77.42% |
| 042646 | COMPOSITE LID ASSY, WW BOX, SS | McClarin Plastics LLC | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.09% | 0.00% | 0.09% | 77.42% |
| 042727 | STRAP, GROUND, 9IN LNG, HVJB | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |



PROTERRA

| PART NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY/VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|-------------|--|---|---|---|-------------|-----------------|--------------|--------------------|-------|---------|------------|
| 042815 | O-RING, AS-147, EPDM | G&E, Inc. | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 042954 | CORD GRIP, SHIELDED MAXLOC, M40 THD, 2/0 AWG CABLE | TTL, Inc | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 043009-013 | FORMED AIRLINE, 1/2" OD, .06" WALL, BLACK | Hydradyne LLC | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 043090 | FITTING, DRAIN, 1/4"-18 MNPT | Fenco USA, Inc. | Netherlands | Mijhecht, NL | 4 | 0 | 0% | 0.02% | 0.00% | 0.02% | 77.42% |
| 043262 | ELBOW, Ø1/2", 90°, 6" LEGS, SILICONE | VenaAir, Inc. | USA | Grand Rapids, MI | 2 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 043377 | CABLE TIE, MOUNT, FIR TREE W/ CABLE TIE ASSY | IFWC CORP. | Certificate not available | Certificate not available | 7 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 043401 | CABLE TIE MOUNT, FIR TREE, OFFSET, 90°, 8.7L | Vallen Distribution, Inc. | NA | Unable to provide | 9 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 043693 | HARN, CONTACTOR, HWJB, GV200 | Gigavac | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.03% | 0.00% | 0.03% | 77.42% |
| 043694 | HARN, CONTACTOR, HWJB, GX26 | Gigavac | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.03% | 0.00% | 0.03% | 77.42% |
| 043699 | CLAMP, BUNDLE, SEPARATOR | IFWC CORP. | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 043720 | COMPRESSION LIMITER, M5, PSM024895-CU | PSM Fastener Corporation | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 043729 | FUSE, 40A, L75Q3040 | TTL, Inc | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 043775 | HINGE, PIANO, REAR HATCH ADJUSTABLE | Monroe Magnus LLC | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.03% | 0.00% | 0.03% | 77.42% |
| 043964 | QUARTER WINDOW, HERON | Coach Glass | USA | Elkhart, IN | 1 | 0 | 0% | 0.03% | 0.00% | 0.03% | 77.42% |
| 043965 | QUARTER WINDOW, 40FT HERON | Coach Glass | USA | Elkhart, IN | 1 | 0 | 0% | 0.02% | 0.00% | 0.02% | 77.42% |
| 043972 | SOLENOID VALVE, 24V, 3-WAY, NC, FLYING LEADS | Hydradyne LLC | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.02% | 0.00% | 0.02% | 77.42% |
| 044137 | CLAMP, CONSTANT TENSION WORM DRIVE, 21 to 38mm OD HOSE | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 5 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 044158 | FITTING, REDUCER, STRAIGHT, Ø5/8" TO Ø3/8" HOSE | Grainger | Certificate not available | Certificate not available | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 044322 | FITTING, BRASS, TEE, 1/2 FPT X 1/2 FPT X 1/2 FPT | Hydradyne LLC | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 044348 | MUFFLER, 1/2MPT | Hydradyne LLC | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 044349 | HOSE, MOLDED, REAR CHASE | Motion Industries, Inc | Certificate not available | Certificate not available | 5 | 0 | 0% | 0.03% | 0.00% | 0.03% | 77.42% |
| 044734 | DESTINATION CUT OUT/HERON | Coach Glass | USA | Elkhart, IN | 1 | 0 | 0% | 0.09% | 0.00% | 0.09% | 77.42% |
| 044735 | GASKET, WINDSHIELD | Yokohama Industries Americas | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.03% | 0.00% | 0.03% | 77.42% |
| 044846 | SHAFT, DRIVE, INTERMEDIATE, LOWER, 21.5 IN | THK Rhythm Automotive Michigan Coporation | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.03% | 0.00% | 0.03% | 77.42% |
| 044866 | FLEX LINE, POWER STEERING | Clire Hose and Hydraulics, LLC | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 044868 | FLEX LINE, POWER STEERING | Clire Hose and Hydraulics, LLC | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 044871 | FITTING, HYDRAULIC, 90 DEGREE | Hydradyne LLC | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 044873 | PANEL, FLUID FILL | Industrial Fabricators, Inc. | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.05% | 0.00% | 0.05% | 77.42% |



| PART NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY / VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|---------------|---------------------------------------|---------------------------------|---|---|---------------|-----------------|--------------|--------------------|-------|---------|------------|
| 044947 | LIGHT, REAR, CENTER MOUNT BRAKE LIGHT | S. Sterling Company | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 045006 | ANTENNA, GPS/AG LTE | Taoglas USA Inc. | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.02% | 0.00% | 0.02% | 77.42% |
| 045039 | SIGHT, GLASS, 3/4" MNPT | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 045143 | LINK, DRAG, ZE, METRIC | ZF Industries -Gainesville LLC | USA | Gainesville, GA | 1 | 0 | 0% | 0.06% | 0.00% | 0.06% | 77.42% |
| 045151 | SEAT, DRIVER, RECARO | Recaro North America, Inc. | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.34% | 0.00% | 0.34% | 77.42% |
| 045161-01AD01 | PANEL, WALL, C/S WHEEL WELL, FRONT | Kenson Plastics Inc | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.03% | 0.00% | 0.03% | 77.42% |
| 045234 | COMPOSITE LID ASSY, WW BOX, CS | McClarin Plastics LLC | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.08% | 0.00% | 0.08% | 77.42% |
| 045257-03AA04 | PANEL, REAR, PILLAR, S/S | Ray Products Company, Inc. | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.03% | 0.00% | 0.03% | 77.42% |
| 045275 | CABLE ASSY, HVAC COMPRESSOR | era-contact USA LLC | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.06% | 0.00% | 0.06% | 77.42% |
| 045276 | CABLE ASSY, BTMS HEATER | era-contact USA LLC | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.02% | 0.00% | 0.02% | 77.42% |
| 045368 | LIGHT, REAR, LICENSE PLATE LAMP | Simcona Electronics Corporation | Certificate not available | Certificate not available | 3 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 045579 | SUSPENSION, FRONT, INDEPENDENT | ZF Friedrichshafen AG | Germany | Passau | 1 | 0 | 0% | 0.95% | 0.00% | 0.95% | 77.42% |
| 045580 | DRIVE AXLE, 6.19:1, 90 DEG, A V 133 | ZF Friedrichshafen AG | Germany | Passau | 1 | 0 | 0% | 1.76% | 0.00% | 1.76% | 77.42% |
| 045590 | PLATE, SWITCH, DASH, CS | Seifert Graphics, Inc. | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 045684 | LIGHT, REAR, LICENSE PLATE LAMP BEZEL | Simcona Electronics Corporation | Certificate not available | Certificate not available | 3 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 045864 | WASHER, ISOLATION | Vallen Distribution, Inc. | NA | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 046062 | SPLIT BLOCK, 21.3MM | Hydradyne LLC | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 046154 | BUSBAR, HVJB, TYPE 1B | China Yexing Auto Part Limited | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 046157 | BUSBAR, HVJB, TYPE 2B | China Yexing Auto Part Limited | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 046158 | BUSBAR, HVJB, TYPE 3B | China Yexing Auto Part Limited | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 046160 | BUSBAR, HVJB, TYPE 4B | China Yexing Auto Part Limited | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 046162 | BUSBAR, HVJB, TYPE 5B | China Yexing Auto Part Limited | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 046164 | BUSBAR, HVJB, TYPE 7B | China Yexing Auto Part Limited | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 046165 | BUSBAR, HVJB, TYPE 8B | China Yexing Auto Part Limited | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 046166 | BUSBAR, HVJB, TYPE 9B | China Yexing Auto Part Limited | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 046167 | BUSBAR, HVJB, TYPE 11B | China Yexing Auto Part Limited | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 046168 | BUSBAR, HVJB, TYPE 12B | China Yexing Auto Part Limited | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |



| PART NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY / VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|-------------|--|-----------------------------------|---|---|---------------|-----------------|--------------|--------------------|-------|---------|------------|
| 046169 | BUSBAR, HVJB, TYPE 13B | China Yexing Auto Part Limited | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 046190 | BUSBAR, HVJB, TYPE 24B | China Yexing Auto Part Limited | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 046250 | PANEL, ENCL., ALUM., HVJB, INVERTER, 1C P B | Ningbo Wego Machinery Co., Ltd | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.03% | 0.00% | 0.03% | 77.42% |
| 046452 | RAIL, GRAB, FRONT, YELLOW | Manson International LLC | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 046495 | BUSBAR, HVJB, TYPE 14B | China Yexing Auto Part Limited | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 046780 | CABLE CLAMP, SCREW-IN, 3/8" ID | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 6 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 046873-003 | SCREW, TAPPING, #8-19x.50 | Bossard North America Inc | Unable to provide | Unable to provide | 6 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 046948 | HARNESS, FOOT SWITCH (FTSW) | Heritage Wire Harness, LLC | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 046954 | PLATE, SPLIT BLOCK, COVER, 3D | Bossard Inc. | Unable to provide | Unable to provide | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 047094 | CABLE ASSY, HV BATTERIES, STRING 1 | TE Connectivity Corporation | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.14% | 0.00% | 0.14% | 77.42% |
| 047095 | CABLE ASSY, HV BATTERIES, STRING 2 | TE Connectivity Corporation | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.16% | 0.00% | 0.16% | 77.42% |
| 047235 | BRACKET, 90 DEG W/ THREADED PIN M8 X 16 THREAD | Austin Hardware & Supply, Inc | Certificate not available | Certificate not available | 4 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 047237 | BASIC 5 POSITION CAM-STAY | Vallen Distribution, Inc. | NA | Unable to provide | 4 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 047240 | BRACKET, U | Vallen Distribution, Inc. | NA | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 047242 | HINGE, FORMED, FRAME LEAF | Allegis Corporation | Certificate not available | Certificate not available | 6 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 047244 | CABLE, LATCH, 500MM | Allegis Corporation | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 047247 | WASHER, RETAINING, NYLON | Bossard Inc. | Unable to provide | Unable to provide | 12 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 047401 | FITTING, QUICK DISC, MILITON S-777 | Hydradyne LLC | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 047453 | SCREW: BUTTON FLANGE HEAD M6-1.0X25 | Bossard North America Inc | Unable to provide | Unable to provide | 12 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 047626 | FERRITE, CLAMP ON | Mouser Electronics | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 047717 | INTERLOCK, KEY, HEXED, RIGHT ANGLE | Steven Engineering | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 047935 | TANK, AIR | Johnson Welded Products, Inc. | USA | Urbana, OH | 4 | 0 | 0% | 0.09% | 0.00% | 0.09% | 77.42% |
| 047979 | RUBBER SEAL D SECTION | Trim-Lok, Inc. | Certificate not available | Certificate not available | 6436 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 048059 | HOSE, MOLDED | Shore Auto Rubber Exports Pvt Ltd | USA | Grand Rapids, MI | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 048114 | EDGE TRIM SEAL, BULB 1" | Trim-Lok, Inc. | Certificate not available | Certificate not available | 3158 | 0 | 0% | 1.34% | 0.00% | 1.34% | 77.42% |
| 048114-SS | EDGE TRIM SEAL, BULB 1 | Trim-Lok, Inc. | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 048115 | EDGE TRIM SEAL, BULB 3/4, TOP | Trim-Lok, Inc. | Certificate not available | Certificate not available | 950 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 048162 | EDGE TRIM SEAL, D 1/2", SIDE | Trim-Lok, Inc. | Certificate not available | Certificate not available | 1770 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |



PROTERRA

| PART NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY / VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|-------------|---|---|---|---|---------------|-----------------|--------------|--------------------|-------|---------|------------|
| 048266 | HARNES, STREETSIDE HEADLIGHT (SSL) | Heritage Wine Harness, LLC | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 048267 | HARNES, CURBSIDE HEADLIGHT (CSHL) | Heritage Wine Harness, LLC | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 048302 | HITTING, BULKHEAD, COOLANT HILL PORT, 3/8" OD | Hydradyne LLC | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 048541 | HITTING, PTC, BRASS, 90 DEG, RIGID, 1/4 MPT X 3/8 PTC | Hydradyne LLC | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 048555 | SPACER, 0.17" ID (#8 SCREW), 5/16" OD, 1/4" LG, NYLON 6/6 | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 3 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 048593 | DUCT, DEFROSTER, 800V, 35 RR AND HERON | Therma-Tech (A.R. Lintern) | USA | Redford, MI | 1 | 0 | 0% | 0.10% | 0.00% | 0.10% | 77.42% |
| 048597-002 | SCREW, THREAD FORMING, FLATHEAD, CSK, M8-1.25X16 | Bossard Inc. | Unable to provide | Unable to provide | 16 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 048670 | SENSOR, TEMPERATURE, COOLANT | TTI, Inc | Certificate not available | Certificate not available | 4 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 048790 | FLAT WASHER, M10, THIN | Bossard Inc. | Certificate not available | Certificate not available | 5 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 048907 | VFD, 800V, TRANSIT BUS, HVAC, 30KW AC, 5.6KW DC OUTPUT | Ebespaecher Climate Control Systems U.S.A. Inc. | USA | Montemey | 1 | 0 | 0% | 0.30% | 0.00% | 0.30% | 77.42% |
| 049363 | ANTENNA, CHROMER NUT | Mobile Communications America, Inc. | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 049714 | HOSE, MOULDED | Shore Auto Rubber Exports Pvt Ltd | USA | Grand Rapids, MI | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 049840 | HARNES, LOW VOLTAGE POWER INTERNAL (IPWR102) | Precisionworks MFG LLC | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 049841 | HARNES, LOW VOLTAGE POWER INTERNAL (IPWR103) | Precisionworks MFG LLC | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 049853 | HARNES, LOW VOLTAGE POWER EXTERNAL (EPWR101) | Precisionworks MFG LLC | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 050539 | CAP, COOLANT, BYPASS, Ø1" | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 050761 | STRAIGHT AIR HARNES | Hydradyne LLC | USA | Ravena, OH | 1 | 0 | 0% | 0.10% | 0.00% | 0.10% | 77.42% |
| 051363 | PLUG, PLASTIC, DRIVERS PLATFORM | The Print Machine Inc. | Certificate not available | Certificate not available | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 051724 | PLATE, ANTENNA, SS | Dellinger Enterprises, LTD | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 051727 | PLATE, ITS | Griffiths Corporation | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.05% | 0.00% | 0.05% | 77.42% |
| 051750 | PLATE, OVERHEAD, DRIVER | GH Metal Solutions, Inc. | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 051958 | FOAM, BACKING, WALL, 1.5" | Munaco Sealing Solutions, Inc. | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 051978 | SPACER, NYLON, 0.16" ID, 0.5" L | McMaster-Carr Supply Co. | Unable to provide | Unable to provide | 44 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 052066 | SWITCH, PRESSURE, AIR, 20PSI | TTI, Inc | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 052067 | SWITCH, PRESSURE, AIR, 5 PSI | TTI, Inc | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| 052635 | FOAM, BACKING, WALL, 1"X1" | Munaco Sealing Solutions, Inc. | Certificate not available | Certificate not available | 13 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |



| PART NUMBER | COMPONENT | SUPPLIER | MANUFACTURING COUNTRY (Foreign or Domestic) | MANUFACTURING LOCATION (City & Country) | QTY/VEHICLE | UNIT OF MEASURE | % US CONTENT | % OF TOTAL VEHICLE | U.S. | FOREIGN | CUMULATIVE |
|---------------|--|---------------------------|---|---|-------------|-----------------|--------------|--------------------|-------|---------|------------|
| 053123 | FIRST AID KIT | Grainger | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 053218 | PANEL, CLOSURE, REAR DOOR | Metal Solutions, Inc. | USA | Vandegrift, PA | 1 | 0 | 0% | 0.06% | 0.00% | 0.06% | 77.42% |
| 053257 | KIT, MODESTY PANEL | Bentech Inc | Certificate not available | Certificate not available | 2 | 0 | 0% | 0.11% | 0.00% | 0.11% | 77.42% |
| 053442 | PLATE, MANUAL CHARGE, CS | Lock-Ridge Tool Co., Inc. | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.01% | 0.00% | 0.01% | 77.42% |
| 053781-05AA07 | COMPOSITE WWB, 40' HERON, CS BASE | McClain Plastics LLC | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.18% | 0.00% | 0.18% | 77.42% |
| 053782-05AA07 | COMPOSITE WWB, 40' HERON, SS BASE | McClain Plastics LLC | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.18% | 0.00% | 0.18% | 77.42% |
| | LKNT,HEX,FLANGE,STL, ZPL,CLASS 10, M10-1.5 | Bossard North America Inc | Unable to provide | Unable to provide | 8 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| | SCREW,BUTTON,FG,TORX,SS,EPOXY BLACK, M6-1.0X25X25 | Bossard North America Inc | Unable to provide | Unable to provide | 8 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| | SEALANT,POLYURETHANE,BLACK | Vallen Distribution, Inc. | NA | Unable to provide | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| | SCREW, CSUNK, PIN IN TORX, ST, BLK, M6-1.0X25X25 | Bossard Inc. | Unable to provide | Unable to provide | 2 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| | LOCKNUT, HEX, M6-1.0, SST, DIN 6926-A2, NYLOCK | Bossard North America Inc | Unable to provide | Unable to provide | 8 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| | | Newark Element 14 | Unable to provide | Unable to provide | 72 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| | BOLT, HEX, M8-1.25x16x16 | Bossard North America Inc | Unable to provide | Unable to provide | 16 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| | BOLT, HEX, M6-1.0x20x20 | Bossard North America Inc | Unable to provide | Unable to provide | 17 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| | | Bossard Inc. | Unable to provide | Unable to provide | 18 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| | CONNECTOR, RECEPTACLE, 2 POSITION, DEUTSCH | LADD Distribution | Certificate not available | Certificate not available | 6 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| | BOLT,HEX,FLANGE,STL, YZPL,CLASS 10.9, M6-1.0X20X20 | Bossard North America Inc | Unable to provide | Unable to provide | 11 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| | WASHER,LARGE | Bossard North America Inc | Unable to provide | Unable to provide | 11 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| | FLAT,STL.,1000HSS,CLASS 10.9, M6 | Bossard North America Inc | Unable to provide | Unable to provide | 11 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| | | Bossard Inc. | Unable to provide | Unable to provide | 16 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| | WEDGE LOCK, 2 PIN RECP. DT SERIES | LADD Distribution | Certificate not available | Certificate not available | 6 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| | | LADD Distribution | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| | SCREW, MACHINE, M4-0.7x25x25 | Bossard North America Inc | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| | WEDGELOCK, DT, 6 WAY RECEPTACLE | Mouser Electronics | Certificate not available | Certificate not available | 1 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |
| | | Bossard Inc. | Unable to provide | Unable to provide | 4 | 0 | 0% | 0.00% | 0.00% | 0.00% | 77.42% |